North 1/4 CORNER OF SECTION TOWNSHIP 108 N RANCE II W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A Stone Monument REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A 1"X 18" Iron Pipe at NE Corner of Stone SKETCH OF REFERENCE TIES SKETCH OF REFERENCE TIES UN 1/2 U 1/2 UN 2/4 U 1/2 OLD FENCE TREES CLD FENCE LINE Y BRUSH CLD FENCE LINE X OLD FENCE LINE X DESCRIPTION OF THE PLANT IN TH		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12788 LAND SURVEYOR, PROFESSIONAL ENGINEER COUNTY SURVEYOR, COUNTY ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

1850s No corner was set during the Original Public Land Survey of Township 108 North, Range 11 West, however, the US Deputy Surveyor set section post and made reference to 2 witness trees for the southeast corner of Section 35, Township 109 North, Range 11 West.

August, 2000 Johnson & Scofield, Inc. found a 12 inch by 24 inch limestone monument at the intersection of a fence line running north, a fence line running east and a fence line running west. The found stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast corner and the northwest corner of Section 1. The stone monument

along side.

NOTE: The northeast corner of Section 1, Township 108
North, Range 11 West is common to the south quarter corner
of Section 36, Township 109 North, Range 11 West, and the
northwest corner of Section 1, Township 108 North, Range 11
West is common to the south quarter corner of Section 35,
Township 109 North, Range 11 West. Therefore, the north
quarter corner of Section 1, Township 108 North, Range 11
West is accepted as being common to the southeast corner of
Section 35, Township 108 North, Range 11 West.

was left as found and a 1 inch by 18 inch iron pipe was driven

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
Northeast corner of Section 1 Township 108 N, Range 11 W, 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A Stone Monument X LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A 1"X 18" Iron Pipe Along Side of Stone		
SVETCH OF DE	FERENCE TIES	
SKETCH OF REFERENCE TIES WY N=131432.62 N=1432.62 NAB. Co. Coord NAD 1983 ADJ. ROAD ROAD		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12794	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
✓ LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
✓ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

northeast corner of Section 1, Township 108 North, Range 11 West

- 1850s The US Deputy Surveyor set a post a made reference to 2 witness trees.
- 1891 F. A. Bratke found a stone monument and bearing trees.
- 1902 E. C. Burns found stone monument.
- 1995 Winona County Surveyor found stone monument.
- August, 2000 Johnson & Scofield, Inc. found the above mentioned stone monument. The stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the east quarter corner of Section 1 and to the north quarter corner of Section 1. The stone monument was left as found and a 1 inch by 18 inch iron pipe was driven along side.

	NE COR. S. 1, T. 108, [C.] INDEX NO.
	CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
	NORTHWEST Corner of Section 6 Township 108 Range 16 5TH P.M.
	STATE OF MINNESOTA, County of Winong
	At the corner location shown on the sketch:
	M On: 7/20/1995 found a CUT STONE THAT WAS CRACKED DATE
	☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)
	On:placed a
	CIVETOU OF DEFENDENCE TIES
	SKETCH OF REFERENCE TIES
	SET 5/8" ROD OLD FENCE
5 5 5 8	
	TO CENTERLINE
	SET SURVEY SIGN AND POST 1.0fT NORTH 29.91ft OF ROAD EAST 29.91ft
	SET 5/8" ROD 97T
en in the second of the second	DOWN 8"
	WEST POR S
	27.20fT SET 5/8" ROD / 3
	DOWN 8"
	TO CENTERLINE
	OF ROAD SOUTH
	Statement of evidence relative to this corner location is on page 2.
	I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.
	Signature Date
	Signature Date Registration No: 17366 Winona County Surveyor
	Statement of Evidence:

with the control of the section of the control of t

and the straight of the designation of the provider of the contract of the con

many wife the property of the month of the action

<u> 1969-9-4-4-4 - 1969-9-1999-9-1999-9-1999-9-1999-9-1999-9-1999-9-1999-9-1999-9-1999-9-1999-9-1999-9-1999-9-19</u>

HISTORY -NW. 6 108-10 WHITEWATER .

6/1853

Gov't notes Deputy Surveyor North between Sections 1 and 6 75.00 Chains Indian Trail NE 80.00 Chains Set post corner to township 108 of ranges 10 and 11 west Bur Oak 10" S 77° 30' E 72 72 links Bur Oak 10" S 395 214 links

1905

E.C. Burns (Book B, Page 138) Found corner established by Parker corner OK, Marked Br Oak 12" N 32° W 78 links

1905

E.C. Burns (Plat of contract with Board of County Commissioners) Legend X = Stone monuments have been placed, map shows X

7/23/1924

E.C. Burns (certificate of location of government corner, Book 2, Page 481) Found stone established by Parker (County Surveyor in 1894) Br Oak 12" N 32' W 78 links, Set 2" x 40" witness pipe east 29'

5/15/1978

Kleinschmidt & Webber found stone monument.

or of publica

But the second of the second

7/20/1995

County Surveyor found cut stone, set survey marker sign and post 1.0' north, took ties.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
East 1/4 corner of Section_ 1 township 108 N _ RANGE 11 W 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A 5/8" I FON Pipa Over a 2" I FON Pipe X LEFT MONUMENT AS FOUND, LOWERED MONUMENT, REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A Wabasha County Monument		
SKETCH OF	REFERENCE TIES	
WAB. CO. COORD. N= 128802.25 NAD 1983 ADJ. E= 549120.55	ROAD	
·		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. LICENSE NO. 1988 LICENSE NO. 12788 LAND SURVEYOR, PROFESSIONAL ENGINEE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
COUNTY SURVEYOR COUNTY ENGINEER	DOCUMENT NUMBER	

- During the Original Public Land Survey, The US Deputy Surveyor set quarter section post and made reference to 2 witness trees.
- 1924 E. C. Burns set a 2 inch iron pipe.
- 1978 Kleinschmidt & Weber found an iron monument.
- August, 2000 Johnson & Scofield, Inc. found a 5/8 inch iron pipe. The iron pipe was tied out and removed. The area was then hand dug and a 2 inch outside diameter iron pipe was found at a depth of 2 feet in the same horizontal location as the 5/8 inch iron pipe. The found 2 inch iron pipe is believed to be the same one as set by E. C. Burns in 1924 and is substantiated by measurements made to the northeast corner and southeast corner of Section 1. Two 1 inch by 18 inch iron pipes were placed above the found 2 inch iron pipe, one on top of the other, with a 2 inch diameter cast iron cap, stamped, "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
North 1/4corner of section 2township 108 N, range 11 W ,5thp.m. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	MENT, _ REMOVED MONUMENT (EXPLAIN)	
X ON8/2000 PLACED A Wabasha Cou	Noty Monument	
SKETCH OF RE		
SKETCH OF REFERENCE TIES WAB. Co. Coord. N= 131462.17 E= 54117.20 SE COR. SEC 34 T. 109, R. 11 FENCE LINE X N 74 COR. SEC 2 T 108, R. 11 X N 74 COR. SEC 2 T 108, R. 11		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. Own Own Own Own	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

•

1850s No corner was set during the Original Public Land Survey.

August, 2000 Johnson & Scofield, Inc. established this corner at the midway position between the northeast and northwest corners of Section 2 and on the line of the standard parallel using the standard corners to the north. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

Northcast CORNER OF SECTION 2 TOWNSHIP 108 N, RANGE 11 W Sth p.m. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON \$\frac{1}{2000}\$ FOUND A Pile of Small Stones and the Remains of a wood stake X LEFT MONUMENT AS FOUND, LOWERED MONUMENT, REMOVED MONUMENT (EXPLAIN) X ON \$\frac{1}{2000}\$ PLACED A Wabasha County Monument		
SKETCH OF REFERENCE TIES N=131446.19 WAB. CO. COORD. E=543831.04 NAD 1983 ADJ. OLD FENCE LINE N=131446.19 WAB. CO. COORD. N=543831.04 NAD 1983 ADJ.		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LICENSE NO. 12788	IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

1850s The US Deputy Surveyor intersected the standard parallel number 2 at quarter section post in south boundary of Section 35 of Township 109 North, Range 11 West.

August, 2000

Johnson & Scofield, Inc. excavated with a backhoe an area 12 feet by 18 feet to a depth of 3 feet. The excavation was centered on the north-south Township Road and a fence line running west. An old road was found at a depth of 1 foot and was built on natural ground. A pile of small stones was found at a depth of 2 feet on east edge of the hole with remnants of an old wood post beneath. The pile of stones was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the east quarter corner of Section 2 and to the southeast corner of Section 34, Township 109, Range 11. A 1 inch by 18 inch iron pipe was driven in the center of the pile of stones. A second 1 inch by 18 inch iron pipe, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top, was set above.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East 14 CORNER OF SECTION 2 TOWNSHIP 108 N RANGE 11 W 5thp.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A Stone Monument _ LEFT MONUMENT AS FOUND, X LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) x ON 8/2000 PLACED A Wabasha County Monument SKETCH OF REFERENCE TIES ROAD N= 128875.77 WAB. CO. COOPP. E=543849.62 NAD 1983 ADJ TOWNSHIP FOAD **TENCE** LINE C CENTERLINE TOWNSHIP STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET. I HEREBY CERTIFY THAT THIS DOCUMENT AND THE OFFICE OF THE REGISTER OF DEEDS DATA CONTAINED HEREIN WAS PREPARED BY ME OR COUNTY OF ___ UNDER MY DIRECT SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT______.M. ON THE _____DAY OF _____A.D., 20___ LICENSE NO. (2788 REGISTER OF DEEDS_____ LAND SURVEYOR, _ PROFESSIONAL ENGINEER

COUNTY SURVEYOR,

_ COUNTY ENGINEER

DOCUMENT NUMBER_____

During the Original Public Land Survey, the US Deputy Surveyor set a 1/4 section post and made reference to two witness trees.

August, 2000

Johnson & Scofield, Inc. excavated with a backhoe at the intersection of the centerline of a north-south township road with the easterly projection of a fence line to the west. The excavation was 6 feet by 10 feet by 3 feet. A 6 inch by 8 inch by 14 inch stone monument was found at a depth of 2.5 feet. The stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast corner and southeast corner of Section 2. The stone monument was lowered and a 1 inch by 18 inch iron pipe was placed along side. Two 1 inch by 18 inch iron pipes were placed above the stone monument, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey monument", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
North 14 CORNER OF SECTION 3 TOWNSHIP 100 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha		
AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	IMENT, REMOVED MONUMENT (EXPLAIN)	
X ON 8/2000 PLACED A Wabasha County Monument		
SKETCH OF RE	FERENCE TIES	
SE COR SEC 33 T. 109, R. 11	•	
WAB. CO. COORD. N= 131491.88 NAD 1983 ADJ. E= 535896.39	N= 131491.66 WAB. Co. COORD. E=535925.57 NAD 1983 ADJ.	
TOWNSHIP	ROAD	
HENCE X	N 1/4 COR. SEC 3 T. 10B, R. 11	
→	- 13′±	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE DATE	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LICENSE NO. 12788	REGISTER OF DEEDS DEPUTY	
LAND SURVEYOR, PROFESSIONAL ENGINEER COUNTY SURVEYOR, COUNTY ENGINEER	DOCUMENT NUMBER	

-

1850s No corner was set during the Original Public Land Survey.

November, 1992 David A. Johnson excavated with a backhoe at the intersection of the centerline of the Township Road and a fence line running south. Nothing was found.

August, 2000 Johnson & Scofield, Inc. established this corner at the midway position between the northeast and northwest corners of Section 3 and on the line of the standard parallel using the standard corners to the north. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northast corner of Section 3 Township 108 N RANGE 11 W 5thp.M.		
STATE OF MINNESOTA, COUNTY OF Wabasha at the corner location shown on the sketch:	·	
X ON 8/2000 FOUND A 1/2" Steel mor	iument	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT	AFINT Y PEMOVED MONIMENT (EXPLAIN)	
_ LEFT MONOMENT AS FOUND, _ LOWERED MONOR	TENT, A REMOVED MOROMENT (EXICANT)	
x ON8/2000 PLACED A Wabasha County Monument		
SKETCH OF REFERENCE TIES		
SY4 COR OF SEC 34		
WAB. Co. COORD. N= 131472.06 NAD 1983 ADJ. E= 538576 38		
WAB. CO. COORD. N= 131472.06	N=131472.02 WAB. CO. COORD.	
NAD 1983 ADJ. E= 538526.38	E=538536.28 NAO 1983 AD.	
TWP. RD.		
(Gov'T. 9.90) NE COR OF SEC 3		
\$ MEAS. T. 108, R. 11		
山		
CENTERLINE TWP. RD.		
TER 7		
•		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT—SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
Vauril- mon 10/30/2000	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
SIGNATURE DATE	REGISTER OF DEEDS	
LICENSE NO. [2788]		
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1850s During the Original Public Land Survey, the US Deputy Surveyor set post for section corner and made reference to 2 witness trees.

1890 William Fraser set stone monument.

1961 John Kerr set 1/2 inch steel monument at corner.

August, 2000 Johnson & Scofield, Inc. found 1/2 steel monument set by John Kerr. An excavation was made with a backhoe at the location of the above mentioned 1/2 inch steel monument. The excavation was 12 feet north and south, 25 feet east and west and to a depth of 4 feet. Nothing was found. It was determined that the road was most likely in a cut section.

The 1/2 inch steel monument set by John Kerr was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the southeast and southwest corners of Section 34, Township 109, Range 11. The found 1/2 inch steel monument was replaced with two 1 inch by 18 inch iron pipes, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
East 1/4 CORNER OF SECTION_3 TOWNSHIP 108 N_RANGE_11 W 5th p.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X_ ON 8/2000 FOUND A 2" I ron Pipe and A Limestone Monument X_ LEFT MONUMENT AS FOUND, LOWERED MONUMENT, REMOVED MONUMENT (EXPLAIN) X_ ON 8/2000 PLACED A Wabasha County Monument.		
SKETCH OF RE	FERENCE TIES	
SKETCH OF REFERENCE TIES N=128904.49 WAB. Co. COORD. N=538595.58 WAD. 1963 RDJ. Z"IRON PIPE SET BY JOHN KERR IN 1961 NOW REMOYED PENCE LINE X SUBSTATION AND NOTE SUBSTATION AND NOTE SUBSTATION NAME NOTE NAME NOTE NAME NOTE NAME NOTE NAME NOTE NAME NOTE NAME NAME NOTE NAME NAM		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12788 LAND SURVEYOR, — PROFESSIONAL ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20 REGISTER OF DEEDS, DEPUTY	
COUNTY SURVEYOR. COUNTY FINGINFER	DOCUMENT NUMBER	

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

John Kerr, on survey in Section 2 for People's Coop Power, placed a 2 inch iron pipe at the corner.

August, 2000 Johnson & Scofield, Inc. found the 2 inch iron pipe placed by John Kerr on the westerly edge of the township road and at a fence line running west. An excavation was made with a backhoe at the location of the found 2 inch iron pipe. The excavation was 8 feet by 12 feet to a depth of 5 feet. An 8 inch by 12 inch by 14 inch limestone was found at the 5 foot depth approximately 7 feet east of the 2 inch iron pipe. The found limestone was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast corner and the southeast corner of Section 3. A 1 inch by 18 inch iron pipe was driven along side the stone monument. Two 1 inch by 18 inch iron pipes were placed above the stone, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
North 1/4 CORNER OF SECTION 4 TOWNSHIP 108 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A Stone Monument Laying Down		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, & REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A Wabasha County Monument		
SKETCH OF REFERENCE TIES		
S'LY PROJECTION OF SCO. RO. # 4 &		
WAB. Co. Coopp. N= 131525.46 NAD 1983 ADJ. E= 530626.55	N=131524.97 WAB. CO. COORD. E=530698.65 NAD 1983 ADJ.	
TOWNSHIP 72.1	ROAD	
SE COR SEC 32) T. 109, R. 11 Y 30' T. 108, R. 11 Y 30' N Y4 COR. SEC 4 T. 108, R. 11		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. Oldown Oldown	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1850s No corner was set during the Original Public Land Survey.

1890 William Fraser set a stone monument.

August, 2000

Johnson & Scofield, Inc. excavated with a backhoe at the centerline of the Township Road running east and west and a fence line running south. The excavation was 15 feet by 12 feet to a depth of 5 feet. Nothing was found. A second excavation was conducted 30 feet east, which better fit the position of the stone as set by William Fraser in 1890. A 26 inch by 10 inch by 6 inch stone monument was found lying down. The position of the stone monument was re-established by measuring 72.10 feet east, which is the distance shown by William Fraser in 1890, from the found stone monument set by William Fraser in 1890 at the southeast corner of Section 32, Township 109, Range 11 and was placed on a straight line between said stone monument at the southeast corner of Section 32 and a found stone monument at the south quarter corner of Section 33, Township 109, Range 11. The stone monument was removed and two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
Corner of Section	$\frac{4}{10}$, Township $\frac{108}{108}$, Range $\frac{11}{100}$, $\frac{5^{TH}}{100}$ P.M.	
STATE OF MINNESOTA, County of Wabash	<u>a</u>	
At the corner location shown on the sketch:		
□ Onfound a	· · · · · · · · · · · · · · · · · · ·	
☐ left monument as found, ☐ lowere	ed monument,	
☑ On <u>Fab. 1993</u> placed a	n pipe 2"dia castiron cap.	
SKETCH OF RE	EFERENCE TIES	
SKETCH OF REFERENCE TIES Spike St face Power Pole 4 gravel Town Rd. Spike St face Power Pole Spike St face Power Pole Power Pole Power Pole Power Pole Power Pole Power Po		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under County of County of		
my direct supervision. 2/18/93 SIGNATURE DATE	I hereby certify that this document was filed in the Reg. of Deeds office at M. on the A.D., 1923 Register of Deeds	
Registration No. Professional Engineer	By Karleen M Jane, Deputy DOCUMENT NO.	
County Surveyor, County Engineer		

Statement of Evidence:

NORTHEAST CORNER OF SECTION 4, TOWNSHIP 108 N, RANGE 11 W

Approximately 1855

Michael Karrick, Deputy Surveyor, set a charred stake at the corner during the original Public Land Survey. No bearing trees were referenced.

Feb. 1993

Norbert J. Rehder, Land Surveyor with Johnson, Scofield & Rehder Inc., searched the area with a magnetic locator and found no monument. corner was remonumented using obliterated methods at the intersection of the fence line along the east line of Section 4, south of State Highway Number 42, projected northerly with the centerline of the Township Road that runs east and west along the Township line. The position for this corner fell where the road is substantially higher than the adjoining land. It appeared that the adjoining land was wet and that substantial storm waters had moved through this area for long periods of time. It was decided that an excavation would be unproductive and very difficult because of the dept of the road fill and silt below the road bed. It was felt that if there had been any monument evidence it was long ago removed by storm waters moving through the area and or by road construction. The obliterated corner position was verified by measurements to occupational evidence to the east. It was felt that this position best perpetuates the original Public Land Survey corner and a Wabasha County Monument was installed and referenced out.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Northcast corner of section 4 TOWNSHIP 108 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: __ ON____FOUND A _ _ LEFT MONUMENT AS FOUND. _ LOWERED MONUMENT. _ REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A Wabasha County Monument SKETCH OF REFERENCE TIES FOUND 5/8" IRON PIPE WAB. CO. COORD. NAD 1983 ADJ. NOW REMOVED N= 131507.62 N=131507.30 WAB. CO. COORD. E = 533 262.03 E= 533314.83 NAD 1983 ADJ ROAD TOWNSHIP 11.31 52:80 WAB. CO. MON. SET IN 1993 NOW REMOUZD -19.53 NE COR. SEC 4 5 1/4 COR. SEC 33 T. 108, R11 T. 109, R. 11 STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET. OFFICE OF THE REGISTER OF DEEDS I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR COUNTY OF ___ UNDER MY DIRECT SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT______.M. ON THE _____DAY OF ______A.D., 20___ DATE LICENSE NO. 12788 REGISTER OF DEEDS_____ LAND SURVEYOR,

DOCUMENT NUMBER____

_ PROFESSIONAL ENGINEER

_ COUNTY ENGINEER

COUNTY SURVEYOR.

1850s During the Original Public Land Survey, the US Deputy Surveyor set a post in mound with trench pits and charred stake and planted osage orange seeds at each angle.

1890 William Fraser set a stone monument.

February, 1993 Norbert Rehder, with Johnson, Scofield & Rehder, Inc., set a Wabasha County monument at the corner using obliterated methods. Norbert Rehder decided not to dig for the corner with a backhoe because of the amount of fill on the Township Road.

Johnson & Scofield, Inc. excavated for the stone set by August, 2000 William Fraser in 1890 with a backhoe. The excavation was 18 feet by 15 feet to a depth of 12 feet, which reached into natural soil. At a depth of 8 to 10 feet, remnants of an old concrete bridge was found. It was determined that the area was most likely disturbed during re-construction of the Township Road and the stone place by William Fraser was destroyed. A second excavation was made for a stone monument place by William Fraser at the south quarter corner of Section 33, Township 109, Range 11. This excavation was 12 feet by 6 feet to a depth of 8 feet. At a depth of 7 feet, a 24 inch by 14 inch by 4 inch pointed stone was found with the point up. The northeast corner of Section 4 was then established at a distance of 52.8 feet, which is government measure east of the found stone monument at the south quarter corner of Section 33 and was placed on a straight line between the southeast corner of Section 33 and the south quarter corner of Section 33. This is the same position which William Fraser set the stone monument in 1890 and best perpetuates the Original Public Land Survey Corner. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East 1/4 corner of section 4 township 108 N _ range 11 W _5th _ p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A I " I Tron PIPQ X LEFT MONUMENT AS FOUND, LOWERED MONUMENT, REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A Wabasha County Monument	
SKETCH OF REI	FERENCE TIES
TIELO FENCE X-INE X	TIELD N=128982.99 E=533313.78
HENCE LINE	FIELD
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. LOCAL DATE LICENSE NO. 12788 LAND SURVEYOR, PROFESSIONAL ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

•

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

March, 1979 Harry S. Johnson Companies, Inc. set a 1 inch by 30 inch pipe at a 4 way fence intersection for the corner.

August, 2000 Johnson & Scofield, Inc. found the 1 inch iron pipe at a 4-way fence intersection. An electronic metal detector was used to search the area for additional monumentation. The area was also probed and dug by hand and nothing was found.

The found 1 inch iron monument was accepted as the best perpetuation of the Original Public Land Survey Corner and is substantiated by measurements to the northeast corner and southeast corner of Section 4. A 2 inch diameter cast iron cap, stamped "Survey Marker", was affixed to the top of the found 1 inch iron pipe.

CERTIFICATE OF LOCATION (OF GOVERNMENT CORNER	
North 1/4 corner of section 5 township 108 N, range 11 W, 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A 1/2 IRON ROD		
★LEFT MONUMENT AS FOUND, LOWERED MONUMENT, REMOVED MONUMENT (EXPLAIN)		
x ONII/2000 PLACED A Wabasha County Monument		
SKETCH OF REFERENCE TIES		
OLD DOWNED FENCE N=131561.45 WAS. Co. COORD. E=525438.05 NAD 1983 RD.		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SURERVISION. SIGNATURE LICENSE NO. 15 LOVE DOCUMENT AND THE DATE LICENSE NO. 15 LOVE DOCUMENT AND THE DATE LICENSE NO. 17 88 LAND SURVEYOR PROFESSIONAL ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20 REGISTER OF DEEDSDEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1850s No corner was set during the Original Public Land Survey.

1890 William Fraser set an iron stake.

August, 2000

Johnson & Scofield, Inc. found a 1/2 inch iron rod at the intersection of old fence remnants running west with old fence remnants running south. Measurements made from the found 1/2 inch iron rod to the south quarter corner of Section 32, Township 109, Range 11 and measurements made to the southeast corner of Section 31, Township 109, Range 11 agree with those measurements shown by William Fraser in 1890. The location of the north quarter corner of Section 5 was established at the intersection of the line of the standard parallel, using the standard corners to the north, with a line between the south quarter corner of Section 5 and the found 1/2 inch iron rod. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Northeast corner of Section 5 TOWNSHIP 108 N, RANGE 11 W, 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON B/2000 FOUND A Stone Monument _ LEFT MONUMENT AS FOUND, & LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) ON 8/2000 PLACED A Wabasha County Monument SKETCH OF REFERENCE TIES N= 131545.04 WAB. CO. COOPP. E=528082.62 NAD 1983 ADJ. FENCE LINE -1.95 FOUND STONE FOUND \$8" IRON MONUMENT PIPE (NOW REMOVED) STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET. I HEREBY CERTIFY THAT THIS DOCUMENT AND THE OFFICE OF THE REGISTER OF DEEDS DATA CONTAINED HEREIN WAS PREPARED BY ME OR COUNTY OF _ UNDER MY DIRECT SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT______.M. ON THE _____DAY OF ______A.D., 20___ DATE LICENSE NO. 12788 REGISTER OF DEEDS_____ _____ DEPUTY LAND SURVEYOR, _ PROFESSIONAL ENGINEER

DOCUMENT NUMBER

COUNTY SURVEYOR,

_ COUNTY ENGINEER

northeast corner of Section 5, Township 108 North, Range 11 West

During the Original Public Land Survey, the US Deputy Surveyor set a post and made reference to 2 witness trees.

1890 William Fraser set a stone monument.

May, 1975 Harry S. Johnson Companies set a 5/8 inch iron pipe.

August, 2000 Johnson & Scofield, Inc. excavated with a backhoe at the location of the 5/8 inch iron pipe set by Harry S. Johnson Companies. A stone monument was found approximately 2.8 feet east of the 5/8 inch iron pipe at a depth of 5 inches. The stone was lowered 2 feet and a 1 inch by 18 inch iron pipe was placed on the east side. The northeast corner of Section 5 was established at the intersection of the line of the standard parallel, using the standard corners to the north, with a line from the east quarter corner of Section 5, projected northerly, through the found stone monument. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
East Quarter Corner of Section 5, Township 108, Range 11, 5TH P.M.		
STATE OF MINNESOTA, County ofWabasha		
At the corner location shown on the sketch:		
on 5/26/94 found a limerack		
DATE		
left monument as found, lowered monument, removed monument (explain)		
On DATE placed a 1 X 10	iron pipa directly above	
to on 5/26/94 placed a 1" X 18" iron pipa directly above stone & balow road bituminous		
SKETCH OF REFERENCE TIES		
1 4	62.62	
- N -		
	7	
48.33	5pika	
	MIN face	
	Power	
	Pole	
į į		
Corres Novto		
Spika North face power		
9010		
7.		
3		
2	28.26 Spike top	
9	quard Post	
3	J	
Statement of suidence velative to this corner legation is on hack of page		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data	OFFICE OF THE DEGISTER OF DEEDS	
contained herein was prepared by me or under my direct supervision	County of	
Klavila (Musm 6/13/an	I hereby certify that this document was filed in the Reg. of Deeds office at 1.30 A.M. on the	
SIGNATURE DATE	A.D. 194	
Registration No	Register of Deeds Healding Suhar By Marlein M Janus, Deputy	
County Surveyor, County Engineer	DOCUMENT NO	

Statement of Evidence:

East Quarter corner of Section 5, Township 108, Range 11

May 26, 1994

David A. Johnson, Wabasha County Surveyor, excavated a 10 by 10 foot area, 4 feet deep to native subsoil. A slab of lime rock was recovered with the butt end down and standing plumb at about a level of 3 feet, just below an old road bed. The found stone was accepted as a perpetuation of the original Public Land Survey corner and left in place. An iron pipe was placed along the north side of the stone to magnetize it. An 1 inch by 18 inch iron pipe was set above the stone so that the top of the pipe would be below the level of the bituminous.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER North 1/4 corner of section 6 township 108 N , range 11 W , 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha.		
AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN)		
x ON 1/2000 PLACED A Wabasha County Monument		
SKETCH OF REFERENCE TIES		
CENTERUNE COURT	N= 131592.48 WAB. CO. COORD. E=520196.66 NAD. 1983 RD.). 47.93 T. WAB. CO. MON. SET INCORRECTLY IN 1986	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. WITH A STORY OF THE PROPERTY OF THE PROP	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	THEDAY OFA.D., 20 REGISTER OF DEEDS	
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1850s No corner was placed during the Original Public Land Survey.

September, 1986 Norbert Rehder, with Johnson & Scofield, Inc., placed a Wabasha County monument midway and on a straight line between the northeast and northwest corners of Section 6.

November, 2000 Johnson & Scofield, Inc. reviewed the methods used by
Norbert Rehder in 1986 and discovered that because Section 6
is on the west side of the Township, the north quarter corner
should have been prorated against government measure and not
placed midway.

The location for north quarter corner of Section 6 was established on the line of the standard parallel using the standard corners to the north and at a proportional distance between the northeast corner and the northwest corner of Section 6, using a measured distance compared to the distance shown on the original government plat. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER				
	,Township <u>108</u> ,Range <u>11</u> , <u>5th</u> P.M.				
STATE OF MINNESOTA, County of Wabasha	· · · · · ·				
At the corner location shown on the sketch:					
On found a					
DATE	and manufacture of the second manufacture to the second manufacture of				
	ed monument, removed monument (explain)				
図 On <u>Sept. 1986</u> placed a <u>Wabasha Cour</u>	nty Monument				
SKETCH OF RE	EFERENCE TIES				
4 6. Rd. No.8					
Spike in a Power Pole					
Wobasha Co. Mon. 66.86	Spike in 6" Spike in 6"				
0/5/2000 \$ 36					
T. 109, P. 12 152.83					
	(3,5)				
Wabasha co. Mon. @	5				
N 1/4 Cor. Sec. 6.	Spika 30"				
	Boxalder				
	·				
Statement of evidence relative to this corner loc	cation is on back of page.				
I hereby certify that this document and the data	OFFICE OF THE REGISTER OF DEEDS				
contained herein was prepared by me or under	County of <u>Avalante</u>				
my direct supervision.	I hereby certify that this document was filed in the Reg. of Deeds office at 11:36 & .M. on the				
tavid A. Johnson 23 Sept. 1986 SIGNATURE DATE	23 and day of A.D., 19£4				
Registration No.					
Land Surveyor, Professional Engineer By					

NORTH QUARTER CORNER OF SECTION 6, TOWNSHIP 108, RANGE 11

No monument was placed during the original Public Land Survey.

Sept. 1986

Norbert Rehder, with Johnson & Scofield placed a Wabasha County Monument midway and on a straight line between the northeast and northwest corners of Section 6. Since the corner was never placed during the original Public Land Survey "obliterated corner" rules do not apply.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
Northeast Corner of Section 6	,Township <u>108</u> ,Range <u>11</u> , <u>5th</u> P.M.
STATE OF MINNESOTA, County of Wabasha	
At the corner location shown on the sketch:	,1
☐ On Sept. 1986 found a 8 inch by 8	stona inch by 18 inch rough^standing plumb ed monument, □ removed monument (explain)
☑ On Sept. 1986 placed a Wabasha cour	nty Monument
SKETCH OF RE	EFERENCE TIES
Lenter top vertical Railroad rail 10 10 10 10 10 10 10 10 10 1	Spika in Power Pola 61:30 Spika in Spika in Wabasha Co. Mon. @ NE Cor. 5.6
Statement of evidence relative to this corner loc	ation is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. David A. Johnson 13 Sept. 1986 Date	OFFICE OF THE REGISTER OF DEEDS County of
County Surveyor, County Engineer	DOCUMENT NO.

NORTHEAST CORNER OF SECTION 6, TOWNSHIP 108, RANGE 11

1855

During the original Public Land Survey a wood post was placed and 2 trees were witnessed.

Sept. 1986

Norbert Rehder, with Johnson & Scofield Inc., and Ray Fisk, with the Wabasha County Engineering Department, excavated with a backhoe and recovered a 8 inch by 8 inch by 18 inch rough stone standing plumb. Three flat stones were found below the plumb stone. The stones fit existing occupation lines and were accepted as a perpetuation of the original Public Land Survey corner. The stones were lowered and a Wabasha County Monument was placed directly above.

CERTIFICATE OF LOCATION C	OF GOVERNMENT CORNER
East Y4 CORNER OF SECTION 6 TOW STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH:	NSHIP 108 N , RANGE 11 W , 5th P.M.
ONFOUND A	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUM	ENT, _ REMOVED MONUMENT (EXPLAIN)
X ON 8/2000 PLACED A Wabasha Co	unty Monument
SKETCH OF REF	ERENCE TIES
TOWNSHIPS A STANSON OF TOWNSHIPS AND TOWNSHI	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORN	NER LOCATION IS ON THE BACK OF THIS SHEET.
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20
LICENSE NO. 12788	REGISTER OF DEEDS
LAND SURVEYOR PROFESSIONAL ENGINEER	BY DEPUTY
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

August, 2000 Johnson & Scofield, Inc. excavated with a backhoe at the intersection of the centerline of the north-south township road with a fence line running east and fence line running west. The excavation was 15 feet by 15 feet to a depth of 7 feet. Nothing was found.

The intersection of the centerline of the north-south township road with the fence line running east and the fence line running west was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 6. Two 1 inch by 18 inch iron pipes were place, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
North 1/4 CORNER OF SECTION 7 TON STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A 1" X 3' 1101 PIN	
* LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT	
SKETCH OF RE	FERENCE TIES
SKETOT OF KE	 -
	N=126476.69 WAB. CO. COORD. E=520188.35 NAD 1983 RDJ.
COUNTY ROAD	NO. 79
L Z K	
H H N S A	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORN	NER LOCATION IS ON THE BACK OF THIS SHEET.
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. MMA. Many 3/04.2000	OFFICE OF THE REGISTER OF DEEDS COUNTY OF I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THE DAY OF A D 20
SIGNATURE DATE LICENSE NO. 12788	THEDAY OFA.D., 20 REGISTER OF DEEDS
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY, DEPUTY
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post in mound with trench, pits and charred stake and planted osage orange seeds northeast and southwest.

February, 1949 John Kerr, on survey in Section 7 for People's Cooperative Power Association, found a hole in the sub-soil 3 inches in diameter and 1 foot in depth. He set a 1 inch by 3 foot long iron pipe in the stake hole for the corner.

August, 2000 Johnson & Scofield, Inc. found the 1 inch by 3 foot iron pipe set in 1949 by John Kerr.

The 1 inch by 3 foot iron pipe, set in 1949 by John Kerr, was accepted as the best perpetuation of the Original Public Land Survey Corner. A 2 inch diameter cast iron cap, stamped "survey marker", was affixed to the top of the found iron pipe.

CERTIFICATE OF LOCATION (OF GOVERNMENT CORNER
Northcastcorner of section_7tow STATE OF MINNESOTA, COUNTY OFWabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND AI"X 3' Rebar LEFT MONUMENT AS FOUND,LOWERED MONUM X ON 8/2000 PLACED AWabashaCo	MENT, X REMOVED MONUMENT (EXPLAIN)
SKETCH OF REF	N= 126405.51 WAB. CO. COORD. E= 522798.45 NAD 1983 ADJ. TOWNSHIP ROAD CENTERLINE
STATEMENT OF EVIDENCE RELATIVE TO THIS CORN	NER LOCATION IS ON THE BACK OF THIS SHEET.
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. 1 HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA OR UNDER MY DIRECT SUPERVISION. 1 HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA OR UNDER MY DATE OR UNDER MY DATE 1 HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA OR UNDER MY DATA OR UNDE	OFFICE OF THE REGISTER OF DEEDS COUNTY OF

During the Original Public Land Survey, the US Deputy Surveyor set a post in mound with trench, pits, and charred stake and planted osage orange seeds at each angle.

August, 2000

Johnson & Scofield, Inc. searched at the intersection of the centerline of a township road running north and a township road running east with an electronic metal detector. A 1 inch by 3 foot rebar was found 6 inches below the surface of the road on the centerline of the township road running east and approximately 5 feet east of the centerline of the township road running north. An excavation was made with a backhoe at the location of the found rebar. The excavation was 15 feet by 15 feet to a depth of 3 feet. Nothing was found. After the excavation, it was determined that the road was in a cut section.

The found 1 inch by 3 foot rebar was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the north quarter corner of Section 8 and measurements made to the north quarter corner of Section 7 and measurements made to the east quarter corner of Section 7. The rebar was removed and two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

STATE OF MINNESOTA, County of WABASHA At the corner location shown on the sketch: \[\text{\text{M}} \] On \[\frac{5/16/88}{DATE} \] \[\text{\text{backhoe.}} \] \[\text{left monument as found, } \[\text{lower.} \]	
SECTION RETCH OF R S.R.P. Disc. OS.B. P. Dis	Natural Gas Substation Gravel Dr. 1/2"Rebar NW. Cor. Cook Tombstone Cermetary Cermetary
Statement of evidence relative to this corner loc	cation is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Walter County Surveyor County Engineer County Surveyor County Engineer County En	OFFICE OF THE COUNTY RECORDER County of

March

EAST QUARTER CORNER, SECTION 7, TOWNSHIP 108 NORTH, RANGE 11 WEST, 5TH P.M., WABASHA COUNTY, MINNESOTA.

June 1854 Michael G. Karrick, Deputy Surveyor, set a post with trench, pits, charred stake and Osage orange seeds at the corner during the Public Land Survey.

1968 Leonard G. Nelson Associates shows a monument 13 feet west of the center line of the County Road during the survey for the plat of Hillcrest Second Addition.

Wabasha County Engineer County Road Plans indicate that a Point of Intersection Control Monument was set at the center line during road reconstruction.

August 1978 Yaggy Associates, Inc. found no monumentation at the corner during a survey for the Plainview Catholic Cemetery.

March 1979 Yaggy Associates, Inc. set a P.K. nail at the center line of the County Road, and on line with a fence to the east. The P.K. nail was used to mark occupation lines for Section analysis only.

May 1988 Yaggy Colby Associates excavated at the west edge of the County Road and on line with the fence east. No monuments were uncovered. A 3/4" x 18" iron pipe was set based on the previous Hillcrest Second Subdivision plat and the 1979 Cemetery Survey.

An analysis of the record and survey data indicates that the 3/4" x 18" iron pipe is accepted as marking the East Quarter Corner of Section 7.

For further information regarding this survey, contact Yaggy Colby Associates, Rochester, Minnesota.

CERTIFICATE OF LOCATION (OF GOVERNMENT CORNER				
North 1/4corner of section_8tow STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A					
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUM	MENT, _ REMOVED MONUMENT (EXPLAIN)				
X ON 8/2000 PLACED A Wabasha County Monument					
SKETCH OF RE	FERENCE TIES				
	. '				
<u>m</u>					
LI X					
H H H H	N=126421.30 WAB. CO. COOPD. E= 525459.37 NAD. 1983 ADJ.				
TOWNSHIP	ROAD				
CENTERLINE	MONUMENT SET IN 1988 BY YAGGY ASSOC.				
	1				
<i>,</i>					
	<u> </u>				
STATEMENT OF EVIDENCE RELATIVE TO THIS CORT	NER LOCATION IS ON THE BACK OF THIS SHEET.				
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF				
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20				
LICENSE NO. 12788	REGISTER OF DEEDS				
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY DEPUTY				
COUNTY SURVEYOR COUNTY ENGINEER	DOCUMENT NUMBER				

•

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

December, 1917 John Rafter, County Surveyor, plats M. J. COSTELLO'S SUBDIVISION in the East Half of the Southeast Quarter of Section 5. The measurement shown on the plat, along the south line of the East Half of the Southeast Quarter is 1331.7 feet. This would indicate that the south line of the Southeast Quarter of Section 5 should measure 2663.4 feet.

June, 1988 Donald R. Borchording of Yaggy Associates, Inc. excavated in the intersection of the centerline of the township road running east and west with a fence line running north and also excavated in the centerline of the township road 22 feet east of the fence line running north. Nothing was found. They placed a 3/4 inch by 18 inch iron pipe at the intersection of the centerline of the township road with a line from the south quarter corner of Section 8, projected northerly through a found 1 and 1/2 inch iron pipe at the center of Section 8. This position falls 21 feet east of the intersection of the centerline of the township road with the fence line running north.

Johnson & Scofield, Inc. found the monument set by Don Borchording in 1988. The distance was measured from the found monument to the northeast corner of Section 8 and found to be approximately 23 feet shorter than the dimension as determined from the recorded plat of M. J. COSTELLO'S SUBDIVISION.

The dimension from the intersection of the centerline of the township road with the fence line running north to the northeast corner of Section 8 agrees with the dimension as determined from the recorded plat of M. J. COSTELLO'S SUBDIVISION and is accepted as the best perpetuation of the Original Public Land Survey Corner and is substantiated by measurements made to the northeast and northwest corners of Section 8. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

August, 2000

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER NORTH QUARTER Corner of Section 8, Township 108N, Range 11W, 5TH P.M. STATE OF MINNESOTA, County of WABASHA				
At the corner location shown on the sketch:				
On 5/16/88 אַאָאָאָאָא <u>no monumentation was found after excavating with</u>				
backhoe. □ left monument as found, □ lowered monument, □ removed monument (explain)				
On $\frac{5/16/88}{\text{DATE}}$ placed a $\frac{3/4\text{"} \times 18\text{"}}{\text{surface.}}$ for inches below gravel surface.				
SKETCH OF REFERENCE TIES				
1 Λ				
4				
-N-				
↑				
SECTION * 5				
*				
75'				
1/2" Rebar Down 0.5				
49.79				
TWSP. RD. (Gravel)21'				
27.78				
▼ 「				
47.3' 40.0'				
Green Painted Green Painted Fence Post Fence Post				
SECTION 8				
Statement of evidence relative to this corner location is on back of page.				
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER				
contained herein was prepared by me or under County of Waland				
my direct supervision. I hereby certify that this document was filed in the Reg. of Deeds office at // a. M. on the				
Mary of mkust 6/27/88 Steday of my A.D. 1962				
Registration No. 10168 Register of Deeds Welling Tuba				
☑ Land Surveyor, □ Professional Engineer By,Deputy				
□ County Surveyor, □ County Engineer □ DOCUMENT NO				

NORTH QUARTER CORNER, SECTION 8, TOWNSHIP 108 NORTH, RANGE 11 WEST, 5TH P.M., WABASHA COUNTY, MINNESUTA.

June 1854 Michael G. Karrick, Deputy Surveyor, set a post with trench pits, charred stake and Osage orange seeds at the corner during the public land survey.

March 1979 Yaggy Associates, Inc. searched at the occupation lines but found no monumentation.

May 1988 Yaggy Colby Associates excavated at the occupation lines and at a point 22 feet further east, where the South Quarter Corner and the Center Section Monument projected north falls. Both excavations revealed no monumentation.

A 3/4" x 18" iron pipe was placed in position at the center line of the Township Road and the northerly extension of a line through the South Quarter Corner and a 1-1/2" iron pipe at the center of Section 8.

An analysis of the record and survey data indicates that original monumentation at the Corner had been destroyed. The position established by the center line of the road and the Center Section and South Quarter Corner monuments is a perpetuation of the original position of the Government Corner and that the 3/4" x 18" iron pipe is accepted as marking the North Quarter Corner of Section 8.

For additional information regarding this survey, contact Yaggy Colby Associates, Rochester, Minnesota.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER					
NORTHEAST SECTION Corner of Section 8	,Township <u>108N</u> ,Range <u>11W</u> ,5th P.M.				
STATE OF MINNESOTA, County of WABASHA					
At the corner location shown on the sketch:					
	FU-10U-14Ulang in C.C. A.U. No. 27				
On Sept. 2, 1994 found a Limestone mon					
_left stone inplace and set a temp. define the left monument as found, □ lowere	ed monument □ removed monument (evoluin)				
1995 😨 On October 6.1885ced a Wabasha Co	ounty Monument in patched blacktop surface				
DATE					
SKETCH OF RE	FERENCE TIES				
E.½ Corner					
Section 5	٨				
[4	A CC.				
NO. ON	SEC.				
SEC. 28.9.91. NO. 3.5. A.H. NO.	2 42				
SE oi	99 C. T.H. NO.				
	CENTER 2" PIPE CENTER 2" PIPE MAILBOX POST				
© TWSP. ROAD - 65.95'					
BO EDGE OF					
TWSP. ROAD COR. OR. OR. OR. OR. OR. OR. OR. OR. OR.					
8 SECTION FRANCE S					
8	9				
SEC. 8	SEC.				
30					
Statement of evidence relative to this corner location is on back of page.					
I horoby contifu that this document and the data	COUNTY RECORDER				
I hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS contained herein was prepared by me or under County of					
my direct supervision	I hereby certify that this document was filed in				
M_{ADa} A (Mmgm $3/13/96$ the Reg. of Deeds office at 1:30 P. M. on t					
SIGNATURE DATE	COUNTY RECORDER Register of Deeds A.D., 19 96				
Registration No. 12788- Land Surveyor, D Professional Engineer	By,Deputy				
County Surveyor. County Engineer	DOCUMENT NO.				

Statement of Evidence: N.E. CORNER SECTION 8-108-11

- Public Land Survey, Micheal Karrick, Deputy Surveyor

 Set post for corner to Sec. 4,5,8,&9

 took 4 bearing trees: Bur Oak 12 S 72°W 6 lks, Bur Oak 12 N15°W 71 lks

 Bur Oak 12 N 51°E 75 lks Bur Oak 11 S 74°E 62 lks
- 1917 Plat of M.J. Costello's Subdivision by John Rafter, Surveyor indicates a stone monument at the S.E. corner of Section 5 with a platted distance to the north to the East Quarter corner of Section 5 of 2621.0 ft. Also shows distance west to S.W. corner of Plat to be 1331.7 ft.
- 1971 Harry S. Johnson, set iron as Section corner in centerline of C.S.A.H. No. 27 apparently no digging was done.
- Johnson, Scofield, and Rehder, Red Wing, MN. Dave Johnson, Wabasha County Surveyor, dug hole in C.S.A.H. NO. 27 at location of 1971 iron monument, found nothing except iron at surface. Reset a Pipe about 12" Deep.
- Sept.2,1994, Roger W.Brand and Assoc. St.Charles,MN. dug holewith MN/DOT backhoe since corner falls in State Highway No.42 R/W. Dug hole at location of msmt from East ½ CornerSection 5 where County Surveyor Dave Johnson found Stone in 1994. Measurement used was from Costello's Plat which is 2621 feet. Hole was dug centering on centerline of C.S.A.H. No. 4 running to the north. Found a limestone standing on end 5"x10"x14" long with top of stone down 2.2' in old roadbed. Old roadbed is at top of what appears to be the original ground level. Placed a ½"x 22" iron rebar on north sideof stone and a piece of metal on south side. Also set a ½"x12" iron rebar over stone as a temporary marker until hole in blacktop surfacegetspatched.

Stone found was 6.55 ft.north and 0.60 ft.west of iron pipe previously used as this Section corner.

Measure to north was re-measured at 2619.91 feet to East $\frac{1}{4}$ corner October 6,1995 after holewas finally patchedwe removed the $\frac{1}{2}$ "x12" rod and set a Wabasha County Monument.

CERTIFICATE OF LOCATION	
	,Township $\frac{108}{}$, Range $\frac{11}{}$, $\frac{577}{}$ P.M.
STATE OF MINNESOTA, County of Wabasha	
At the corner location shown on the sketch:	
On 5/26/94 found a 5/8" X 12	l'iron pipa
	ed monument, removed monument (explain)
on 5/26/94 placed a 1"X 19" as found pipe \$ balon	road bituminous
SKETCH OF R	EFERENCE TIES Cantar 2"
- N N N N N N N N	67.95 Per Pox Post pox post
Le Harrier	
d Stone ± 6.5'N.	Rd. Mo.27
this pipe which rains inplace	VOID See cert dated 3/13/96
10	A
	Pike west face Power pole
The second secon	
Statement of evidence relative to this corner lo	cation is on back of page.
I hereby certify that this document and the data	OFFICE OF THE REGISTER OF DEEDS
contained herein was prepared by me or under my direct supervision.	I hereby certify that this document was filed in the Reg. of Deeds office atM. on the
SIGNATURE DATE	day of A.D. Ja.
Registration No. 12)88	Register of Deeds Sesseldene John
Land Surveyor, 🗆 Professional Engineer	By Market NO. Deputy
County Surveyor, County Engineer	DOCUMENT NO.

Northeast corner of Section 8, Township 108, Range 11

May 26, 1994

David A. Johnson, Wabasha County Surveyor, excavated a 10 by 10 foot area, 5 feet deep with a County backhoe to native subsoil. 5/8 inch by 12 inch iron pipe was recovered just under the surface of the bituminous. It was referenced out and the excavation was completed. No other monument evidence was recovered. A 1 inch by 18 inch iron pipe was set in the same position as the recovered 5/8 inch by 12 inch pipe. 1 inch by 18 inch iron pipe was set so that the top of the pipe would be below the bottom of the bituminous. The recovered 5/8 inch by 12 inch iron pipe was accepted as a perpetuation of the original Public Land Survey corner.

CERTIFICATE OF LOCATION O	F GOVERNMENT CORNER
EAST QUARTER Corner of Section 8	Township 108N Range 11W 5TH P.M.
STATE OF MINNESOTA, County of WABASHA	
At the corner location shown on the sketch:	
On 5/10/88 found a T-Bar Monument. DATE	recorded reference ties.
☑ left monument as found, □ lowered n	nonument, \square removed monument (explain)
□ Onplaced a	
SKETCH OF REFE	RENCE TIES
	PK. Nail in 36" Elm - 60.75 - 0
80 34" Elm 14" NO 34" Elm 34.35 *** *** *** *** *** ** ** **	SECTI SECTION
Statement of evidence relative to this corner locati	on is on back of page.
contained herein was prepared by me or under my direct supervision. I have been signature by the signature between the signature by the signa	ereby certify that this document was filed in Reg. of Deeds office at // aM. on the act day of

EAST QUARTER CORNER, SECTION 8, TOWNSHIP 108 NORTH, RANGE 11 WEST, 5TH P.M., WABASHA COUNTY, MINNESOTA.

June	1854	Michael G.	Karrick,	Deputy	Surveyor,	set a p	ost at the
		corner and Public Land		ties to	two bearin	ng trees	during the

March 1976 Tom Taylor found a T-bar monument at the corner. The t-bar lies 1.7 feet west of a fence south, and 12 feet more or less east of fence running north.

March 1979 Yaggy Associates, Inc. found the T-bar Monument at the corner.

August 1983 Goodhue County Land Surveying Company, Inc. found a t-bar at the corner.

May 1988 Yaggy Colby Associates found a T-bar Monument at the corner and recorded reference ties to the Monument.

An analysis of the record and survey data indicates the T-bar Monument is accepted as marking the East Quarter Corner of Section 8.

For further information regarding this survey, contact Yaggy Colby Associates, Rochester, Minnesota.

STATE OF MINNESOTA. County of <u>W</u> At the corner location shown on the \(\overline{\text{N}} \) On \(\frac{6-25-98}{DATE} \) found a \(\frac{NOTHING}{DATE} \)	Township 108N Range 11W 5thP.M. ABASHA sketch: vered monument removed monument	
	FERENCE TIES	
SEC N-N- 81.50 SW TO MAG NAIL IN WEST END OF 18" CMP FIELD DRIVE	26.66 NE TO 1/2" PIPE £ CO RD #27 32.46 SE TO 1/2" PIPE	
SEC 9		
Statement of evidence relative to this I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Vincent A. Fangman Licensed Land Surveyor Minnesota Registration No. 14888 6/25/1998 Date.	OFFICE OF THE COUNTY RECORDER County of	

Reviewed by Wabasha County Surveyor ______ Date _____

North Quarter Corner Section 9 T108N R11W

June 1854, Michael G. Karrick, Deputy Surveyor, set a quarter section post as per instructions and referenced to two bearing trees in the original public land survey.

June 25, 1998, Vince Fangman, private land surveyor, searched area for a corner. No monument was found. No excavation was done, since this corner falls in a four to five foot cut area in the existing County Road No. 27. There is a well established fence line running from the south and ends at the south right of way line of County Road No. 27. Some 1971 erial photographs, filed in the Wabasha County Surveyor's Office, were carefully examined to find that there was good occupation running to the north in 1971. That occupation line fell in the same line as the occupation line that ran to the south. There was also a north-south 16th occupation line running to the north located a quarter of a mile to the west of this corner, which scaled to be midway between this corner and the northwest corner. There were no 16th occupation lines to the east of this corner. Lost position was not considered because of the occupation at the center of Section 9, which the computed center of section 9 falls 12 feet east of a four way fence intersection. A Wabasha County Monument was set in line with the fence to the south and in the center of the County Road No. 27 and accepted as the public land survey corner.

STATE OF MINNESOTA. County of At the corner location shown on the \overline{\text{\tin}\text{\tetx{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\text{\text{\text{\text{\texi\text{\texi\text{\texi{\texi{\text{\texi{\texi{\texi{\text{\text{\texi}\texi{\texit	Township 108N Range 11W 5th P.M. WABASHA sketch: PE Wered monumentremoved monument
SKETCH OF RE	EFERENCE TIES
SEC 4	SEC 3 43.28 NE TO 30D SPIKE IN A 6"WALNUT 16' © OF COUNTY ROAD No.27
81.70 SE TO 30D SPIKE IN WEST FACE 15" OAK SEC 9	105.10 SE TO 30D SPIKE IN NE FACE 18"OAK SEC 10
Statement of evidence relative to this	corner location is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Vincent A. Fangman Licensed Land Surveyor Minnesota Registration No. 14888 L/25/1998 Date. Pine Land SURVEYING Date.	OFFICE OF THE COUNTY RECORDER County of
Reviewed by Wabasha County Surveyor	Date

Northeast Corner Section 9 T108N R11W

June 1854, Michael G. Karrick, Deputy Surveyor, set a section post as per instructions and referenced to four bearing trees in the original public land survey.

June 25, 1998, Vince Fangman, private land surveyor, found a half inch pipe in the center of the County Road No. 27 and in line with fences to the north and to the south. The distance to the north 16th fence line fence running south through the Northwest Quarter of Section 10 is 1338.6 feet and the distance from there to the fences running north and south near the North Quarter corner of Section 10 is 1336.8 feet. The distance from there to the center of a four way road intersection located near the northeast corner of Section 10 is 2639.6 feet. The origin of the half inch pipe is unknown. This pipe was accepted as being the public land survey corner.

STATE OF MINNESOTA. County of <u>WABA</u> At the corner location shown on the On 6-25-98 found a 6"X8" LIM DATE X left monument as found low	Township <u>108N</u> Range <u>11W</u> 5th P.M. ASHA
SKETCH OF REFERENCE TIES SKETCH OF REFERENCE TIES SECURITY SERVICE TIES STEEL POST 1.65 W TO 30D NAIL IN N FACE OF BRACE POST FENCE LINE FENCE LINE 7.772 S TO 30D NAIL IN FIRST FENCE POST SOUTH STEEL POST SOUTH	
Statement of evidence relative to this I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Vincent A. Fangman Licensed Land Surveyor Minnesota Registration No. 14888 6/25/1998 Date.	OFFICE OF THE COUNTY RECORDER County of WABASHA I herby certify that this document was filed in Co. Recorder's office at //:00 A.M. on the 2/st day of 1998. County Recorder fully ditten By Conculantains

Reviewed by Wabasha County Surveyor ______ Date _____

East Quarter Corner Section 9 T108N R11W

June 1854, Michael G. Karrick, Deputy Surveyor, set a quarter section post as per instructions in the original public land survey and reference corner to two bearing trees.

June 25, 1998, Vince Fangman, private land surveyor, found a limestone with an irregular shaped pointed top. This stone fit the occupation lines in all four directions. The stone is approximately 16 feet south of midway distance along the east line of Section 9. The stone was accepted as the public land survey corner.

CERTIFICATE OF LOCATION	OF GOVERNMEN I CORNER	
North 1/4 CORNER OF SECTION 10 TOWNSHIP 108 N. RANGE 11 W 5th P.M.		
STATE OF MINNESOTA, COUNTY OF Wabasha.		
AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
	AUDIT DEVOVED MANUALENT (EVEN MAN)	
_ LEFT MONUMENT AS FOUND, LOWERED MONU	MENI, _ KEMUYEU MUNUMENI (EXPLAIN)	
X ON 8/2000 PLACED A Wabasha Co	ounty Monument.	
	TERRING TIPE	
SKETCH OF REFERENCE TIES		
]	\	
•	2 	
Weller and a second sec	√ m _	
WAB CO. COORD. N=126338.09 NAD 1983 ADJ. E= 535995.39	× m - N - N - N - N - N - N - N - N - N - N	
	k—3′± ×	
COUNTY ROAD	NO. 27	
CENTERLINE		
×		
ន ម		
E5TABL1381E		
	าม 2	
—	ت ا	
	N C L	
	ኮ ጠ	
070		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS	
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	COUNTY OF	
O avid A. 1 moon 10/30/2000	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
SIGNATURE DATE LICENSE NO. 12788	REGISTER OF DEEDS	
	BY DEPUTY	
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER		
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

John Kerr, on survey in Section 2 for People's Coop Power, measures the south line of the Southeast Quarter of Section 3 at 2644 feet. He does not indicate any monuments in place.

August, 2000 Johnson & Scofield, Inc. searched with an electronic metal detector at the intersection of the centerline of County Road Number 27 with the fence line running south. Nothing was found. The Wabasha County Engineer was contacted for permission to excavate in County Road Number 27. The County Road had recently been overlaid with new blacktop and the excavation was prohibited.

The distance from the intersection of the centerline of County Road Number 27 with the fence line running south to the northeast corner of Section 10 agrees with the measurement by John Kerr in 1961. The intersection of the centerline of County Road Number 27 with the fence line funning south was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast corner and northwest corner of Section 10. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "Survey Marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
Northwast corner of section 10 township 108 N, range 11 W 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A Wabasha County Monument		
SKETCH OF RE	FERENCE TIES	
COUNTY ROAD CENTERLINE	N=126310.95 WAB. CO. COORD. E=538639.15 NAD 1983 ADJ.	
# HSNMOT	3′±	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12788	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR COUNTY ENGINEER	DOCUMENT NUMBER	

1850s During the Original Public Land Survey, the US Deputy Surveyor set a post in mound with pits, trench, charred stake and planted osage orange seeds at each angle.

John Kerr, on survey in Section 2 for People's Coop Power, measures the south line of the Southwest Quarter of Section 2 and also measures the south line of the Southeast Quarter of Section 3. He indicates setting a 1/2 inch steel monument at the northeast corner of Section 10.

August, 2000 Johnson & Scofield, Inc. searched with an electronic metal detector at the intersection of the centerline of County Road Number 27 with the centerline of a township road running north and the centerline of a township road running south. Nothing was found. The Wabasha County Engineer was contacted for permission to excavate in County Road Number 27 with a backhoe. The County Road had recently been overlaid with new blacktop and permission was denied.

The location for the northeast corner of Section 10 was established on the centerline of County Road Number 27 at a proportionate measure between the south quarter corner of Section 2 and the south quarter corner of Section 3 using the measured distance between the south quarter corner of Section 2 and the south quarter corner of Section 3 compared to the measured distance by John Kerr in 1961.

This position is accepted as the best perpetuation of the Original Public Land Survey Corner and is substantiated by measurements made to the east quarter corner of Section 3, the east quarter corner of Section 10, the south quarter corner of Section 2 and the south quarter corner of Section 3. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East 1/4 CORNER OF SECTION 10 TOWNSHIP 108 N RANGE 11 W 5th P.M.	
STATE OF MINNESOTA, COUNTY OF Wabasha.	
AT THE CORNER LOCATION SHOWN ON THE SKETCH:	,
ONFOUND A	
_ LEFT MONUMENT AS FOUND, LOWERED MONU	MENT, _ REMOVED MONUMENT (EXPLAIN)
X ON 8/2000 PLACED A Wabasha Co	unty Monument
SKETCH OF RE	FERENCE TIES
. \	
	N=123681-16 WAB. CO. COORD.
	E=538649.53 NAD 1983 ADJ.
FENCE LINE	
	
-	Z X X Y Y Y Y Y Y Y Y
	2 4
ľ	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	COUNTY OF
$\sqrt{2}$ $\pm i\Omega$	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED
SIGNATURE DATE	IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20
LICENSE NO. 12788	REGISTER OF DEEDS
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

August, 2000 Johnson & Scofield, Inc. excavated with a backhoe at the intersection of the centerline of the north-south Township Road and a fence line running west. The excavation was 15 feet by 8 feet to a depth of 4 feet, which reached approximately 1 and 1/2 feet into natural ground. Nothing was found.

The intersection of the centerline of the north-south Township Road with the fence line running west was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 10. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

north quarter corner of Section 11, Township 108 North, Range 11 West

1855

U.S. Deputy Surveyor, Michael Kerrick, set a wood post and reference ties were taken.

July 12, 1994

Johnson, Scofield and Rehder, Wabasha County Surveyors, searched the site for evidence of the Original Public Land Survey Corner, it's reference ties and any subsequent remonumentation, but nothing was found. The corner falls in a cut section of Wabasha County Road Number 27 and was not excavated. The north line of Section 11, along with occupation along the north-south quarter line of Section 11, was analyzed. It was determined that the centerline of Wabasha County Road Number 27, intersected with the existing fence line along the northsouth quarter line, is the best evidence of the location of the Original Public Land Survey Corner. A 1 inch by 18 inch iron pipe with 1 2 inch cast iron top was set.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
Northeast corner of Section 11 Township 108 N, RANGE 11 W, 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH:	
ONFOUND A	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	MENT, _ REMOVED MONUMENT (EXPLAIN)
x ON B/2000 PLACED A Wabasha Co	unty Monument
SVETAL AS DE	EEDENOE TEC
SKETCH OF RE	FERENCE HES
hu l	
CENTERLINE	۵
9	4
	N= 126247.88 WAB CO COORD
3	E = 543865.17 NAD 1983 ADJ.
	/
COUNTY ROAD NO. 27	
CENTERLINE	
	T S
<u> </u>	
	3
	0
ľ	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT_SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS
SWINA Mon 10/30/2000 DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20
LICENSE NO. 12788	REGISTER OF DEEDS
√	BY DEPUTY
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER	DOCUMENT NUMBER
COUNTY SURVEYOR, _ COUNTY ENGINEER	OOOUMLIT! HUMDER

1850s During the Original Public Land Survey, the US Deputy Surveyor set section post and made reference to 3 witness trees.

John Kerr, on survey in Section 2 for Peoples Coop Power, measures the south line of the Southeast Quarter at 2635 feet, but does not indicate any monuments in place.

August, 2000 Johnson & Scofield, Inc. searched with an electronic metal detector at the intersection of the centerline of County Road 27 and the centerline of a Township Road running north and the centerline of a Township Road running south. Nothing was found. The Wabasha County Engineer was contacted for permission to excavate in County Road Number 27. The County Road had recently been overlaid with new blacktop and the excavation was prohibited.

The centerline intersection was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the south quarter corner of Section 1 and measurements made to the south quarter corner of Section 2. The measurement made to the south quarter corner of Section 2 was within 1.5 feet of the measurement made by John Kerr in 1961. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION (OF GOVERNMENT CORNER	
East 14 CORNER OF SECTION 11 TOV	WISHIP 108 N RANGE II W 5th P.M.	
STATE OF MINNESOTA, COUNTY OF Wabasha.		
AT THE CORNER LOCATION SHOWN ON THE SKETCH:	, , , , , , , , , , , , , , , , , , ,	
X ON 8/2000 FOUND A Stone Monu	ment	
LEFT MONUMENT AS FOUND, LOWERED MONUMENT	MENT, REMOVED MONUMENT (EXPLAIN)	
X ON 8/2000 PLACED A Wabasha Cou	inty Manument	
A UNITY ISSUE A VESTICAL A VESTIC		
SKETCH OF REFERENCE TIES		
ام		
ROAD		
	N=123608.37 WAB. CO. COORD. E=543893.94 NAD 1983 ADJ.	
FENCE LINE	X	
× × ×		
	·	
	W Z	
<u>-</u>	Z	
	A T	
NWOT		
101	(
STATEMENT OF EVIDENCE RELATIVE TO THIS COR	NER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS	
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SURERVISION.	COUNTY OF	
DUNTALA (Moson 310+0000)	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON	
SIGNATURE DATE	THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

August, 2000 Johnson & Scofield, Inc. excavated with a backhoe at the intersection of the centerline of the north-south Township Road with a fence line running west. The excavation was 4 feet by 12 feet to a depth of 3 feet. A 6 inch by 8 inch by 17 inch stone monument was found at the top of natural ground with pieces of brick along side. The stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner. The stone was lower 2 feet and a 1 inch by 18 iron pipe was set on the east side. A second 1 inch by 18 iron pipe was place directly above the stone, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
North 1/4 corner of section 12 township 108 N, range 11 W 5th p.m STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A 5/8" Iron Pipa		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, X REMOVED MONUMENT (EXPLAIN)		
X ON 8/2000 PLACED A Wabasha County Monument		
SKETCH OF REFERENCE TIES		
	N= 126211.50 WAB. CO. COOPD. E= 546503.64 NAD 1983 ADJ.	
COUNTY ROAD	NO. 27	
CENTERLINE		
コ 2 3 4		
X A A A A		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

August, 2000 Johnson & Scoffield, Inc. found a 5/8 inch iron pipe at the intersection of the centerline of County Road Number 27 and a fence line running south

The County Engineer was contacted to see if it was possible to excavate in County Road Number 27 with a backhoe. The County Road had recently been overlaid with new blacktop and an excavation was prohibited.

The found 5/8 inch iron pipe at the intersection of the centerline of County Road Number 27 with the fence line running south was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the southeast corner and southwest corner of Section 1. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Northeast corner of section 12 township 108 N , range 11 W , 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A			
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT	MENT, _ REMOVED MONUMENT (EXPLAIN)		
x ON8/2000 PLACED A Wabasha C			
SKETCH OF RE	FERENCE TIES		
	N=126166.24 E=549137.04		
COUNTY ROAD	No. 27		
CENTERLINE	CENTERLINE		
X N N N	TWINOHA CO. SIGN		
计 而 CC			
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.			
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. (2788)	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER	DOCUMENT NUMBER		
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT INDER		

northeast corner of Section 12, Township 108 North, Range 11 West

- During the Original Public Land Survey, the US Deputy Surveyor set a section corner post and made reference to 2 witness trees.
- 1891 F. A. Bratka set a stone monument.
- 1905 E. C. Burns shows a stone and stake in place.
- 1924 E. C. Burns shows a found stone.
- August, 2000 Johnson & Scoffeld, Inc. searched at the intersection of the centerline of County Road Number 27 and a fence line running south with an electronic metal detector and nothing was found.

The County Engineer was contacted to see if it was possible to excavate in County Road Number 27 with a backhoe. The County Road had recently been overlaid with new blacktop and an excavation was prohibited. The intersection of the centerline of County Road Number 27 with the fence line running south was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the east quarter corner and south quarter corner of Section 1 and by measurements made to the east quarter corner of Section 12. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East 14 CORNER OF SECTION 12 TO STATE OF MINNESOTA, COUNTY OF Wabasha.	WNSHIP 108 N RANGE 11 W 5th P.M.	
AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A	· · · · · · · · · · · · · · · · · · ·	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN)		
X ON 8/2000 PLACED A Wabasha County Monument		
SKETCH OF REFERENCE TIES		
LI N H		
の で で		
The state of the s	N=123535.46 WAB. Co. COORD.	
! ************************************	F=549144.11 NAO 1983 ADJ.	
#ENCE LINE X	× FENCE LINE ×	
TAN TA		
×		
.n.		
E CC		
₩. 		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
OUN A Mon 3104.2000 SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

1891 F. A. Bratka indicates a stone monument in place.

August, 2000 Johnson & Scofield, Inc. searched for the stone monument in a 10 foot diameter area around a 4-way fence intersection. The area was probed and hand dug to a depth of 3 feet and nothing was found.

The stone monument indicated, by F. A. Bratka, was most likely destroyed during fence construction. The 4-way fence intersection was accepted as the best perpetuation of the Original Public Land Survey Corner and is substantiated by measurements made to the northeast and southeast corner of Section 12. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
North 14 CORNER OF SECTION 13 , TOWNSHIP 108 N, RANGE 11W , 5th p.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ON FOUND A LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) X ON Aug 2000 PLACED A WABASHA County Monument		
SKETCH OF REFERENCE TIES PLACED "Copper Monument N=120984.24 E:546572.03 WAB. Co. Coord. System NAD 83, 1996 Adj. (HARN) 11/19/2018 H=120984.24- E=546572.03-		
COUNTY ROAD	No. 8	
CENTERLINE T - T WITE		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. LAND SURVEYOR, PROFESSIONAL ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

May, 1989 Norbert Rehder, of Johnson, Scofield & Rehder, Inc., excavated an area 8 feet by 8 feet to a depth of 3 feet centered on the centerline of County Road Number 8 and at a split of the occupation at the northeast and northwest corners of Section 13. Nothing was found.

August, 2000 Johnson & Scofield, Inc. established a location for the corner at the intersection of the centerline of County Road Number 8 with the southerly projection of a fence line running along the north-south quarter line of Section 12 and the north-south quarter line of Section 13. The 2 fence line projections intersected the centerline of County Road Number 8 at the same location. The area was searched with an electronic metal detector and nothing was found. This location falls approximately 30 feet east of the location dug in 1989 by Norbert Rehder..

The above mentioned intersection of the centerline of County Road Number 8, with the projected fence lines, was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by a measurement made to a fence line running along the east line of the West Half of the Southwest Quarter of Section 12. It was also substantiated by a measurement made to the northwest corner of Section 13. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

North Quarter Corner of Section 13, Township 108 North, Range 11 West

Johnson & Scofield, placed a 1 inch copper monument October 30, 2018 using previously recorded coordinates to restore the corner following road resurfacing of County Road No. 8 which destroyed the previously set monument.

Marcus S. Johnson

Wabasha County Surveyor License No. 47460

Date: November 19, 2018

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
Northeast Corner of Section 13	,Township108N,Range11W,_5thP.M.	
STATE OF MINNESOTA, County of Wabasha	·	
At the corner location shown on the sketch:		
On May 11, 1989 found a 5/8 inch by 18 inch rebar at surface and a 1½ inch by 24 inch iron pipe directly below. □ left monument as found, □ lowered monument, ☒ removed monument (explain) for further excavation ☑ On May 11, 1989 placed a Wabasha County Monument DATE		
· SKETCH OF RE	FERENCE TIES	
PLACED "WAB CO MONUMENT" FENCE. LINES		
	monument x x x x x x x x x x x x x x x x x x x	
4 CO. R.D. #8 7 N = 120912.11	£ CO. R.D. # 30 / >-51.83	
N=120912.11 E=549155.14 WAB CO. COORD. SYSTEM II D NAD 83, 1996 Adj. (HARN) NAD 83, 1996 Adj. (HARN) NAD 11/19/2018	Minona Co. R/W monument	
dD		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE REGISTER OF DEEDS County of WABASAA I hereby certify that this document was filed in	
Vavu A. Johnson 7/10/89 SIGNATURE DATE	the Reg. of Deeds office at _3 _P .M. on the 180 day of A.D., 1985	
Registration No. 12つらり 位 Land Surveyor, ロ Professional Engineer	Register of Deeds Anslin Deputy By Ag Daefe ,Deputy	
☑ County Surveyor, ☐ County Engineer	DOCUMENT NO.	

M.H.D. FORM NO. 2105

Statement of Evidence:

NORTHEAST CORNER OF SECTION 13, TOWNSHIP 108N, RANGE 11W

1854

U.S. General Land Office marked the corner with a wood post and witnessed the following bearing trees.

12 inch Black Oak South 9½ degrees West 171 links (112.86 feet) 13 inch Bur Oak North 63 degrees West 175 links (115.5 feet)

10 inch Bur Oak South 50 degrees East 130 links (85.80 feet)

12 inch Bur Oak North 62 degrees East 103 links (67.98 feet)

1924


E.C. Burns, Winona County Surveyor, states on tie sheet that a stone set in 1904 was gone, but U.S. General Land Office bearing tree (Bur Oak North 63 degrees West 175 links) still stands, reset corner placing a 2 inch iron pipe 34 inches long, also references another pipe $2\frac{1}{2}$ inches by 40 inches at South 33 feet.

1934

E.C. Burns, Winona County Surveyor, states on tie sheet that pipe set in 1924 is still inplace along with reference pipe and U.S. General Land Office bearing tree. At this time he places another reference pipe at north 30 feet.

1989

Wabasha County Surveyors Office searches the area for E.C. Burns corner or reference monuments nothing is found that would fit E.C. Burns descriptions of what he set. A 5/8 inch by 18 inch rebar is found at the surface and a $1\frac{1}{2}$ inch by 24 inch iron pipe directly below. These monuments are removed in order to excavate the area with a backhoe. An area 8 feet by 8 feet by 3 feet deep is excavated to natural soils but no further corner evidence is recovered. The found rebar and iron pipe are accepted as the best evidence of the U.S. General Land Office corner and a Wabasha County Monument is set.



Northeast Corner of Section 13, Township 108 North, Range 11 West

October 30, 2018 Johnson & Scofield, Inc., placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road resurfacing of County Road No. 8 which destroyed the previously set monument.

Marcus S. Johnson Wabasha County Surveyor

License No. 47460 Date: November 19, 2018

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
East 1/4 CORNER OF SECTION 13 TOWNSHIP 108 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	MENT, REMOVED MONUMENT (EXPLAIN)	
X ON B/2000 PLACED A Wabasha Cou	·	
SUSTELL OF DE	FEDERACE TICK	
SKETCH OF RE	FERENCE HES	
	·	
	N= 118267.69 WAB. CO. COORD. E= 5491964Z NAD 1983 ADJ.	
FENCE LINE	E- 341 146.42 N. 10 1165 H26.	
xxx	LARGE TREE	
. <u>u</u> 		
=		
	<u>*</u> 	
in the state of th		
រ ប្រ រ		
H	-	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS	
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
	BY, DEPUTY	
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER		
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

August, 2000 Johnson & Scofield, Inc. dug and probed by hand in a 10 foot diameter area around the intersection of the easterly projection of a fence line running west and the northerly projection of a fence line running south. Nothing was found.

The intersection of the projected fence lines was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 13. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

· · · · · · · · · · · · · · · · · · ·	
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTH QUARTER Corner of Section 14 , Township 108 H, Range 11 W, 5TH P.M.	
STATE OF MINNESOTA, County of WABASI	· · · · · · · · · · · · · · · · · · ·
At the corner location shown on the sketch:	•
□ Onfound a	
· · · · · · · · · · · · · · · · · · ·	
	ed monument, removed monument (explain)
4 On 7/12/1994 placed a 1 X 18 1	RON PIPE @ 2"CAST IRON CAP
SKETCH OF RI	EFERENCE TIES .1 -121 021 01
oct. 30, 2018	E = 541268.31
PLACED I" COPPER MONUMent	WAB CO COORD System
-N- STAMPED "WAB CO MONUMENT"	
	NAD 83, 1996 adj. CHARN)
4	Contraction
9 (11/x 19/1 1200 PIPE
283	
& COUNTY	SET 1"X 18" -IRON PIPE ROAD
./	
***	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
CONE)	GONE
L'X B" PEN O	SET IXIE"
×××	
× × × × × × × × × × × × × × × × × × ×	, ø
* R	Ø
W	and grant of the second of the
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE REGISTER OF DEEDS
contained herein was prepared by me or under	County of Wabasha
my direct supervision.	I hereby certify that this document was filed in
DAVA A. JAMESON 2/2/96 SIGNATURE DATE	the Reg. of Deeds office at 10:00 AM. on the 6th day of February A.D., 1996
Registration No. 12788	Register of Deeds R. R.
☐ Land Surveyor, ☐ Professional Engineer	By,Deputy
🗹 County Surveyor, 🛘 County Engineer	DOCUMENT NO.

Statement of Evidence:

north quarter corner of Section 14, Township 108 North, Range 11 West

1855

U.S. Deputy Surveyor, Michael Kerrick, set a wood stake in a mound with trench. No reference ties where available.

1989

Johnson, Scofield and Rehder, Wabasha County Surveyors, searched the area for evidence of the Original Public Land Survey Corner, but nothing was found on the surface. This corner falls at the intersection of Wabasha County Road Number 8 and a Township Road to the south. A 10 foot by 10 foot square area was excavated, which included the centerline intersection to a depth of 1.0 foot below natural soils. No evidence was recovered.

July 12, 1994

Johnson, Scofield and Rehder, Wabasha County Surveyors, analyzed the north line of Section 14, along with the existing fence line along the north-south quarter line of Section 11. It was determined that the centerline of Wabasha County Road Number 8, intersected with the existing fence line along the north-south quarter line of Section 11, and the centerline of the Township Road along the north-south quarter line of Section 14 is the best evidence of the Original Public Land Survey Corner. A 1 inch by 18 inch iron pipe and a 2 inch cast iron top was set.

North Quarter Corner of Section 14, Township 108 North, Range 11 West

October 30, 2018

Johnson & Scofield, Inc., placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road resurfacing of County Road No. 8 which destroyed the previously set monument.

Marcus S. Johnson

Wabasha County Surveyor Licens No. 47460

Date: November 19, 2018

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
Northeast corner of Section 14 , Township 108 N, RANGE 11 W, 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A Wabasha County Monument		
* LEFT MONUMENT AS FOUND LOWERED MONU	MENT, _ REMOVED MONUMENT (EXPLAIN)	
ONPLACED A		
Oct. 30 , 2018 SKETCH OF RE	FERENCE TIES	
PLACED A 1" Copper Morument	Note:	
STAMPED "WAB CO MONUMENT"	TIES ARE PER NORBET REHPER, MAY, 1989	
SPIKE SOUTH FACE POWER POLE Q 50.33	CMP CULVERT END RIVET ON TOP OF CULVERT	
COUNTY ROAD	No. 8	
CENTERLINE		
E:543928.81 WAB CO COORD System NAD83, 1996 Adj. (HARN) MX 11/19/2018		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12788	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER		
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

- 1850s During the Original Public Land Survey, the US Deputy Surveyor set a section post in the mound with pits and trench and planted osage orange seeds at each angle.
- May, 1989 Norbert Rehder, of Johnson, Scofield & Rehder, Inc., excavated with a backhoe at the intersection of the centerline of County Road Number 8 and the township road running north and a township road running south. The excavation was 8 feet by 8 feet to a depth of 3 feet. Nothing was found.
- January, 1990 Norbert Rehder, Johnson, Scofield & Rehder, Inc., set a
 Wabasha County monument at the intersection of the
 centerline of County Road Number 8 with the centerline of the
 Township Road running north and the centerline of the
 Township Road running south. No Certificate of Location of
 Government corner was filed.
- August, 2000 Johnson & Scofield, Inc. found the Wabasha County monument set by Norbert Rehder in January of 1990. The Wabasha County monument, set by Norbert Rehder, was accepted as the best perpetuation of the Original Public Land Survey Corner, and was substantiated by measurements made to the west quarter corner and south quarter corner of Section 12 and by measurements made to the north quarter corner and the east quarter corner of Section 14.

Northeast Corner of Section 14, Township 108 North, Range 11 West

October 30, 2018 Johnson & Scofield, Inc., placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road resurfacing of County Road No. 8 which destroyed the previously set monument.

Marcus S. Johnson Wabasha County Surveyor License No. 47460 Date: November 19, 2018

CERTIFICATE OF LOCATION (OF GOVERNMENT CORNER	
East 14 corner of section 14 township 108 N range 11 W 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ON FOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUM	MENT, _ REMOVED MONUMENT (EXPLAIN)	
x ON B/2000 PLACED A Wabasha Cour	ity Monument	
SKETCH OF REF	FERENCE TIES	
TOWNSHIP ROAD N= 118372.25 WAB. Co. COORD. E= 543961.33 NAD 1983 ADJ.		
	· ·	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE LICENSE NO. (2788)	IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy Surveyor set a quarter post and made reference to 2 witness trees.

August, 2000 Johnson & Scofield, Inc. probed in a 10 foot diameter area to a depth of 1 foot around the intersection of a fence line running west and the southerly projection of the centerline of the Township Road. Nothing was found. The area appears to have been cut during the construction of the Township Road.

The intersection of the fence line running west with the southerly projection of the Township Road centerline was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 14. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
North Quarter Corner of Section 15	,Township <u>108N</u> ,Range <u>11W</u> , <u>5th</u> P.M.	
STATE OF MINNESOTA, County of Wabasha		
At the corner location shown on the sketch:		
On May 10, 1989 found a 1 inch by 18	3 inch iron pipe R.L.S. No. 12788	
☐ left monument as found, ☐ lower	ed monument, 🛛 removed monument (explain)	
for further excavation On May 10, 1989placed a Wabasha Cou		
DATE		
OCT. 31 2018 SKETCH OF R	EFERENCE TIES	
1 PLACED a 1" COPPER MOHUMENT	Base steel corner post set	
Struped "WAB CO MONUMENT"	(in concrete	
	.65	
121093.82 FENCE X LINES		
N=121093.82 N=121093.82		
E=536055.94 × × ×	$\leftarrow x - x \rightarrow x \rightarrow x$	
WAB CO COORD System 62.562: WAD 83, 1996 Adj. (HARN)	& Co. R.D. #8 7	
Mg-11/1/2018		
1/1/2018	\$8.42	
C 250	July Conte	
spike s.E. face telephone guard	spike s.w. face	
telephone quard	A felephone guard Post	
telephone guard	A Post	
,5	0	
(4)	<u></u>	
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS County of Wabasha	
my direct supervision.	I hereby certify that this document was filed in	
David A Lomen 7/10/89 SIGNATURE DATE	the Reg. of Deeds office at $3 P$.M. on the $18th$ day of A.D., 19 89	
Registration No. 12788	Register of Deeds Geraldine Tibor By Register Of Deeds Geraldine Tibor	
☐ Land Surveyor, ☐ Professional Engineer	By Joseph Document No	
M County Surveyor II County Engineer	DOCOMENT NO.	

M.H.D. FORM NO. 2105

Statement of Evidence:

NORTH QUARTER CORNER OF SECTION 15, TOWNSHIP 108N, RANGE 11W

1854

Michael Karrick, U.S. Deputy Surveyor marked the corner with mound, trench, pits and charred stake with osage orange seeds northeast and southwest.

1979

Harry S. Johnson Company Inc., Red Wing, Minnesota, during a land survey in Section 15 placed an iron pipe at the intersection of the centerlines of County Road Number 8 and the Town Road.

1989

Wabasha County Surveyors Office excavated the area with a backhoe an area 8 feet by 8 feet by 4 feet deep down to natural soils, centered on the centerlines of County Road Number 8 and the Town Road. No evidence of the corner was recovered. The found iron pipe was accepted as the best evidence of the original U.S. General Land Office corner, and a Wabasha County Monument was set.

North Quarter Corner of Section 15, Township 108 North, Range 11 West

October 31, 2018

Johnson & Scofield, Inc., placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road resurfacing of County Road No. 8 which destroyed the previously set monument.

Marcus S. Johnson

Wabasha County Surveyor Licens No. 47460

Date: 1 Nov. 2018

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
	,Township 108N , Range 11W , 5th P.M.
STATE OF MINNESOTA, County of Wabasha	, rownship, runge,,,, r.w.
At the corner location shown on the sketch:	
	inch hu 12 inch long guaraind atoms
On May 10, 1989 found a 8 inch by 8	inch by 12 inch long quarried stone
☑ left monument as found, ☐ lower	ed monument, 🗆 removed monument (explain)
On May 10, 1989 ploced o Wabasha Cou	nty Monument
10/31/2018 SKETCH OF R PLACED a 1" Copper Monument of Stamped "WAB CO MONUMENT" ?	EFERENCE TIES
A Acid a 1" CODDER Monument of	£: 538663.71
Stamped "WAB CO MONUMENT" >	WAB CO COORD System
-N-	NAD83, 1996 adj. (HARN)
ام	Ne 1/1/2018
Spike N.E. face W Power Pole St. 53	Ī
Power Pole of	
. (0)	1. alt alt
4 CO. RD. #8 7	1
200.20.	<u>- </u>
	D
C - DA	
Fence Vine Nort	1 mil- Coule
Fence Line Scrot	I to to spike s.W. face
	Helephone guard
spike east tace	Post
end wood fence	Pest
Post	
7	3
	4
	[0
Statement of evidence relative to this corner lo	cation is on back of page.
	OFFICE OF THE DECISION OF DECIS
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS County ofWabasha
my direct supervision.	I hereby certify that this document was filed in
	the Reg. of Deeds office at 3 P .M. on the
Swy A. Jomson 7/10/89 SIGNATURE DATE	18th day of July A.D., 19 89
Registration No. 12798	Register of Deeds Geraldine Tilor
☑ Land Surveyor, ☐ Professional Engineer	By Kay Dock Deputy
☑ County Surveyor. ☐ County Engineer	DOCUMENT NO.

M.H.D. FORM NO. 2105

Statement of Evidence:

NORTHEAST CORNER OF SECTION 15, TOWNSHIP 108N, RANGE 11W

1854

Michael Karrick, U.S. Deputy Surveyor, marked the corner in a mound with trench, pits and charred stake with osage orange seeds northeast and southwest.

1989

Wabasha County Surveyors Office excavated an area 8 feet by 8 feet by 4 feet deep with a backhoe centered on the centerline of County Road Number 8 and the centerline of a Town Road to the north. A 8 inch by 8 inch by 12 inch long quarried stone was recovered at a depth of 4 feet setting in natural clay. The stone was accepted as a perpetuation of the original U.S. General Land Office corner. The stone was left inplace and a Wabasha County Monument was set.



Northeast Corner of Section 15, Township 108 North, Range 11 West

October 31, 2018

Johnson & Scofield, Inc., placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road resurfacing of County Road No. 8 which destroyed the previously set monument.

Marcus S. Johnson

Wabasha County Surveyor Licens No. 47460

Date: 1 Nov. 2018

CERTIFICATE OF LOCATION (OF GOVERNMENT CORNER	
East 1/4 CORNER OF SECTION 15 TOWNSHIP 108 N , RANGE 11 W , 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A 5"X 6" X 15" Stone Monument.		
LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN)		
x ON 8/2000 PLACED A Wabasha County Monument.		
SKETCH OF REFERENCE TIES		
FIELD DRIVE N= 118425-19 WAB. Co. COORD. NAD. 1983 90J. FENCE LINE N= 118425-19 NAD. 1983 90J.		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORN	NER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SOPERVISION. SIGNATURE LICENSE NO. 12788 LAND SURVEYOR, PROFESSIONAL ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

•

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

August, 2000 Johnson & Scofield, Inc. excavated with a backhoe at the intersection of the easterly projection of a fence line running west and the northerly projection of a fence line running south. The excavation was 12 feet by 12 feet to a depth of 5 feet. At a depth of 2 1/2 feet, a 5 inch by 6 inch by 15 inch stone monument was found. The stone monument was just below

The stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 15. A 1 inch by 18 inch iron pipe was placed on the north side of the stone. An additional 1 inch by 18 inch iron pipe was placed above the stone, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

the old original gravel field drive entrance in natural soil.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER NO 1/4 Corner of Section 16 Township 108N Range 11W 5th P.M. STATE OF MINNESOTA. County of WABASHA At the corner location shown on the sketch: \[\times On \frac{6-25-98}{1000000000000000000000000000000000000		
X_left_monument as foundlowered monumentremoved monument On placed a		
N=121148.6 SKETCH OF RE E=530805.93 WAB CO COORD System N-HARN (HARN) E OF COUNTY ROAD No.8 56.60 S-SW TO 30D SPIKE IN WEST FACE OF A 24" WALNUT	FERENCE TIES C 9 10/31/18 PLACED A. "Copper Monument Stamped "WAB CO MONUMENT" 38/10 N TO 30D SPIKE IN WEST FACE OF WOODEN POST LEANING SLIGHTLY NORTH CONE 46.25 S TO 40D SPIKE IN WEST FACE OF PP CONE CONTE	
SEC 16		
Statement of evidence relative to this	corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Vincent A. Fangman Licensed Land Surveyor Minnesota Registration No. 14888 6/25/1998 Date. LIND SURVEYING PINE LIND SURVEYING LI	OFFICE OF THE COUNTY RECORDER County of	
Reviewed by Wabasha County Surveyor	Date	

North Quarter Corner Section 16 T108N R11W

June 1854, Michael G. Karrick, Deputy Surveyor, set a quarter section post as per instructions in the original public land survey.

June 25, 1998, Vince Fangman, private land surveyor, found a 1" shaft in the center of County Road No. 8. The distance from the iron shaft to the north-south 16th line fence in the Southeast Quarter of Section 9 is 1312.5 feet. The distance from this fence line to the southeast corner of Section 9 measures 1315.65. would put the computed south 16th corner of the Southeast Quarter of Section 9 to be 1.65 feet east of the fence line running to the The owner of the Northeast Quarter of Section 16 also owns the east one rod of the Northwest Quarter of Section 16. There is a fence line running to the south 17 feet west of the found The origin of the 1" shaft is unknown. monument. There was a 10x10 foot excavation done, centered on County Road No. 8 by Wabasha County previously, Nothing was found. The center of the trench is 11 feet west of the found 1" iron shaft. There is a dimension of 2614.4 feet along the south line of the Southwest Quarter of Section 9 shown on the plat of Kreofsky Addition. would fit the location of the fence line which runs to the north near this north quarter corner. However, because of previous "Onion Farms" layed out in the Southwest Quarter of Section 9 in the early 1900's, which showed many one rod accesses through out the Southwest Quarter of Section 9, the fences in the Southwest Quarter can't be trusted to be on the public land survey lines. The 1" iron shaft was accepted as being the public land survey corner.

STATEMENT OF EVIDENCE

North Quarter Corner of Section 16, Township 108 North, Range 11 West

October 31, 2018

Johnson & Scofield, Inc., placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road resurfacing of County Road No. 8 which destroyed the previously set monument.

Marcus S. Johnson

Wabasha County Surveyor Licens No. 47460

Licens No. 47460 Date: 1 Nov. 2018

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Northeast Corner of Section16	,Township108N,Range11W,5thP.M.		
STATE OF MINNESOTA, County of Wabasha	Mada Jamah Palinawa - A Adama		
At the corner location shown on the sketch:			
	ed monument, 🗆 removed monument (explain)		
On May 10, 1989 placed a Wabasha Cou	nty Monument		
N=121124.96 SKETCH OF REFERENCE TIES 10/31/18 Placed A 1" Copper Monwhent Placed A 1" Copper Monwhent The Mad 1996 Adj. (HARN) Base steel corner post Set in concrete 1996 Spike S.E. face 19984 = 19984 = 19984			
Fence line	== \$5.00 spike east face end word corner post Gone		
Statement of evidence relative to this corner location is on back of page.			
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. March March 1/0/89	OFFICE OF THE REGISTER OF DEEDS County of		
M.H.D. FORM NO. 2105			


NORTHEAST CORNER OF SECTION 16, TOWNSHIP 108N, RANGE 11W

1854

Michael Karrick, U.S. Deputy Surveyor, marked the corner with a trench, pits, charred stake and osage orange seeds.

1989

Wabasha County Surveyors Office excavated an area 8 feet by 8 feet by 7 feet deep with a backhoe centered on the center-line of County Road Number 8 and a fence line to the north. A 6 inch by 8 inch by 12 inch long white quarried stone setting in natural clay at a depth of 7 feet was recovered. This stone was accepted as a perpetuation of the original U.S. General Land Office corner and a Wabasha County Monument was set.



STATEMENT OF EVIDENCE

Northeast Corner of Section 16, Township 108 North, Range 11 West

October 31, 2018

Johnson & Scofield, Inc., placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road resurfacing of County Road No. 8 which destroyed the previously set monument.

Marcus S. Johnson

Wabasha County Surveyor Licens No. 47460

Date: 1 Nov. 2018

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East 1/4				
SKETCH OF REI	N= 118489.90 WAB. CO. COORD. E= 533451.27 NAD 1983 ADJ.			
STATEMENT OF EVIDENCE RELATIVE TO THIS CORT	NER LOCATION IS ON THE BACK OF THIS SHEET.			
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. LAND SURVEYOR, PROFESSIONAL ENGINEER COUNTY SURVEYOR, COUNTY ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF			

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

August, 2000 Johnson & Scofield, Inc. probed in 10 foot diameter area around a point mid-way between the northeast and southeast corners of Section 16 and on a north-south fence line. The mid-way point was used because there is no existing east-west occupation. Nothing was found.

The north-south fence line, at a point mid-way between the northeast and southeast corners of Section 16, was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by a measurement made to a fence line running along the south line of the Northwest Quarter of the Northwest Quarter of Section 15 and a measurement made to a fence line running along the south line of the Northeast Quarter of the Southeast Quarter of Section 16. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

	J OF GOVERNMENT CORNER ,Township,Range,5TH	
STATE OF MINNESOTA, County of WABASHA	·	
At the corner location shown on the sketch:	•	
☑ On 5/10/88 found a Chiseled "X	" on a 6" iron disc., recorded reference	
ties. △ left monument as found, □ lower	red monument, 🗆 removed monument (explain)	
□ Onplaced a		
DATE		
SKETCH OF R	REFERENCE TIES	
1 4		
-N-	SECTION 8	
	Water Systems	
15 T	Cor. Brick / Brick 2'Up	
Bit.)	B C	
	63.80 - 65.45	
O		
	50.65	
	N.W. Cor. Brick	
	Flag Base	
	City Hall	
SECTION 17		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER		
contained herein was prepared by me or under my direct supervision.	County of Waland	
100 RB Q 2 1/2/88	I hereby certify that this document was filed in the Reg. of Deeds office at // .M. on the	
SIGNATURE DATE Registration No. 10/62	Register of Deeds Line	
☐ Land Surveyor, ☐ Professional Engineer	By,Deputy	
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO	

M.H.D. FORM NO. 2105

NORTH QUARTER CORNER, SECTION 17, TOWNSHIP 108 NORTH, RANGE 11 WEST, 5TH P.M., WABASHA COUNTY, MINNESOTA.

June 1854 Michael G. Karrick, Deputy Surveyor, set a post with trench, pits, charred stake and Osage orange seeds at the Corner during the Public Land Survey.

December 1856 Original Plat of Centerville, shows a post at the corner.

The post is graphically depicted as being on the center line of Broadway Street.

November 1961 Leonard G. Nelson & Associates, Consulting Engineer, Plainview City Engineer, shows an Iron Monument at the corner. The Engineer was drafting a property corner map for the City of Plainview.

March 1979 Yaggy Associates, Inc. found a chiseled "X" on a 6" iron plate at the corner.

May 1988 Yaggy Colby Associates found the chiseled "X" and 6" iron plate, and recorded reference ties.

An analysis of the record and survey data indicates that the Chiseled "X" on the iron plate is accepted as marking the North Quarter Corner of Section 17.

For further information regarding this survey, contact Yaggy Colby Associates, Rochester, Minnesota.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Northast corner of section 17 , township 108 N , range 11 W , 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON \$\frac{1}{2000}\$ FOUND A \(\frac{5}{6}\)" Iron Pipa R.L.S. # 14888			
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUM	HENT, X REMOVED MONUMENT (EXPLAIN)		
X ON B/2000 PLACED A Wabasha Cou	inty Monument		
SKETCH OF REF	FERENCE TIES		
STH STREET			
E. BROAD WAY	SAN. MANHOLE		
WAB. CO. COORD. N=121167.97 NAD 1983 ADJ. E=528179.78			
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.			
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		
David A. Moon 11/3/2000 DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20		
LICENSE NO. 12788	REGISTER OF DEEDS		
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY		
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER		

1850s During the Original Public Land Survey, The US Deputy Surveyor set a post in mound with trench, pits and charred stake and planted osage orange seeds at each angle.

December, 1971 Nick Kenitz, Wabasha County Surveyor, indicates an iron pin in place at the corner.

1979 Yaggy and Associates, found 1/2 inch rebar at the corner.

1988 Yaggy Colby and Associates set a PK nail at the corner.

August, 2000 Johnson & Scofield, Inc. found a 5/8 inch iron pipe with a cap marked RLS 14888. The found 5/8 inch iron pipe agrees with the location of the previously set monuments. No excavation was made for the corner because it falls in a residential street with sanitary sewer and water in place. The installation of the sewer and water would have destroyed any additional corner evidence.

The found 5/8 inch iron pipe marked RLS 14888 was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the east quarter corner and south quarter corner of Section 8 and the north quarter corner and west quarter corner of Section 16. A 1 inch by 18 inch iron pipe was placed with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East 1/4 COr. Corner of Section 17, Township 108, Range 11, 542 P.M.			
STATE OF MINNESOTA, County of Wabasha			
At the corner location shown on the sketch:			
On April, 2000 found 1/2" re6a	r, westedge Confepost		
☐ left monument as found, ☐ lower	red monument, Kremoved monument (explain)		
12 On April 13, 2000 placed 5/8 1 i on pare replaced Meas'd	pipe with plastic cap into with GPS from west		
SKETCH OF REFE	RENCE TIES		
Temporary record only,			
-N- Center of wood Post - North			
Smalls drainage drainage drainage x -7,40°			
Temains of fences			
Statement of evidence relative to this corner location is on b	pack of page.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE COUNTY RECORDER.		
Signature Brand May 10, 2000	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE COUNTY RECORDER'S OFFICE AT M. ON THE DAY OF A.D., 19		
With Hogistored Edita editoyor Ele. No.	COUNTY RECORDER		
☐ LAND SURVEYOR ☐ COUNTY SURVEYOR			
ROGER W. BRAND & ASSOCIATES	BY, DEPUTY		
Surveying and Mapping	DOCUMENT NO.		
ST. CHARLES, MN 55972 507 / 932-3895 OFFICE			

CERTIFICATE OF LOCATION North Quarter Corner of Section 18 , STATE OF MINNESOTA, County of WA	Township <u>108</u> , Range <u>11</u> , <u>5</u> P.M.		
At the corner location shown on the sketch: IX On APRIL 2010 found a 5/8" REROD WITH 3" ALUMINUM WABASHA COUNTY CAP.			
	nonument, removed monument (explain) IKE AND DISC RECESSED 1/2"		
SKETCH OF RE	FERENÇE TIES		
Punch hole in top steel pipe N28°46'27"W 54.21'	Nail & Disk west face power pole		
N24°52'38"E 65.17'			
	on vi		
S11°50'39"W -====================================	TH 247		
WABASHA CO. COORDINATES Spike in 40" Mople tree X= 520254.206 Y= 121180.842 NAD 83 (1996 ADJ.)			
Statement of evidence relative to this corner location	n is on back of page.		
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.	OFFICE OF THE COUNTY RECORDER County of WABASHA I hereby certify that this document was filed in the Co. Recorder's office atM. on the day of A.D., 20 County Recorder		
Type or Print Name License No.	By, Deputy DOCUMENT NO		

1853

During the original Public Land Survey a post was placed.

1952

Minnesota Department of Transportation right of way map and field notes for Highway Number 247 indicate that the corner was assumed to be the intersection of the old road centerline with a fence line running north. The right of way map shows the corner 12.9 feet south of the present road centerline and about 9.4 feet east of the fence running south.

May 1986

Norbert Rehder, with Johnson & Scofield Inc., recovered a 3/8 inch rebar 12.9 feet south of the road centerline. Analysis of the resurvey distances made to the northeast and northwest corners of Section 18 with Highway stationing indicate that the found rebar perpetuates the assumed position by Minnesota Department of Transportation in 1952. Further analysis with occupation lines along the full length of the north-south quarter line of Section 18 indicate that the found rebar agrees with the obliterated position for the corner and was therefore accepted as the best perpetuation of the original Public Land Survey corner. The rebar was removed and a Wabasha County Monument was installed.

April 2010

Mn/DOT survey crew locates the Wabasha county monument. A VRS position of monument is recorded, previous to upcoming bituminous overlay.

Sept. 2016

Mn/DOT survey crew sets mag spike and washer on top of in-place monument.

Mn/DOT accepts this position as the perpetuation of the original position of the original Public Land Survey.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
North Quarter Corner of Section 18	,Township <u>108</u> ,Range <u>11</u> , <u>5th</u> P.M.		
STATE OF MINNESOTA, County of Wabasha			
At the corner location shown on the sketch:			
	an		
○			
☐ left monument as found, ☐ lowere	ed monument, \square removed monument (explain)		
On May 1986 placed a Wabasha Cou	nty Monument		
SKETCH OF RE	EFERENCE TIES		
<u> </u>			
CENTERLINE	O SPIKE IN POWER POLE		
NO SCALE	CENTERLINE		
STATE 12.9	HIGHWAY		
NUMBER 247			
SPIKE IN CORNER FENCE POST SPIKE IN 30" MAPLE TREE			
Statement of evidence relative to this corner location is on back of page.			
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. August 1986	OFFICE OF THE REGISTER OF DEEDS County of		
Registration No			
County Surveyor. Cl County Engineer	DOCUMENT NO		

M.H.D. FORM NO. 2105

NORTH QUARTER CORNER OF SECTION 18, TOWNSHIP 108, RANGE 11

1853

During the original Public Land Survey a post was placed.

1952 more or less

Minnesota Department of Transportation right of way map and field notes for Highway Number 247 indicate that the corner was assumed to be the intersection of the old road centerline with a fence line running north. The right of way map shows the corner 12.9 feet south of the present road centerline and about 9.4 feet east of the fence running south.

May 1986

Norbert Rehder, with Johnson & Scofield Inc., recovered a 3/8 inch rebar 12.9 feet south of the road centerline. Analysis of the resurvey distances made to the northeast and northwest corners of Section 18 with Highway stationing indicate that the found rebar perpetuates the assumed position by Minnesota Department of Transportation in 1952. Further analysis with occupation lines along the full length of the north-south quarter line of Section 18 indicate that the found rebar agrees with the obliterated position for the corner and was therefore accepted as the best perpetuation of the original Public Land Survey corner. The rebar was removed and a Wabasha County Monument was installed.

Index	Nο		

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER			
Northeast Corner of Section 18 ,	Township <u>108</u> , Range <u>11</u> , <u>5</u> P.M.			
STATE OF MINNESOTA, County ofWA				
At the corner location shown on the sketch: Solution Shown on the sketch: DATE DATE)D			
 Is left monument as found, ☐ lowered On SEPT. 4, 2016 placed a MAG SF 	monument, removed monument (explain) PIKE AND DISC RECESSED 1/2"			
SKETCH OF RE	EFERENCE TIES			
<i>X</i>	ty 4+01 Church			
N15°17'53"E 78.52'	Star nut in west face power pole up 1.5'			
	TH 247			
TH 247 \$29°28'57"\ S47°49'11"E				
Top nut of Fire Hydrant ⊕	Spike in power pole			
WABASHA CO. COORDINATES				
X= 522884.816 / Y= 121152.767 NAD 83 (1996 ADJ.)				
Statement of evidence relative to this corner location	n is on back of page.			
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.	OFFICE OF THE COUNTY RECORDER County ofWABASHA I hereby certify that this document was filed in the Co. Recorder's office atM. on the			
My W. Book 2-15-2017	day of A.D., 20			
Signature Date	County Recorder			
Type or Print Name 4792 License No.	By, Deputy DOCUMENT NO			

1853	During the original Public Land Survey a post was placed.
1853-1986	Several plats were recorded in Plainview which refer to the corner.
1952, more or less	Minnesota Department of Transportation right of way map and field notes for Highway Number 247 indicate that the corner was assumed to be the intersection of the centerlines of roads running East, West and North.
1978	Donald Borcherding, Land Surveyor, with Yaggy Associates, Inc., shows recovering a 3/4 inch pipe at the corner in several surveys.
1982	David A. Johnson, Land Surveyor, with Johnson & Scofield Inc., recovers a 3/4 inch pipe at the corner and uses same to base a survey for the Cable T.V. tower.
May, 1986	Norbert Rehder, with Johnson & Scofield Inc., recovers a ¾ inch pipe. Analysis of the resurvey distances indicate that the found pipe is in perpetuation of the Minnesota Department of Transportation location and is the same pipe used by Borcherding in 1978 and Johnson in 1982. It was felt that the found pipe best perpetuates the original Public Land Survey corner. The pipe was left in place and a 5/8 inch re-rod was driven down the center of the pipe and a 3 inch diameter aluminum Wabasha County Monument was affixed to the re-rod.
April 2010	Mn/DOT survey crew locates the 5/8 inch re-rod with no cap. A VRS position of monument is recorded, previous to upcoming bituminous overlay.
Sept. 2016	Mn/DOT survey crew sets mag spike and washer on top of in-place monument.
I	Mn/DOT accepts this position as the perpetuation of the original position of the original Public Land Survey.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER				
Northeast Quarter Corner of Section 18 , Township 108 , Runge 11 , 5th P.M.				
STATE OF MINNESOTA, County of Wabasha				
At the corner location shown on the sketch:				
On May 1986 found o 1 inch iron	pipe			
	ed monument, removed monument (explain)			
☑ On <u>May 1986</u> placed a <u>Wabasha Coun</u>	CA LIMITATION			
SKETCH OF R	EFERENCE TIES			
	<u> </u>			
	CENTERLINE			
NOMB	CEN			
	Q SPIKE IN POWER			
NO SCALE S.	POLE			
S	00			
STATE HIGHWAY	48.01 CENTERLINE			
NUMBER 247				
30.91	33.80			
*	OBJUE IN COMED BOLE			
TOP NUT OF FIRE HYDRANT	SPIKE IN POWER POLE			
	• •			
Statement of evidence relative to this corner location is on back of page.				
I hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS				
contained herein was prepared by me or under my direct supervision.	County of Analos			
	I hereby certify that this document was filed in the Reg. of Deeds office at 4.3 M. on the			
Begistration No. (2788)	A.D., 1926			
Registration No Professional Engineer	Register of Deeds			
© County Surveyor. □ County Engineer	DOCUMENT NO.			

M.H.D. FORM NO. 2105

NORTHEAST CORNER OF SECTION 18, TOWNSHIP 108 N, RANGE 11 W

During the original Public Land Survey a post was placed.

1853-1986 Several plats were recorded in Plainview which refer to the

corner.

1952, more or less Minnesota Department of Transportation right of way map and

field notes for Highway Number 247 indicate that the corner was assumed to be the intersection of the centerlines of

roads running East, West and North.

1978 Donald Borcherding, Land Surveyor, with Yaggy Associates, Inc.,

shows recovering a 3/4 inch pipe at the corner in several

surveys.

1982 David A. Johnson, Land Surveyor, with Johnson & Scofield Inc.,

recovers a 3/4 inch pipe at the corner and uses same to base

a survey for the Cable T.V. tower.

May 1986 Norbert Rehder, with Johnson & Scofield Inc., recovers a 3/4

inch pipe. Analysis of the resurvey distances indicate that the found pipe is in perpetuation of the Minnesota Department

of Transportation location and is the same pipe used by Borcherding in 1978 and Johnson in 1982. It was felt that the found pipe best perpetuates the original Public Land Survey corner. The pipe was left in place and a 5/8 inch

rerod was driven down the center of the pipe and a 3 inch diameter aluminum Wabasha County Monument was affixed to

the rerod.

De Distriction	CERTIFICATE OF LOCATION OF GOVERNMENT CORNER				
	East Quarter Corner of Section 18 , Township 108 , Range 11 , 5th P.M.				
	STATE OF MINNESOTA, County of <u>Wabasha</u>				
	At the corner location shown on the sketch:				
PRESENTATION OF STREET,	☑ On May 1986 found a 1 inch squar	e bolt			
- Annicas and an anni	☐ left monument as found, ☐ lower	ed monument, 🖫 removed monument (explain)			
	☑ On May 1986 ploced a Wabasha Cou	nty Monument			
·	4 HWY. No.42 SKETCH OF B	PK NAIL			
	-N- I	O REBAR AT FENCE CORNER			
	CENTERLINE 75.36	86.88 = 10162			
S)		curner			
- ***	PK NAIL IN POWER POLE	1/2" REBAR			
115195 Nouthic was for	Mark Fevertson @ 24.80 QV ABetts reports cim on 2.59 & 0.41 west on 2.59 & 0.41 west of a location. Our records as location. Our records	33.65			
11000 mm. 124 c 12-19	ong 2.59 à 0.41 west is location. Our records yagger was to set Evendently it was not E	O SPIKE IN POWER POLE			
	Statement of evidence relative to this corner lo	cation is on back of page.			
	I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Own H.	OFFICE OF THE REGISTER OF DEEDS County of I hereby certify that this document was filed in the Reg. of Deeds office at #1:3 @.M. on the /7% day of			
	□ Land Surveyor, □ Professional Engineer	By,Deputy			
	👺 County Surveyor, 🗆 County Engineer				

M.H.D. FORM NO. 2105

1978

1980

EAST QUARTER CORNER OF SECTION 18, TOWNSHIP 108, RANGE 11

During the original Public Land Survey a post was placed.

Donald Borcherding, Land Survey, with Yaggy Associates Inc., shows recovering a 1 inch steel bar at the corner in several

surveys.

Donald Borcherding, Land Surveyor, with Yaggy Associates Inc., excavated in the roadbed with a backhoe and recovered 4 iron monuments, all of varying materials, sizes and locations. No stone monuments were recovered. He accepted the recovered 1 inch square bolt as the Public Land Survey corner and

replaced it in its original position.

May 1986

Norbert Rehder, with Johnson & Scofield Inc., recovered the bolt found by Borcherding. Analysis of the resurvey distances indicates that the bolt is very near the lost position for the corner. It was felt that the found bolt best perpetuates the original Public Land Survey corner. The bolt was removed

and a Wabasha County Monument was installed.

Index	NI-		
ILICIDA	IMIL		

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
North quarter Corner of Section 19	,Township <u>108</u> , Range <u>11</u> , <u>5th</u> P.M.
STATE OF MINNESOTA, County ofWabasha	
At the corner location shown on the sketch:	
□ On found a	
·	ed monument, 🗆 removed monument (explain)
On 4/26/88 placed a Wabasha Cou	nty Monument
SKETCH OF RE	EFERENCE TIES
4	
PK NAILS IN 69 END OF 90	NAIL IN WEST FACE OF POWER POLE
NO SCALE	
36.44	CENTERLINE
TOWNSHIP	ROAD
,	
	l
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE REGISTER OF DEEDS County of
Signature CT & BATE	Register of Deeds A.D. 19 PA
Registration No. (2786) Land Surveyor, Professional Engineer	ByDeputy
County Surveyor. County Engineer	DOCUMENT NO

NORTH QUARTER CORNER OF SECTION 19, TOWNSHIP 108, RANGE 11

1853

April 26, 1988

During the original Public Land Survey a post was placed.

Richard Petersen, with Johnson & Scofield Inc., searched the area with an electronic locater but no monuments were found. The fence line along the north-south quarter line south of the center of Section 19 was projected north. The old fence and berm evidence along the north-south quarter line north of the center of Section 18 was projected South. The fence projection from Section 19 fell about 20 feet east of the fence projection from Section 18. A 10 foot wide by 30 foot long area was excavated with a backhoe to natural ground but no evidence of the corner was discovered. The fence and berm projection from Section 18 coincided with a fence 61 rods west of the corner and also agreed with berm remnants just north of the corner. The corner was remonumented using obliterated methods. A Wabasha County Monument was set on the centerline of the east-west Township Road at the deed distance of 61 rods east of the north-south fence in the Southwest Quarter of Section 18. It was felt that this position best perpetuates the original Public Land Survey

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
NECORNER OF SECTION_19_, TOWNSHIP_108, RANGE_11, 5_P.M. STATE OF MINNESOTA, COUNTY OF_Wabasha		
AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
LEFT MONUMENT AS FOUND,LOWERED MONU	UMENT REMOVED MONUMENT (EXPLAIN)	
V ON 2000 PLACED A 2" dia. cast iron pipe	Tron cap or 1 ~ 10	
SKETCH OF REFERENCE	TIFS	
gravel		
Spike So. Face power		
tace Power Pole	Spike So. face 20" Pina	
74.02	45.89 gravel road	
Spike 520 east face power pole		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SOPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

northeast corner of Section 19, Township 108, Range 11

Michael G. Karrick, US Deputy Surveyor, set a post in a mound during the Original Public Land Survey. No trees were witnessed.

June, 1910 John Rafter, County Surveyor, performed a survey in the North Half of the Southwest Quarter of Section 17. In his descriptive field notes he mentions finding 2 monuments at the southwest corner of Section 17. One stone monument and an iron stake. He says that "these two last name markers are 13 feet apart north and south, but are both in the north and south line. These markers are in dispute as to which is the true corner."

1969 McGhie and Betts placed a monument at the Section corner by measuring between the west quarter corner of Section 17 and the west quarter corner of Section 20.

Johnson and Scofield, Inc. recovered the McGhie and Betts monument placed in 1969 and used it's position to verify the obliterated position for the north quarter corner of Section 20, Township 108, Range 11.

June, 2000

Johnson and Scofield, Inc. searched the intersection with an electronic locator, but no metal monuments were found. The intersection was excavated with a backhoe to a depth that went into the subsoil. No additional monument evidence was recovered. The corner was remonumented using obliterated methods by assuming that the fence line that exists along the northerly and easterly boundaries of the south 62.5 rods of the west 52.2 rods of the southwest quarter of Section 17 were placed when the location of the southwest corner of Section 17 was known. Measurements were made from the fences along the northerly and easterly lines of the above referenced property and a 2 inch cast iron cap on a 1 inch by 18 inch iron pipe monument was placed to agree with these fences. It was felt that this position bests perpetuates the original position of the Public Land Survey Corner. This position falls approximately 10 feet north and 7 feet west of the 1969 McGhie and Betts position.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East 1/4 CORNER OF SECTION 19 TOWNSHIP 108 N , RANGE 11 W 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUM		
X ON 11/2000 PLACED A Wabasha Cou	inty Monument.	
SKETCH OF REFERENCE TIES		
	N=113298.24 WAB. Co. COORD. E=522964.13 NAD 1983 AD).	
Y FENCE X LINE Y	495.00 FENCE LINE X FOUND IRON ROD	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY DEPUTY	
_ COUNTY SURVEYOR COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

November, 2000

Johnson & Scofield, Inc. found an iron rod at the northeast corner of the west 30 acres of the Southwest Quarter of Section 20. A position for the east quarter corner of Section 19 was established by measuring 495 feet west from the found iron rod along a line from the east quarter corner of Section 20 projected westerly through the found iron rod. This position falls on an east-west fence line with no occupation north or south.

A 10 foot diameter area, around the above mentioned position, was probed and hand dug to a depth of 1 foot and nothing was found. This position was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 19. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTH QUARTER Corner of Section 20	
STATE OF MINNESOTA, County of WABASH.	
At the corner location shown on the sketch:	
□ On found a	
	ed monument, removed monument (explain)
On 14 Nov. 1987 placed a WABASH!	•
DATE DATE	COURT I MONOCHIE IN I
SKETCH OF RE	FERENCE TIES
4	
4	
# # T	
Spike in power of Pole	A spike in power pole
	o` h`
, 2° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° °	5 *0
centerline	TOWN ROAD
	``.

a)	'b I"x18" iron pipe
ا ا	יאוט שטוו דידי
9	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS County of WABASHA
my direct supervision.	I hereby certify that this document was filed in
Bard A. Smem 11/17/89	the Reg. of Deeds office at 11:30 A.M. on the 21st day of November A.D., 19 89
Registration No. 12788	Register of Deeds Geraldine Tibor
Land Surveyor, - Professional Engineer By Tay Oracle, Deputy	
🗗 County Surveyor, 🗆 County Engineer	DOCUMENT NO.

NORTH QUARTER CORNER OF SECTION 20, TOWNSHIP 108, RANGE 11

June 1854

Michael G. Karrick, U.S. Deputy Surveyor, set a charred wood post in an earth mound with a pit. No other reference ties were taken.

June 1986

James E. Swanson, Land Surveyor, found and used a 60d spike in the centerline of County Road Number 4 as the north quarter corner of Section 20.

October 1989

Alan K. Scofield, Land Surveyor, while performing a land survey in Section 17 recovered the 60d spike used by James E. Swanson in 1986, and used this to analyze the north line of Section 20.

Nov. 14, 1989

Wabasha County Surveyors excavated an area 6 feet by 10 feet by 3 feet deep with a backhoe centered on the centerline intersection of County Road Number 4 and the Townroad. The 60d spike found in 1986 is within this area. No evidence of previous monumentation was recovered. It appears that the area falls in an area that was subcut during road construction. The corner was remonumented by a derivative method on line between found monuments at the northeast and northwest corners of Section 20, this straight line fits the centerline of the east-west Township Road at the north quarter corner, and on the centerline of County Road Number 4. This position was accepted as the best evidence of the original Pulbic Land Survey corner and a Wabasha County Monument was set.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
Northeast corner of Section 20 Township 108 N RANGE 11 W 5th P.M.		
STATE OF MINNESOTA, COUNTY OF Wabasha.	MISHIF 1991, MANUSE 11, 1991, F.M.	
AT THE CORNER LOCATION SHOWN ON THE SKETCH:		
X ON 8/2000 FOUND AN ALUMINUM Wab	asha County Monument	
KLEFT MONUMENT AS FOUND LOWERED MONUMENT	MENT, _ REMOVED MONUMENT (EXPLAIN)	
	· 	
ONPLACED A		
SKETCH OF RE	FERENCE TIES	
1	TENEROL MES	
	•	
	N=115913.57 WAB. Co. COORD. E=528217.08 NAD 1983 RDJ.	
SPIKE IN SOUTH SIDE POWER POLE		
TOWNSHIP 16.65	SPIKE IN SOUTH SIDE POWER POLE	
TOWNSHIP		
	CENTERLINE	
31.58)	
SPIKE IN 36" COTTONWOOD		
型 2 1		
<u>,</u>	_	
NOTE: TIES ARE PER MCGHIE & BETTS INC. 1985	· ·	
•		
H R N C G		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
✓LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1850s During the Original Public Land Survey, the US Deputy Surveyor set a post in mound, with trench, pits and charred stake and planted osage orange seeds at each angle.

McGhie & Betts, Inc., Rochester, Minnesota, established the corner at the intersection of the fence line to the south projected north with the center line of the east-west township road.

Parole evidence by Forest Lamprecht (Plainview Township Clerk and adjacent land owner to corner) stated that in 1950 a tile line was installed at this location to drain the field to the north. He said at that time a stone and pipe were located where M&B set the corner. M&B excavated and found nothing but a large leaning timber.

September, 1985 McGee & Betts, Inc., placed a Wabasha County aluminum monument at the intersection of the fence line to the south, projected north, with the centerline of the east-west Township Road.

August, 2000 Johnson & Scofield, Inc. found the Wabasha County aluminum monument placed in 1985.

The Wabasha County aluminum monument, placed in 1985, was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the north quarter corner and west quarter corner of Section 21 and by measurements made to the east quarter corner and south quarter corner of Section 17.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East 14 CORNER OF SECTION 20 TOWNSHIP 100 N , RANGE 11 W 5th P.M.		
STATE OF MINNESOTA, COUNTY OF Wabasha.		
AT THE CORNER LOCATION SHOWN ON THE SKETCH:ONFOUND A		
_ LEFT MONUMENT AS FOUND, LOWERED MONUMENT		
X ONIO/2000 PLACED A Wabasha Cou	inty Monument	
SKETCH OF REI	FERENCE TIES	
LINE LINE		
٦ <u>/</u> *	·	
Ä		
) FENCE	N= 113281.88 WAB. Co. COOPP.	
	N= 113281.88 WAB. CO. COORP. E= 528219.25 NAD 1983 ADJ.	
Y'		
Y FENCE X LINE X	X-X-X-FENCE X LINE	
*IEL X	FIELD	
	¢'C	
ר א ת		
1 1		
E N C E		
THE STATE OF THE S		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS	
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	COUNTY OF	
VaidA. Imom 9Nov. 2000	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON	
SIGNATURE DATE	THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY, DEPUTY	
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

October, 2000 Johnson & Scoffeld, Inc. probed a 10 foot diameter area centered on a 4-way fence intersection. Nothing was found.

The 4-way fence intersection was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 20. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
North 1/4 corner of section 21 , township 108 N, range 11 W, 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND AN ALUMINUM Wabasha County Monument.		
* LEFT MONUMENT AS FOUND, _ LOWERED MONUM	MENT, REMOVED MONUMENT (EXPLAIN)	
ONPLACED A		
SKETCH OF REI	FERENCE TIES	
	ш	
J	الله الله الله الله الله الله الله الله	
	[.0-	
WAB. CO. COORD. N= 115885-08	3	
NAD 1983 APJ. E= 530868.66		
	SPIKE ON TOP OF FENCE POST	
TOWNSHIP 9	= 37.25 ROAD	
		
1	CENTERLINE	
332CX	SPIKE ON SIDE POWER POLE FENCE POST	
	\ *	
NOTE: TIES ARE PER LARRY		
SHANNON, 1985.	l	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORI	NER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12784	REGISTER OF DEEDS	
_	BY, DEPUTY	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER		
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charted stake planted osage orange seeds northeast and
southwest.

June, 1985 Larry Sherman, Registered Survey Number 16096, found a stone monument during a survey a Section 21. The stone monument was 1.0 feet west and 2.5 feet south of the intersection of the centerline of an east-west Township Road and a fence line running north. A 5/8 inch iron pipe was placed on the east side of the stone monument. An aluminum Wabasha County monument was placed above the stone monument.

August, 2000 Johnson & Scofield, Inc. found the aluminum Wabasha County monument placed in 1985.

The stone monument, found in 1985, and marked by the aluminum Wabasha County monument, was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and northwest corners of Section 21.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Northast corner of Section 21 , TOWNSHIP 108 N , RANGE 11 W , 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ___ ON_____FOUND A ____ _ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) x ON 8/2000 PLACED A Wabasha County Monument SKETCH OF REFERENCE TIES N=115854.85 WAB. CO. COORP. E=533468.56 NAD 1983 ADJ. ROAD TOWNSHIP CENTERLINE STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET. I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR OFFICE OF THE REGISTER OF DEEDS COUNTY OF ___ UNDER MY DIRECT/SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT ______ .M. ON THE _____DAY OF ______A.D., 20___ SIGNATURE LICENSE NO. (2)88 REGISTER OF DEEDS_____ _ LAND SURVEYOR, _ PROFESSIONAL ENGINEER DOCUMENT NUMBER_____ _ COUNTY SURVEYOR. _ COUNTY ENGINEER

1850s During the Original Public Land Survey, the US Deputy Surveyor set a section post in mound with trench, pits and charred stake and planted osage orange seeds at each angle.

August, 2000 Johnson & Scofield, Inc. excavated with a backhoe at the intersection of a east-west Township Road and a fence line running north. The excavation was 12 feet by 12 feet to a depth of 4 feet. Nothing was found...

The intersection of the centerline of the east-west Township Road with the fence line running north was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the west quarter corner and south quarter corner of Section 15 and measurements made to the north quarter corner and east quarter corner of Section 21. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East 14 CORNER OF SECTION 21 TOWNSHIP 108 N, RANGE 11 W, 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha.		
AT THE CORNER LOCATION SHOWN ON THE SKETCH:	•	
ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	MENT, _ REMOVED MONUMENT (EXPLAIN)	
X ON 10/2000 PLACED A 6' Long Steel	<u>"4" Post</u>	
SKETCH OF REFERENCE TIES		
MAN HOLE TO	<u>.</u> 2	
OUTFALL ~		
WASTE WATER TREATMENT		
STREAM		
N=113245.38 WAB. CO. COORD. E=533469.45 NAD. 1983 ADJ.		
FENCE X LINE		
R RIP PAP		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR PROFESSIONAL ENGINEER	BY DEPUTY	
COUNTY SURVEYOR COUNTY ENGINEER	DOCUMENT NUMBER	

October, 2000 Johnson & Scofield, Inc. searched for corner evidence at the intersection of the easterly projection of a fence line running west and the southerly projection of a fence line running north. Nothing was found. The above mentioned intersection falls in a ravine used for the disposal of waste water from the Plainview Wastewater Treatment Facility.

The intersection of the easterly projection of the fence line running west with the southerly projection of the fence line running north was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 21. A 6 foot long steel U post was set in the ravine to mark the corner.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
North 14 CORNER OF SECTION 22 TOWNSHIP LOBN RANGE II W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha.			
AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A 4"x 5"x 17" 5to	one Monument		
_ LEFT MONUMENT AS FOUND, & LOWERED MONUM	MENT, _ REMOVED MONUMENT (EXPLAIN)		
X ON 8/2000 PLACED A Wabasha Co	unty Monument		
SKETCH OF REI	FERENCE TIES		
SKETCH OF REFERENCE TIES OF THE STATE OF TH			
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.			
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20		
LICENSE NO. 12788	REGISTER OF DEEDS		
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY DEPUTY		
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER		

1850s During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest

June, 1979 Harry S. Johnson Companies set a 1 inch by 24 inch iron pipe at the intersection of a fence line running south and the centerline of an east-west Township Road.

August, 2000 Johnson & Scofield, Inc. found the iron pipe set by Harry S. Johnson Companies in 1979. An excavation was made with a backhoe at the location of the found iron pipe. The excavation was 12 feet by 10 feet to a depth of 4 feet. At a depth of 2 feet, approximately 7 feet west of the iron pipe, a 4 inch by 5 inch by 17 inch stone monument was found.

The found stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and northwest corners of Section 22. The stone monument was lower and two 1 inch by 18 inch iron pipes were placed above the stone, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

Index No
VERNMENT CORNER
nip <u>108 N</u> , Range <u>11 W</u> , <u>5th</u> P.M.
_
<i>i</i> ·
,fences east-west-south
nt, 🗆 removed monument (explain)
er cap) on south side fe post
TIES
**
. 14
le of fallen 18" tree(could,
le of fallen 18" tree(Court) le of fallen 18" tree(Court) le of North - 39 ft
sture land
sture
X X X
n West side of 14" Br.Oak
14.2 feet r of 24" Br.Oak N.E. 16 feet
r of 40" Maple Tree used as fence
r of fences East-West-N.NEly
11.5 feet.
n back of page.
COUNTY RECORDER OF THE RECUSTRER VOEX DEEDS
ertify that this document was filed in

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
	,Township $\frac{108 \text{ N}}{}$, Range $\frac{11 \text{ W}}{}$, $\frac{5 \text{th}}{}$ P.M.	
STATE OF MINNESOTA, County of WABASHA		
At the corner location shown on the sketch:		
的 Dec.6,1988 found of fence corner	junction, fences east-west-south	
☐ left monument as found, ☐ lowered	monument, \square removed monument (explain)	
On Jan.5,1989 placed a 1" iron pipe	(no number cap) on south side fe post	
SKETCH OF REF	ERENCE TIES	
of the state of th	Stump hole of fallen 18" tree(could, be Oak Tree) 3 ft. east of North-39 ft be Oak Tree) and pasture land s: Spk in West side of 14" Br.Oak North 14.2 feet Center of 24" Br.Oak N.E. 16 feet Center of 40" Maple Tree used as fence corner of fences East-West-N.NEly West 11.5 feet.	
Statement of evidence relative to this corner location is on back of page.		
COUNTY RECORDER		
contained herein was prepared by me or under my direct supervision.	hereby certify that this document was filed in the Reg. of Deeds office at #/:00 Ca.M. on the	
- Doger W. Brand Nov. 27, 1989 :	2PM day of Show A.D. 1929	
	Register of Deeds Healling to Deputy	
*	OCUMENT NO	

M.H.D. FORM NO. 2105

1854 M. Karrick Deputy Gov't Surveyor set Section Corner to 14,15,22,23

Took 4 B.T.s Br.Oak S 40 W 100 lks

Br.Oak N 31 W 75 lks.

Br.Oak N 41 E 179 lks.

Br.Oak S 42 E 142 Lks

No other records available.

1-1989 Roger W.Brand & Assoc., St.Charles, MN. visited corner location. Found 2 fence corners positions. The fence from the north intersects at a large maple tree and appears to bend to the west to attach to the tree. The other fence corner appears stable and lines with fence running south. We chose this corner post location as the section corner and placed an iron pipe beside it. Measured distances South and East.

No B.T.s were identified as being an original although there are Oak trees to the Northeast.

Index	Nia		
((11(1)		

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Common Quarter FAST QUARTER Corner of Section 22 , Township 108 N , Range 11 W , 5th P.M.			
STATE OF MINNESOTA, County of WABASHA			
At the corner location shown on the sketch:			
□ Onfound a			
	ed monument,		
X On <u>Jan.5,1989</u> placed a <u>1/2" iron</u>	Pipe on east side of corner fence		
	ost fence junction		
SKETCH OF RI	EFERENCE TIES		
Ι Δ			
7	· ·		
-N-	Pasking Super		
xed all	grove of		
Der king	60. \ \sqrt{\langle} \langle \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
1 State of the sta			
***	Openitive of the North Start Start Start		
Fance (in - 18/est			
Fonce (ine-West	Set 1/2" iron pipe as Quarter Corner		
large Trees in fence to West			
	a we		
, 0 0	5 OVER JORG		
See 8 al 8	S. Cor Gre		
opentisted set of	#		
J 2 1			
10 to 6			
100			
Statement of evidence relative to this corner location is on back of page.			
I hereby certify that this document and the data	COUNTY RECORDER OFFICE OF THE RECORDER STATE		
contained herein was prepared by me or under	County of		
my direct supervision.	I hereby certify that this document was filed in		
Goger W. Brand Nov. 27, 1989	the Reg. of Deeds office at 11: 0. M. on the and day of		
Registration No	Register of Deeds Leading Library		
	By,Deputy		
☐ County Surveyor. ☐ County Engineer	DOCUMENT NO.		

M.H.D. FORM NO. 2105

1854 M.Karrick, Deputy Gov't Surveyor, set Qr.Sec.corner Took one B.T. Br.Oak 14" S68W 285 lks.

No other records available.

1-1989 Roger W.Brand & Assoc., St.Charles, MN. visited corner location.

Found fence corner junction. Fences North, South, & West. Large Trees in fence running west. No B.T. location found.

Accepted fence corner as being the Quarter Section corner position and place ½" iron pipe beside it as actual monument.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTH QUARTER Corner of Section 23 , Township 108N, Range 11 W, 5 THPM.		
STATE OF MINNESOTA, County of WABASH	,	
At the corner location shown on the sketch:		
Onfound a		
DATE		
	ed monument, 🛛 removed monument (explain)	
M On 20 June 1989 placed a WABASHA	COUNTY MONUMENT	
AVETALL AF A	TEPENCE TIES	
SKETCH OF REFERENCE TIES I"XIB" iron pipe fence line I"XIB" iron pipe I"XIB" iron pipe I"XIB" iron pipe		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data	OFFICE OF THE REGISTER OF DEEDS	
contained herein was prepared by me or under my direct supervision.	County ofWABASHA	
	I hereby certify that this document was filed in the Reg. of Deeds office at <u>11:30 A</u> .M. on the	
Registration No. 12788	21st day of November A.D., 19 89	
Registration No. 12708 Land Surveyor, Professional Engineer	Register of Deeds Geraldine Tibor By Aug Deputy	
County Surveyor, County Engineer	DOCUMENT NO	

NORTH QUARTER CORNER OF SECTION 23, TOWNSHIP 108N, RANGE 11W

June 1854

Michael G. Karrick, U.S. Deputy Surveyor, set a wood post and referenced two Bur Oak trees. 8 inch North 3 degrees East 308 links 203.28 feet 10 inch North 20 degrees West 35 links 23.10 feet

May 2, 1989

Wabasha County Surveyors visited the site and searched the area for the Public Land Survey bearing trees and any existing monumentation or occupational evidence. A substantial fence line was found along the north line of the Northwest Quarter of Section 23, also a railroad spike set by Roger Brand (Land Surveyor) was recovered at the approximate position of the quarter corner.

May 3, 1989

Wabasha County Surveyors analyzed the north line of Section 23 and it was found that setting the corner by obliterated methods by intersecting an easterly extension of the line fence along the north line of the Northwest Quarter of Section 23 with the southerly extension of the tangent centerline of the Townroad to the north, which would agree with the found railroad spike set by Roger Brand was the best evidence of the original Public Land Survey corner. A Wabasha County Monument was set.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Northastcorner of section _23township_108 N _range 11 W _5th_p.m. STATE OF MINNESOTA, COUNTY OFWabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A LEFT MONUMENT AS FOUND,LOWERED MONUMENT,REMOVED MONUMENT (EXPLAIN)			
X ONIO/2000 PLACED A Wabasha C	ourcy tribitativent		
SKETCH OF REF	FERENCE TIES		
SKETCH OF REFERENCE TIES 2 36" BURR OAK N= 115729.91 WAB. CO. COORD. E=544005.57 NAD 1983 ADJ.			
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.			
HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20		
LICENSE NO. [2788]	REGISTER OF DEEDS		
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY		
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER		

October, 2000 Johnson & Scofield, Inc. probed to a depth of 3 feet in a 10 foot diameter area around the intersection of a fence line running north and a fence line running west. Nothing was found.

The 2-way fence intersection was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the south quarter corner and west quarter corner of Section 13 and by measurements made to the north quarter corner and east quarter corner of Section 23. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East 1/4 CORNER OF SECTION 23 TOWNSHIP 108 N RANGE 11 W 5th P.M.		
STATE OF MINNESOTA, COUNTY OF Wabasha at the corner location shown on the sketch:	antition state destinated of the state of th	
ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	MENT, REMOVED MONUMENT (EXPLAIN)	
1 ON10/2000PLACED A Wabasha Co	under DA and	
S UNITY STATED A WEBSTIE CO	ancy with the ment	
SKETCH OF RE	FERENCE TIES	
	*	
S ^N	*	
Hoop Jerry) 20'±	
3	N= 113120.06 WAB. Co. COORD. E= 543987.23 NAD 1983 ADJ.	
7	E= 54 9487.23 KMS 130 7 7 7	
	· ·	
l I		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. (2788	REGISTER OF DEEDS	
_ LAND SURVEYOR, PROFESSIONAL ENGINEER	BY DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

October, 2000 Johnson & Scofield, Inc. hand dug and probed to a depth of 1 foot in a 10 foot diameter area around the lost position.

Nothing was found.

Because no monument or occupational evidence was found, the corner was re-established at the lost position. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER North 1/4 CORNER OF SECTION 24 TOWNSHIP 108 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ON. FOUND A _ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) x ON10/2000 PLACED A Wabasha County Monument SKETCH OF REFERENCE TIES END OF FENCE WAB. CO. COORD. N=115704.08 NAD 1983 ADJ. E-54621.49 E=546621.49 FIELD DIVISION LINE STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET. I HEREBY CERTIFY THAT THIS DOCUMENT AND THE OFFICE OF THE REGISTER OF DEEDS COUNTY OF ______ DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNGER MY DIRECT SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT_______.M. ON THE _____DAY OF ______A.D., 20___

LICENSE NO. 12788 LAND SURVEYOR, _ PROFESSIONAL ENGINEER COUNTY SURVEYOR, _ COUNTY ENGINEER

REGISTER OF DEEDS_____ BY_____, DEPUTY DOCUMENT NUMBER_____

October, 2000 Johnson & Scofield, Inc. established the location for the corner at the intersection of a straight line between the northwest corner and northeast corner of Section 24 and the southerly projection of a fence line running along the north-south quarter line of Section 13. No occupation lines exist along the north line of Section 24. An area 10 feet in diameter around the

and nothing was found.

The intersection of a straight line between the northwest and northeast corners of Section 24 with the southerly projection of the fence line running along the north-south quarter line of Section 13 was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated with measurements made to the northeast and northwest corners of Section 24. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

above mentioned intersection was probed to a depth of 3 feet

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
Northeast corner of Section 24 , Township 108 N, RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON10/2000 FOUND A 6"X 6" X 24" Stone Monument With X on TOP		
* LEFT MONUMENT AS FOUND, _ LOWERED MONUM	MENT, _ REMOVED MONUMENT (EXPLAIN)	
ONPLACED A		
SKETCH OF REI	FERENCE TIES	
SKEICH OF REI		
FENCE		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 1788	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

- 1850s During the Original Public Land Survey, the US Deputy Surveyor set a section post and made reference to 4 witness trees.
- 1891 F. A. Bratka indicates a stake and bearing trees.
- 1905 E. C. Burns indicates a stone and bearing tree.
- October, 2000 Johnson & Scofield, Inc. excavated with a tractor and hydraulic bucket along a north-south fence line near the lost position. The excavation was 60 feet north and south by 12 feet east and west to a depth of 1.5 feet. A 6 inch by 6 inch by 24 inch stone monument, with an X in the top, was found at the northerly end of the excavation at a depth of 6 inches. The stone monument is believed to be the one set by E. C. Burns in 1905 and is accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the east quarter corner of Section 13 and to the east quarter corner of Section 24. The top of the stone monument was left exposed and a steel fence post was driven on the south side.

CERTIFICATE OF LOCATION C	F GOVERNMENT CORNER
East 1/4 CORNER OF SECTION 24 ,TOWN STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A LEFT MONUMENT AS FOUND, _ LOWERED MONUM	
X ON 10/2000 PLACED A Wabasha Count	ty Monument
SKETCH OF REF	ERENCE TIES
WAB. CO. N=113117.17 L. COORD. NAD E= 549221.89 X L. COORD. NAD E= 549221.89	BOTTOM OF BLUFF
STATEMENT OF EVIDENCE RELATIVE TO THIS CORN	NER LOCATION IS ON THE BACK OF THIS SHEET.
HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 1788	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
	BY, DEPUTY
LAND SURVEYOR, _ PROFESSIONAL ENGINEER COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER
_ COUNTY SURVETOR, COUNTY ENGINEER	

October, 2000 Johnson & Scofield, Inc. hand dug and probed in a 20 foot diameter area to a depth of 1 foot at the intersection of an eastwest fence line with a straight line between the northeast and southeast corners of Section 24. Nothing was found.

The intersection of the east-west fence line with a straight line between the northeast and southeast corners of Section 24 was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast corner and southeast corner of Section 24. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER North 1/4 CORNER OF SECTION 25 TOWNSHIP 108 N. RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 10/2000 FOUND A 1" X 14" x 24" Flat Iron Bar LEFT MONUMENT AS FOUND. _ LOWERED MONUMENT. KREMOVED MONUMENT (EXPLAIN) X ON 10/2000 PLACED A Wabasha County Monument SKETCH OF REFERENCE TIES N=110497.80 WAB. CO. COOPD. E=546595.99 NAD 1983 ADJ. CENTERLINE STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET. I HEREBY CERTIFY THAT THIS DOCUMENT AND THE OFFICE OF THE REGISTER OF DEEDS DATA CONTAINED HEREIN WAS PREPARED BY ME OR COUNTY OF __ I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT______.M. ON THE _____DAY OF ______A.D., 20___ LICENSE NO. 12788 REGISTER OF DEEDS_____ _ LAND SURVEYOR. _ PROFESSIONAL ENGINEER DOCUMENT NUMBER____ COUNTY SURVEYOR, _ COUNTY ENGINEER

October, 2000 Johnson & Scofield, Inc. found a 1 inch by 1/4 inch by 2 foot long flat iron bar standing plum in the ground. A 10 foot diameter area around the flat iron bar was probed to a depth of 2 feet and no further evidence was found.

The found 1 inch by 1/4 inch by 2 foot long flat iron bar was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the southeast and southwest corners of Section 24. The flat iron bar was replaced with two 1 inch by 18 inch iron pipes, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
Northast corner of Section 25 , Tov	WISHIP 108 N , RANGE 11 W , 5th P.M.	
STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH:	·	
X ON 10/2000 FOUND A 6"x6" Stone N	Monument With x" on top	
	MENT, REMOVED MONUMENT (EXPLAIN)	
ONPLACED A		
SKETCH OF REI	FERENCE TIES	
E Constanting of the Constanting	N= 110482.90 WAB. Co. COORD. /E= 549229.64 NAD. 1983 ADJ.	
Eux S		
2.5′	STEEL FENCE POST	
	3.	
,σι Ή ₁		
<u>ŏ</u>		
Juni Juni	circles - k	
3	k	
3	2	
FIEL	E	
STATEMENT OF EMPENCE BELADIVE TO THIS CORNED LOCATION IS ON THE BACK OF THIS SHEET		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
Maril A. Mism 11/3/2000	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON	
SIGNATURE DATE	THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

1905 E. C. Burns indicates a stone and bearing tree at the corner.

October, 2000 Johnson & Scofield, Inc. found a 6 inch by 6 inch limestone monument with a chiseled X on the top. The top of the stone monument was 1 foot above ground.

The found stone monument was believed to be the one set by E. C. Burns in 1905 and is accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the north quarter corner and east quarter corner of Section 25 and by measurements made to the east quarter corner of Section 24. The stone monument was left as found and is marked with a steel fence post on the east side.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East 14 CORNER OF SECTION 25 TO	WNSHIP 108 N , RANGE 11 W , 5th P.M.	
STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH:		
X ON 8/200 FOUND A 10" X 12" X ZO" S	stone Monument	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	MENT, _ REMOVED MONUMENT (EXPLAIN)	
X ON8/2000 PLACED A Wabasha Cou	nty Manument	
N UNG PLACEU A WADASHA COU	- Ly I COMMILENC	
SKETCH OF RE	FERENCE TIES	
ROAD		
$ ec{\omega} $	N=107851.76 WAB. CO. COORD. E= 549234.24 NAO. 1983 ADJ.	
X FENCE X LINE X		
	lu l	
	77 77 77 77 77 77 77 77 77 77 77 77 77	
	CENTERLINE	
	() (0)	
N S 1		
TOWN		
~		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR	OFFICE OF THE REGISTER OF DEEDS	
UNDER MY DIRECT SUPERVISION.	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED	
SIGNATURE DATE	IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY DEPUTY	
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	
=: V == = = = · · · · · · · · · · · · · ·	Į.	

- 1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.
- 1923 E. C. Burns found the quarter corner as evidenced by a government witness tree. He placed a 1 and 1/2 inch by 34 inch iron pipe.
- August, 2000 Johnson & Scofield, Inc. searched with an electronic metal detector at the intersection of the centerline of the north-south Township Road and a fence line running west. Nothing was found. A 10 foot by 10 foot by 2 foot deep excavation was made with a backhoe. A 10 inch by 12 inch by 20 inch stone monument was found in natural soil at a depth of 2 feet. The stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 25. The stone monument was lowered and a 1 inch by 18 inch iron pipe was placed on the north side. A second 1 inch by 18 inch iron pipe was placed above the stone with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTH QUARTER Corner of Section 26 , Township 1081, Range 11 W, 5 th P.M.		
STATE OF MINNESOTA, County of WABASHA		
At the corner location shown on the sketch:		
□ On found a		
	ed monument, removed monument (explain)	
M On 3 Nov. 1989 placed a WABASHA COUNTY MONUMENT		
SKETCH OF R	EFERENCE TIES	
1 4		
-N-		
Spike easterly side 8" PINE 16		
Spike easterly side 8"PINE ** TREE ** *** *** *** *** ** ** ** *	n o	
***	1'-0 1"X18" pipe set in G	
.01		
oile easterly		
spike easterly / F side Power Pole &		
4		
Statement of avidence relative to this corner location is an back of page		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS County of WABASHA	
my direct supervision.	I hereby certify that this document was filed in	
Pavid A. Jomen 11/17/89 SIGNATURE DATE	the Reg. of Deeds office at $\frac{11:30}{A}$.M. on the $\frac{21st}{A}$ day of $\frac{11:30}{A}$.A.D., 1989	
Registration No. 12786	Register of Deeds Geraldine Tibor	
Land Surveyor, 🗆 Professional Engineer	By Tay Oracle Deputy	
County Surveyor, County Engineer	DOCUMENT NO.	

NORTH QUARTER CORNER OF SECTION 26, TOWNSHIP 108N, RANGE 11W

June 1854 Michael G. Karrick, US Deputy Surveyor, set a wood post and referenced two Bur Oak trees

16 inches North 52 degrees East 188 links, 124.08 feet

12 inches South 15 degrees West 230 links, 151.80 feet

May 2, 1989 Wabasha County Surveyors visited the site and searched the area for the Public Land Survey bearing trees and any existing

monumentation or occupational evidence, but nothing was recovered. A position was set on line and at the midway point between the occupied corners of the northeast and

northwest corners of Section 26.

May 3, 1989 Wabasha County Surveyors excavated an area 8 feet square and 3.5 feet deep with a backhoe at the above described position,

but nothing was recovered.

Nov. 3, 1989 Wabasha County Surveyors after further examination decided to excavate an area along the centerline of the Township Road.

at a point equal distance from the occupied centers of Sections 23 and 26. An area 6 feet square and 4 feet deep was excavated with a backhoe but no evidence was recovered. The corner was remonumented using obliterated methods on the centerline of the existing North-South Township Road so that the fence occupation lines at the center of Section 23 and at the center of Section 26 are at equal distances. This position is confirmed by the East-West 1/16th fence between the center of Section 23 and the south quarter corner. It was felt that this position best perpetuates the original

Public Land Survey corner and a Wabasha County Monument was

installed.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER northeast Corner of Section 26, Township 108, Range 11, 5th		
·	OF MINNESOTA, County ofWabasha	,rownship, range,,, P.M.
ŀ	corner location shown on the sketch:	
		sino.
[[3]	On Dec 19, 1997 found a 2 inch iron p) The
	☑ left monument as found, ☐ lowere	ed monument, removed monument (explain)
23	On Dec 22, 1997 placed a 2 inch Wabash by 18 inch in iron pipe.	na County cast iron cap on top of a 1 inch ron pipe over another 1 inch by 18 inch
SKETCH OF REFERENCE TIES		
FENCE IN WEST SIDE OF TREE		
SPIKE IN 8" OAK		
UP 2' ON EAST SIDE		
20.50 < 27.45		
	SPIKE IN 16" OAK UP 2.5' ON SOUTHEAST SIDE	
	* \ /	
××××× × × × × × × × × × × × × × × × ×		
SPIKE IN 10" TREE		
UP 1.5' ON SOUTH SIDE		
$2'\pm 2 - \frac{1}{2}$		
17.62 SPIKE IN 24" OAK		
17.62 SPIKE IN 24 DAK UP 1' ON NORTHEAST SIDE		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS		
contained herein was prepared by me or under County of Wabasha		
my di	irect supervision.	I hereby certify that this document was filed in the Reg. of Deeds office at 1:00 P.M. on the
10	WW H. Man 1/2/98 SIGNATURE DATE	13th day of January A.D., 1998
Regis	tration No. 12788	Register of Deeds Reflery R. aither
	Land Surveyor, 🗆 Professional Engineer	By Janeu Cantoenias ,Deputy
	County Surveyor, County Engineer	DOCUMENT NO.

Northeast corner of Section 26, Township 108 North, Range 11 West

June, 1855

Michael G. Karrick, Goodhue Surveyor, set a post and referenced 4 bur oak trees during the Original Public Land Survey.

December, 1997

Brad Bohlen, of Johnson, Scofield & Rehder, Inc., searched the area and found a two inch diameter iron pipe at a fence corner intersection. The area was excavated and probed. but no other monument evidence was recovered. The original bearing trees were also searched for, but none were recovered. Measurements were made to occupation lines to the north, the south, the east and the west. It was determined that all of these measurements compared favorably with the Original Public Land Survey measurements. As the monument coincided with local fence occupation lines and compared favorably with Public Land Survey measurements, it was accepted as the obliterated position for the Original Public Land Survey Corner. The two inch diameter iron pipe was left as recovered and two 1 inch by 18 inch iron pipe were driven down the center of the existing two inch pipe and a two inch diameter cast iron Wabasha County cap was affixed to the top of the top 1 inch iron pipe.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East 14 CORNER OF SECTION 26 TOWNSHIP 108 N RANGE 11 W 5th P.M.		
STATE OF MINNESOTA, COUNTY OF Wabasha		
AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 1/2000 FOUND A 1-1/2" Iron Pipa		
上 LEFT MONUMENT AS FOUND, _ LOWERED MONU!	MENT, _ REMOVED MONUMENT (EXPLAIN)	
x ON 11/2000 PLACED A Wabasha Con	unty Monument	
SKETCH OF REFERENCE TIES		
DE 107880.57 E= 543956.23 No. 25		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY DEPUTY	
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

December, 1997 Johnson & Scofield, Inc. found a 1 and 1/2 inch iron pipe at the corner.

November, 2000 Johnson & Scofield, Inc. found the same 1 and 1/2 inch iron pipe, as was found in 1997.

The above mentioned found 1 and 1/2 inch iron pipe was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 26. A 1 inch by 18 inch iron pipe, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top, was driven inside the found 1 and 1/2 inch iron pipe.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
North 1/4 corner of section 27 township 100 N, range 11 W, 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha.		
AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN)		
X ON 10/2000 PLACED A Wabasha County Monument		
SKETCH OF REFERENCE TIES		
	N= 110583.41 WAB. CO. COORD. E= 536109.27 NAD 1983 ADJ.	
COUNTY ROAD	NUMBER 25	
☆		
щ		
LINE	·	
T EN CE	,	
7 7		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. [2788]	REGISTER OF DEEDS	
_ LAND SURVEYOR, PROFESSIONAL ENGINEER	BY, DEPUTY	
COUNTY SURVEYOR COUNTY ENGINEER	DOCUMENT NUMBER	

October, 2000 Johnson & Scofield, Inc. searched with an electronic metal detector at the intersection of the centerline of County Road Number 25 with a fence line running south. Nothing was found. The construction plans for County Road Number 25, obtained from the Wabasha County Engineer, indicated an approximate 4 foot cut at the corner location, therefore the corner was not excavated.

The intersection of the centerline of County Road Number 25 with the fence line running south was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and northwest corners of Section 27. A 1 inch by 18 inch iron pipe was placed, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
Northcast corner of section 27, Township 108 N _, Range 11 W _, 5th p.m. STATE OF MINNESOTA, COUNTY OF		
SKETCH OF RE	FERENCE TIES	
FENCE LINE TENCE LINE	N= 110551.16 WAB. CO. COORD. E= 538707.42 NAD 1983 ADJ.	
	·	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY DEPUTY	
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy Surveyor set a section post and made reference to 2 witness trees.

December, 1997 Vince Fangman found a 6 inch by 10 inch limestone monument at the corner.

October, 2000 Johnson & Scofield, Inc. found the stone monument made reference to by Vince Fangman in 1997. The stone monument is approximately 1.5 feet southeasterly of a 3-way fence intersection.

The stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the south quarter corner and west quarter corner of Section 23 and by measurements made to the north quarter corner and east quarter corner of Section 27. The stone monument was left as found and is marked with a white fiberglass fence post.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
East 1/4 CORNER OF SECTION 27 TOV	WISHIP 108 N , RANGE 11 W , 5th P.M.
AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A 5/8 Inch Iron Pipe	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT	MENT, X REMOVED MONUMENT (EXPLAIN)
X ON 8/2000 PLACED A Wabasha Coun	ty Monument
SKETCH OF REI	FERENCE TIES
ROAD	
[8]	N= 107895-95 WAB. CO. COORD. /E= 538702.24 NAD. 1983 ADJ.
FENCE LINE	X FENCE X LINE X
×	X X X
	如文
	CENTERLI NE
d H	
W	
TOWN	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20
LICENSE NO. 12788	REGISTER OF DEEDS
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

December, 1999 Vince Fangman found an iron monument at the corner.

August, 2000

Johnson & Scofield, Inc. found a 5/8 inch iron pipe at the intersection of the centerline of a north-south Township Road and a fence line running east and a fence line running west. The 5/8 inch iron pipe is believed to be the same one found by Vince Fangman in 1997. A 12 foot by 13 foot by 4 feet deep excavation was made with a backhoe at the location of the found iron pipe. Nothing was found.

The found iron pipe was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 27. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

North 14 CORNER OF SECTION 28 TOWNSHIP 108 N , RANGE 11 W , 5th p.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A Wabasha County Monument	
	N= 110621.18 WAR CO. COORD. E= 530851.98 NAD 1983 ADJ.
COUNTY ROAD	No. 25
TOWNSHIP ROAD CENTERLINE	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
SIGNATURE DATE	IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20
LICENSE NO. (2788	REGISTER OF DEEDS
LAND SURVEYOR, PROFESSIONAL ENGINEER	DOCUMENT NUMBER
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

north quarter corner of Section 28, Township 108 North, Range 11 West

During the Original Public Land Survey, the US Deputy
Surveyor set the quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

August, 2000 Johnson & Scofield, Inc. searched with an electronic metal detector at the intersection of the centerline of County Road Number 25 with the centerline of a Township Road running south. Nothing was found. The construction plans for County Road Number 25 were obtained from the Wabasha County Engineer. The plans indicate that at the corner location the road was cut one to two feet. Therefore, no excavation for the corner was made.

The intersection of the centerline of County Road Number 25 with the centerline of the Township Road running south was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and northwest corners of Section 28. A 1 inch by 18 inch iron pipe was placed, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 28 TOWNSHIP 108 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabashas. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	JMENT, REMOVED MONUMENT (EXPLAIN)
X ON 10/2000 PLACED A Wabasha Coun-	Ly Monument
SKETCH OF RI	EFERENCE TIES
SKETCH OF REFERENCE TIES SCOUNTY ROAD # 25 COUNTY ROAD # 25	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12788 LAND SURVEYOR, PROFESSIONAL ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

During the Original Public Land Survey, the US Deputy Surveyor set a section post and made reference to 4 witness trees.

October, 2000 Johnson & Scofield, Inc. hand probed and dug in a 10 foot diameter area around the intersection of a north-south fence line with the easterly projection of the centerline of County Road Number 25. Nothing was found.

The intersection of the north-south fence line with the easterly projection of the centerline of County Road Number 25 was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the west quarter corner and south quarter corner of Section 22 and by measurements made to the north quarter corner and east quarter of Section 28. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East 1/4 CORNER OF SECTION 28 TOWNSHIP 108 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 10/2000 FOUND A 6 Inch x 8 Inch x 18 Inch Limestone Manument	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT	MENT, AREMOVED MONUMENT (EXPLAIN)
X ON10/2000 PLACED A Wabasha Co	unty Monumant
SKETCH OF RE	FERENCE TIES
SKETCH OF REFERENCE TIES N= 107979.06 WAB. CO. COOPD. E= 533456.99 NAD. 1983 ADJ. YENCE Y LINE Y FENCE Y LINE Y	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20 REGISTER OF DEEDS, DEPUTY DOCUMENT NUMBER
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOODING!! WOMBEN

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

October, 2000 Johnson & Scofield, Inc. probed a 10 foot diameter area to a depth of 1 foot at a 3-way fence intersection. A 6 inch by 8 inch by 18 inch pointed limestone monument was found at the fence intersection.

The found pointed limestone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corner of Section 28. The stone monument could not be lower and therefore was removed and replaced with two 1 inch by 18 inch iron pipes, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
North 1/4 CORNER OF SECTION 29 TOWNSHIP 108 N, RANGE 11 W, 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A	
_ LEFT MONUMENT AS FOUND,LOWERED MONU	MENT, REMOVED MONUMENT (EXPLAIN)
X ON 10/2000 PLACED A Wabasha Cour	nty Monument
SKETCH OF REFERENCE TIES //0642.33	
1.1	N=4064233
4	E= 525591.17
.	WAB. Co. COORD. SYSTEM NAD. 83, 1996 Adj. (HARN)
	165 Oct. 2018
92	N=110642.33 WAS CO. COOED.
	5-525591. 17 NAD 1983 FIDJ.
COUNTY ROAD	NO. 25
COUNTY ROAD CENTERLINE	
10/16/18	
Stamped "WAB Co. Monument" &	CENTERLINE
Stamped "WAB Co. Monument"	H H
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
ار ا	8
Y T N	
	•
STATEMENT OF EVIDENCE RELATIVE TO THIS CORT	NER LOCATION IS ON THE BACK OF THIS SHEET.
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
MWWA. IMEM 9 Nov. 9000 SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20
LICENSE NO. 12788	REGISTER OF DEEDS
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY DEPUTY
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

north quarter corner of Section 29, Township 108 North, Range 11 West

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post in mound with trench, pits and charred stake and planted osage orange seeds northeast and southwest.

May, 1956 Norbert Rehder, with Johnson & Scofield, Inc., excavated with a backhoe an area 6 foot by 12 foot to a depth of 4 feet. The excavation was centered on the intersection of the centerline with an east-west road with the centerline of a north-south road. Nothing was found.

October, 2000 Johnson & Scofield, Inc. accepted the intersection of the centerline of the east-west road with the centerline of the north-south road as the best perpetuation of the Original Public Land Survey Corner. It was substantiated by measurements made to the northeast and northwest corners of Section 29. A 1 inch by 18 inch iron pipe was placed, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

STATEMENT OF EVIDENCE

North Quarter Corner of Section 29, Township 108 North, Range 11 West

October 16, 2018

Johnson & Scofield, Inc. placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road grading and resurfacing of County Road No. 25 which destroyed the previously set county monument.

Marcus S. Johnson Wabasha County Surveyor MN License No. 47460 Date: October 23, 2018

During the Original Public Land Survey, the US Deputy Surveyor set a section post in mound with trench, pits and charred stake and planted osage orange seeds at each angle.

May, 1986 Norbert Rehder, with Johnson & Scofield, Inc., excavated a 6 foot by 12 foot area to a depth of 4 feet with a backhoe at the intersection of the centerline of an east-west road with occupation lines to the north and south. Nothing was found.

October, 2000 Johnson & Scofield, Inc. accepted the intersection of the centerline of the east-west Township Road with the occupation lines running north and south as the best perpetuation of the Original Public Land Survey Corner. This was substantiated by measurements made to the west quarter corner and south quarter corner of Section 21 and by measurements made to the north quarter corner and east quarter corner of Section 29. A 1 inch by 18 inch iron pipe was placed, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 29	,Township <u>108</u> ,Range <u>11</u> , <u>5th</u> P.M.
STATE OF MINNESOTA, County of Wabasha	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowere	ed monument, removed monument (explain)
Onplaced a	
SKETCH OF RE	FERENCE TIES
4	
CERTIFICATE OF SEARCH	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS County of
my direct supervision.	I hereby certify that this document was filed in
David A. Johnson 5/9/86	the Reg. of Deeds office at // AM. on the
Registration No. 12788	Register of Deeds Weekler Il
△ Land Surveyor, □ Professional Engineer	By,Deputy
County Surveyor, County Engineer	DOCUMENT NO.
M.H.D. FORM NO. 2105	

Statement of Evidence:

CERTIFICATE OF SEARCH

NORTHEAST CORNER OF SECTION 29, TOWNSHIP 108, RANGE 11

June 1854

Michael G. Karrick, Deputy Surveyor, placed a charred stake in a mound.

April 29, 1986

Norbert Rehder, with Johnson & Scofield Inc., excavated a 6 foot by 12 foot area 4 feet deep with a backhoe and found no evidence. The excavation was centered on the intersection of the East-West road centerline with the North-South occupation lines.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
East 1/4 CORNER OF SECTION 29 TOWNSHIP 108 N , RANGE 11 W , 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 11/2000 FOUND A 5 " x 6" x 24" Stone Monument		
SKETCH OF RE	FERENCE TIES	
SKETCH OF REFERENCE TIES N= \08019.94 WAB. CO. COOPD. E= 528206.90 NAD 1983 RDJ. FENCE LINE TREES		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. Man	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY, DEPUTY	
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

During the Original Public Land Survey, the US Deputy
Surveyor set a quarter section post in mound with trench, pits
and charred stake and planted osage orange seeds northeast and
southwest.

November, 2000

Johnson & Scofield, Inc. hand dug and probed around a 3-way fence intersection. A 5 inch by 6 inch by 24 inch limestone monument was found at the fence intersection. The top of the stone monument was 1/2 foot below the ground surface.

The found stone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 29. The top of the stone monument was left exposed and is marked by the 3-way fence intersection.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
North 1/4 CORNER OF SECTION 30 TO	WNSHIP 108 N RANGE 11 W ,5th P.M.
STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH:	namen salan sa
X ON 10/2000 FOUND A 5/8" X 12" Iron Pi	IPC
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	
_ LEFT MUNUMENT AS FUUND, _ LUWERED MUNU	MILITI, _ REMOVED MONUMENT (EXPLAIN)
* ON 10/2000 PLACED A Wabasha Cour	nty Monument
SKETCH OF REFERENCE TIES	
I N E	
اِ تَـ	
w v	
开 N C C C	
× ×	N= 110671.40 WAS. CO. COOPD.
1	E=520321.72 NAD 1983 Act.
COUNTY ROAD	No. 25
C CENTERLINE	A A A A A A A A A A A A A A A A A A A
10/16/2018	N=110671.40
DLACED I" COPPER Monument	E :520 321.72 WAB CO. COORD SYSTEM.
PLACED " COPPER MONUMENT" Stamped "WAB CO MONUMENT"	NAD 83, 1994 Adj. (HARN)
	405- Oct. 2018
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
SIGNATURE DATE	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT
LICENSE NO. 12788	REGISTER OF DEEDS
	BY DEPUTY
LAND SURVEYOR, PROFESSIONAL ENGINEER	
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

north quarter corner of Section 30, Township 108 North, Range 11 West

- 1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post in mound with trench, pits and charred stake and planted osage orange seeds northeast and southwest.
- April, 1980 Harry S. Johnson Companies set a 5/8 inch by 12 inch iron pipe at the intersection of the centerline of County Road Number 25 with a fence line running north.
- May, 1994 David A. Johnson, Wabasha County Surveyor, on survey for Wabasha County Engineering Department to establish section corners along the route of County Road Number 25, determined that this corner location was in a cut section of the road and no excavation was necessary.
- October, 2000 Johnson & Scofield, Inc. found a 5/8 inch by 12 inch iron pipe placed in April of 1980.

The 5/8 inch by 12 inch iron pipe placed in 1980 was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast corner and the northwest corner of Section 30. The pipe was replaced with a 1 inch by 18 inch iron pipe, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

STATEMENT OF EVIDENCE

North Quarter Corner of Section 30, Township 108 North, Range 11 West

October 16, 2018

Johnson & Scofield, Inc. placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road grading and resurfacing of County Road No. 25 which destroyed the previously set county monument.

Marcus S. Johnson Wabasha County Surveyor MN License No. 47460 Date: October 23, 2018

CERTIFICATE XOFX MOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 30, Township 108, Range 11, 5, P.M.	
STATE OF MINNESOTA, County ofWabasha	
At the corner location shown on the sketch:	
on 5/24/94 found a iron sipe	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
Y on 5/24/94 placed a 1"X18" iron pipe in Some position	
as found pipe 4 below Good bituminous	
SKETCH OF REFERENCE TIES	
A sketch of reference ties pipe 6 north of road adga	
1 -N- 499	
10/16/18 PLACED I"	
Copper Monument	
Stamped "WAR Co	
& Co. Rd. No. 257 / monsument"	
N=110653.38	
E = 522953.64 22.04	
WAB Co. COOKD. System	
NAD 83, 1996 adj. (HARN) OP: pa 10' south	
16 Oct. 2018 of Rd. Odga	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS contained herein was prepared by me or under County of	
my direct supervision I hereby certify that this document was filed in	
the Reg. of Deeds office at 11:30 A.M. on the 4 day of 12.30 A.D., 1994	
Registration No. 12788 Register of Beeds Gualdine Johan	
Land Surveyor, - Professional Engineer By Warleen M. Ancipeputy	

Statement of Evidence:

Northeast corner of Section 30, Township 108, Range 11

May 24, 1994

David A. Johnson, Wabasha County Surveyor, excavated a 10 by 10 foot area, 7 feet deep with a County backhoe prior to an overlay project on County Road Number 25. The excavation was made to original subsoil, but no monument evidence was recovered. An iron pipe was recovered on the surface of the blacktop road prior to the excavation. It was referenced out and returned to it's original location after the excavation. The iron pipe was accepted as a perpetuation of the original Public Land Survey corner.

STATEMENT OF EVIDENCE

Northeast Corner of Section 30, Township 108 North, Range 11 West

October 16, 2018

Johnson & Scofield, Inc. placed a 1 inch copper monument using previously recorded coordinates to restore the corner following road grading and resurfacing of County Road No. 25 which destroyed the previously set county monument.

Marcus S. Johnson Wabasha County Surveyor MN License No. 47460 Date: October 23, 2018

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East 1/4 CORNER OF SECTION_30 TOWNSHIP_108 N _RANGE 11 W _5th_p.m. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A LEFT MONUMENT AS FOUND, LOWERED MONUMENT, REMOVED MONUMENT (EXPLAIN) x ON 11/2000 PLACED A Wabasha County Monument	
SKETCH OF RE	FERENCE TIES
SKETCH OF REFERENCE TIES FIELD N=108014.81 WAB. CO. COORD. E=522937.69 NAD 993 ADJ. FENCE LINE TREE LINE TREE LINE FIELD	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12788 LAND SURVEYOR, PROFESSIONAL ENGINEER COUNTY SURVEYOR, COUNTY ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF

During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

November, 2000 Johnson & Scofield, Inc. hand dug and probed to a depth of 2 feet in a 10 foot diameter area centered around the intersection of a fence line running east, a fence line running south and a field division line running north. Nothing was found.

The above mentioned fence intersection was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 30. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
North 1/4corner of section 31township 108 N _range 11 W _5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A	
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	MENT, _ REMOVED MONUMENT (EXPLAIN)
Y ON 11/2000 PLACED A Wabasha Cou	inty Monument
SKETCH OF RE	FERENCE TIES
SKETCH OF REFERENCE TIES WASS. Co. Coop.D. N= 105404-60 E= 520 292.58 WASS. Co. Coop.D. N= 105404-60 E= 520 292.58 WASS. Co. Coop.D. N= 105404-60 E= 520 292.58	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. WWW. Alba A	OFFICE OF THE REGISTER OF DEEDS COUNTY OF
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER _ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

November, 2000

Johnson & Scofield, Inc. probed and hand dug a 10 foot diameter area around the intersection of a straight line between the northeast and northwest corner of Section 31 with a fence line running north and south. Nothing was found. The intersection of a straight line between the northeast corner and northwest corner of Section 31 with the fence line running north and south was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and northwest corners of said Section 31. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker" affixed to the top.

CERTIFICATE OF LOCATION	N OF GOVERNMENT CORNER
NORTHEAST Corner of Section 3	Township 108 N, Range 11 W, 5 th. P.M.
STATE OF MINNESOTA, County of WABASH	
At the corner location shown on the sketch	
\boxtimes On $\frac{9-17-79}{\text{sate}}$ found a $\frac{13/8"}{\text{IRON}}$	I PIPE, DOWN 0.3'
	ered monument, D removed monument (explain)
Ø On 7-26-89 placed a 3/4" x 24"	IRON PIPE WITH 2" CAST IRON CAP,
UP 0.4', INSIDE A 13/8" IRON PI	IPE , DOWN 0.3'
SKETCH OF F	REFERENCE TIES
N 45 W X 25.84' X DNR NAIL & DISC SW SIDE 5" POPLAR UP 1.0'	OTE: MONUMENT IS 1.3' NORTH OF STEEL FENCE POST IO2.0' NORTH OF ELECTRIC FENCE EAST ON N-S FENCE ON N-S WOODS LINE
WOODS	< CULTIVATED
CULTIVATED S 8 1° W 11.35'	S27°E 12.02' DNR NAIL & DISC
DNR NAIL & DISC × NORTH SIDE 8" BOXELDER	WSW SIDE 8" BOXELDER UP 1.0'
UP 1.0'	FIELD
	ELECTRIC FENCE
FIELD x	— x —— x —— x
×	
	BEARINGS OBSERVED WITH COMPASS
Statement of evidence relative to this corner loc	cation is on back of page P. 078. 00.01
I hereby certify that this document and the data contained herein was prepared by me or under	County of WABASHA
My direct supervision Youll R. Tommerening 9-21-89	I hereby certify that this document was filed in the Co. Recorders office at 4:00 PM. on the 22nd day of September A.D., 19 89
Registration No. 17005	County Récorder Geraldine Tibor
Land Surveyor, Professional Engineer	DOCUMENT NO
County Surveyor County Engineer	DOCUMENT NO.

Northeast Corner Section 31, Township 108 North, Range 11 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN Secretary of State Wabasha County Recorder and Auditor Wabasha County Highway Engineer Plainview Township Clerk

1854 The U.S. General Land Office notes in the the Secretary of State's Office show the corner marked with a post and recorded the following bearing trees:

Burr Oak 10", N. 4° W., 65 links Burr Oak 12", N. 50° E., 115 links Also dug a trench.

- 1938 Airphotos from the DNR Bureau of Engineering show a definite line of occupation running north-south at this corner.
- The DNR Bureau of Engineering contracted J. J. Kleinschmidt of Winona to survey the boundary of Carley State Park. In the course of this survey, a 1" by 24" iron pipe was set at this corner. A fence line south is shown at this corner which measures:

2622.32 ft. from the east quarter corner Section 31 5244.64 ft. from the southeast corner Section 31

1979 September, the DNR Bureau of Engineering conducted a search for this corner and found a 1-3/8" inside diameter iron pipe up 0.3 ft. on a north-south fence. Searched for, but did not find evidence of the government bearing trees. There is no east-west occupation at this corner. Iron pipe was found to measure:

5226.58 ft. from the southeast corner Section 31

2646.69 ft. from the north quarter corner Section 32

2644.41 ft. from a corner fence post at the east quarter corner Section $30\,$

5241.94 ft. from the intersection of roads at the northwest corner Section 31

Analysis of the available information led the DNR Bureau of Engineering to conclude that the found iron pipe marks the location of the corner. The method used to set this corner is unknown, however, its relative position with occupation and other government corners bear out its position. It should be noted that the position of the southeast corner of Section 31 has been moved since 1967.

July, the DNR Bureau of Engineering revisited this corner and found it as described in 1979. Set a 3/4" by 24" iron pipe with 2" cast iron cap inside of the found iron pipe, up 0.4 ft..

CERTIFICATE	CERTIFICATE OF LOCATION OF GOVERNMENT CORNER				
EAST QUARTER Corner of Section 31 Township 108 N, Range 11 W, 5 th. P.M.					
STATE OF MINNESOTA, County of WABASHA					
At the corner location she	own on the sketch				
On	On found a				
☐ left monu	ument as found, D la	owered monument, D removed monument (explain)			
On 7-25-89 placed a 1"x 12 1/2" IRON PIPE WITH 2" CAST IRON CAP, UP 0.1'					
SKETCH OF REFERENCE TIES					
DNR NAIL & DISC WEST SIDE 9" BITTERNUT HICKORY UP 1.0'					
NOTE: MONUMENT IS 2.5' WEST OF OLD 40.0' NORTH OF TO BANK WHITEWAT	OP LEFT : 👉				
	WOODS	WOODS WOODS			
		× *			
	WHITE	WATER RIVER ——			
		BEARINGS OBSERVED WITH COMPASS			
Statement of eyidence relative to this corner location is on back of page P. 078.00.01					
I hereby certify that this contained herein was preportion		O IOE O. IIIE OCOMOEN			
Xoull K. Jonnera	ucy //s 9-21-89	22nd day of September A.D., 19 89			
Registration No. 17005		County Récorder Geraldine Tibor			
■ Land Surveyor, □	Professional Engineer	By The Overfee Deputy			
County Surveyor	1 County Engineer	DOCUMENT NO.			

East Quarter Corner Section 31, Township 108 North, Range 11 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN Secretary of State Wabasha County Recorder and Auditor Wabasha County Highway Engineer Plainview Township Clerk

1854 The U.S. General Land Office notes in the the Secretary of State's Office show the corner marked with a post and recorded the following bearing trees:

Burr Oak 8", S. 63° W., 14 links Burr Oak 12", N. 77° E., 34 links

The government notes also show the corner l chain north of the Whitewater River.

- 1938 Airphotos from the DNR Bureau of Engineering show the corner in a thick 1954 woods, with no discernable occupation at the corner area.
- 1967 The DNR Bureau of Engineering contracted J. J. Kleinschmidt of Winona to survey the boundary of Carley State Park. In the course of this survey, an iron pipe was set at this corner. Iron is shown:

near a north-south fence 2622.32 ft. from adjoining section corners north of the Whitewater River

- 1979 September, the DNR Bureau of Engineering conducted a search for this corner and did not find the iron pipe set by Kleinschmidt. No evidence of the government bearing trees was found. Located a north-south fence and the banks of the Whitewater River. Computed the lost position for the corner and found it to measure:
 - 2613.29 ft. from adjoining section corners
 - 2.5 ft. west of the north-south fence
 - 39.5 ft. north of the north bank of the Whitewater River
 - 86.3 ft. north of the south bank of the Whitewater River

Analysis of the available information led the DNR Bureau of Engineering to conclude that the lost position should be used for the corner, based on the above distance comparisons. It should be noted that the position of the southeast corner of Section 31 has been moved since 1967.

July, the DNR Bureau of Engineering revisited this corner and found it as described in 1979. Set a 1" by $24\frac{1}{2}$ " iron pipe, down 1.0 ft., and placed a 1" by $12\frac{1}{2}$ " iron pipe with 2" cast iron cap over it, down 0.1 ft. at the lost position.

	CERTIFICATE OF LOCATION South Quarter (wabasha North Quarter Corner o	OF GOVERNMENT CORNER (a) 3/ /08N // W f Section 6 , Township 107N , Range 11W ,		
S	TATE OF MINNESOTA, County of Olmsted			
	At the corner location shown on the sketch:	Quincy Twp.		
	Drove a $5\%8$ " by 23" rod where the	ree-sided boulder (5"/7"/8" by 16" long stone stood and set the stone on the Wid monument, removed monument (explain) side.		
	On 8-14-1980 placed a Cast Iron	Monument over the rod set 11-16-1979.		
	SKETCH OF RE	FERENCE TIES		
1 -	North C.S. Disc in Corner post C.S. Disc in			
	(1/4 Cor. Sec. 6) Corner NNW 3	c.s. Disc in pp# 32981		
		N.E. 125.51		
-	Crushed rock rd. C.I.M. 2'North & I' West fence So. 6'' East fence N.			
		F.C.S. Disc in pp# 43493 S.E. 39.22		
	Statement of evidence relative to this corner loc	ation is on back of page.		
	I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. SIGNATURE Registration No. 8952	OFFICE OF THE REGISTER OF DEEDS Tree Index County of		
	▲ Land Surveyor, 🗆 Professional Engineer	By		
	🛮 County Surveyor, 🗀 County Engineer	2000 17 Done 564		

(a) 10 0 0 a

9-25-1853

Government Notes John Ball, Deputy Surveyor West between sections 6 and 31.

40.00 chs.

Set post for quarter section corner. Burr Oak 12 in. Sl2½°W 254 lks. and dug

trench per instructions.

79.20 chs. To township corner.

Found no other records of this corner.

11-16-1979

The County Surveyor dug in line with the fence south and in the center of the road. Found a three-sided greenish boulder (5"/7"/8" by 16" long and coming to a point) standing $1\frac{1}{2}$ deep with its base in clay. Drove a 5/8"x23" rod where the stone stood and set the stone on the West side of the rod.

11-19-1979

The County Surveyor dug again to cover a corner location at prorated government measure from the N. W. Cor. Sec. 6 to the fence line north at the N.E. Cor. Sec. 6. This location came approximately 12' East of the stone found. Found nothing further. Traversed to the fence corner at the S. $\frac{1}{4}$ Cor. Sec. 6 and the fence corner at the Center Section 6 and found the fence line on the N-S quarter line of Sec. 6 to agree with the stone found at the N. $\frac{1}{4}$ Cor. Sec. 6.

8-14-1980

The County Surveyor accepted the location of the stone found 11-16-1979 as the corner location and set a Cast Iron Monument over the iron set 11-16-1979. This corner fits the lines of occupation-the fence line South and the center of the E-W road, and our traverse in Section 6 shows that it is probably the corner used to subdivide Section 6.

Snnk 17	D-2562
Index No	

OF GOVERNMENT CORNER) 3/-32 /08 N // W of Sections 5-6 , Township 107 N , Range 11 W ,				
Quincy Twp.				
dario, inp.				
At the corner location shown on the sketch: On 11-15&16-1969nd a 1" pipe at the road surface. Dug and found a 3' diameter spot where someone else had dug. Found nothing further. □ left monument as found, □ lowered monument, □ removed monument (explain) pipe to dig				
Monument over a $\frac{1}{2}$ " iron as the corner the N. $\frac{1}{4}$ Cor. 5 and in line with the fend				
EFERENCE TIES Nor				
North Sec. Cor. 6-5				
Crushed Rock Road (rushed Rock Road				
Out Port 22995 S.E. 47.63				
cation is on back of page.				
OFFICE OF THE REGISTER OF DEEDS County of				

Statement of Evidence: COMMON COR. SEC'S 31-32 - 108-11

9-25-1853 Gov

Government Notes John Ball, Deputy Surveyor

West between sections 5 and 32.

80.00 chs. Set post and drove charred stake for corner to sections 5,6,31, and 32. Built mound with trench per instructions. Planted S.E. Osage Orange seed, N.E. apple seed.

10-1853

Government Notes William A. Jones, Deputy Surveyor South 26' East on true line between sections 5 and 6. 40.29 chs. Set a quarter section post in mound of earth and sod, deposited charcoal. Made a trench and pits. Planted Osage Orange seed E. & W. of trench.

5-1967

Kleinschmidt and Webber set a 1" by 30" pipe as the corner.

1979

The DNR found the pipe set by Kleinschmidt and Webber .5' West of the fence line North, 1.0' North of the centerline of the East-West road and 2.5' West of the centerline of the road South.

11-15&16-1979

The County Surveyor found the pipe set by Kleinschmidt and Weber. The fence North is now gone. Removed the pipe to dig. Dug over a large area with the backhoe. Found only a 3' diameter area in the center of the intersection and appx. beneath the pipe where someone had dug into clay -these diggings being entirely beneath a road found 2' beneath the present road. The conditions here were very poor with no black dirt remaining on the clay.

8-14-1980

The County Surveyor set a Cast Iron Monument over a $\frac{1}{2}$ " rod as the corner on line from the N. $\frac{1}{4}$ Cor. 6 (found this survey) to the N. $\frac{1}{4}$ Cor. 5 (set this survey) and in line with the fence North as recorded by the DNR in 1979. Measured 2657.55 South to $\frac{1}{4}$ Cor. 5-6 (found this survey). This corner 10.61 North and .5 East of Kleinschmidt and Webber location.

The corner location was chosen E-W to hold the former line of occupation North--the fence North, and was chosen N-S since it brings the measure South to $\frac{1}{4}$ Cor. 5-6 just 1.59 short of the recorded Government measure. The Government measurements in this area have been fairly accurate and the land from $\frac{1}{4}$ Cor. 5-6 to the N. Sec. Cor. 5-6 is very level, so the measure here should be very close to that of the Public Land Survey. The corner as set brings the fence corner at the 1/16th North very near $\frac{1}{4}$ the measure to the N.W. Cor. 32 as set by Kleinschmidt and Webber, Inc., Winona, Mn. and very near the line to the N-S fence in the area of $\frac{1}{4}$ Cor. 31-32

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
Common North Section Corner of	of Section s 5–6 , Township <u>107N</u> , Range <u>11W</u> ,
STATE OF MINNESOTA, County of Olmsted	Quincy Twp.
At the corner location shown on the sketch:	,
3' diameter spot where someone ☐ left monument as found, ☐ lower On 8-14-1980 placed a Cast Iron	t the road surface. Dug and found a else had dug. Found nothing further. ed monument, I removed monument (explain) pipe to dig i Monument over a ½ iron as the corner the N. ½ Cor. 5 and in line with the features.
	EFERENCE TIES
North Sec. Cor. 6-5	R Spike in telephone pole North 24.95
Crushed Rock Road	and 2' West & road South
	PR C.S. Disc in pp # 32995 S.E. 47.63
Statement of evidence relative to this corner loc	cation is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. SIGNATURE Registration No. 8952	OFFICE OF THE REGISTER OF DEEDS County of I hereby certify that this document was filed in the Reg. of Deeds office atM. on the day of A.D., 19 Register of Deeds

9-25-1853

Government Notes John Ball, Deputy Surveyor

West between sections 5 and 32.

Set post and drove charred stake for corner 80.00 chs. to sections 5,6,31, and 32. Built mound with trench per instructions. Planted S.E. Osage Orange seed, N.E. apple seed.

10-1853

Government Notes William A. Jones, Deputy Surveyor South 26' East on true line between sections 5 and 6. 40.29 chs. Set a quarter section post in mound of earth and sod. deposited charcoal. Made a trench and pits. Planted Osage Orange seed E. & W. of trench.

5-1967

Kleinschmidt and Webber set a 1" by 30" pipe as the corner.

1979

The DNR found the pipe set by Kleinschmidt and Webber .5' West of the fence line North, 1.0' North of the centerline of the East-West road and 2.5' West of the centerline of the road South.

11-15&16-1979

The County Surveyor found the pipe set by Kleinschmidt and Weber. The fence North is now gone. Removed the pipe to dig. Dug over a large area with the backhoe. Found only a 3' diameter area in the center of the intersection and appx. beneath the pipe where someone had dug into clay -these diggings being entirely beneath a road found 2' beneath the present road. The conditions here were very poor with no black dirt remaining on the clay.

8-14-1980

The County Surveyor set a Cast Iron Monument over a 2" rod as the corner on line from the N. $\frac{1}{4}$ Cor. 6 (found this survey) to the N. $\frac{1}{4}$ Cor. 5 (set this survey) and in line with the fence North as recorded by the DNR in 1979. Measured 2657.55 South to $\frac{1}{4}$ Cor. 5-6 (found this survey). This corner 10.61 North and .5 East of Kleinschmidt and Webber location.

The corner location was chosen E-W to hold the former line of occupation North--the fence North, and was chosen N-S since it brings the measure South to $\frac{1}{4}$ Cor. 5-6 just 1.59 short of the recorded Government measure. Government measurements in this area have been fairly accurate and the land from $\frac{1}{4}$ Cor. 5-6 to the N. Sec. Cor. 5-6 is very level so the measure here should be very close to that of the Public Land Survey. The corner as set brings the fence corner at the 1/16th North very near 1 the measure to the N.W. Cor. 32 as set by Kleinschmidt and Webber, Inc., Winona, Mn. and very near the line to the N-S fence in the area of 2 Cor. 31-32

Index No			
	Inday	Nia	

CERTIFICATE OF LOCATION				
	of Section <u>5</u> , Township <u>107N</u> , Range <u>11W</u>			
STATE OF MINNESOTA, County of Olmsted	Quincy Twp.			
At the corner location shown on the sketch:				
Date bedrock.	hub 6' deep and in old road on			
	ed monument, \square removed monument (explain)			
On 8-14-1980 placed a Cast Iron location of the hub found 7-1	Monument over a $\frac{1}{2}$ "xl8" rod at the 0-1980.			
SKETCH OF RE	EFERENCE TIES			
1				
Punch mark in North end 36" culvert WNW 101.53	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			
M	crushed rock rd.			
M crushed rock rd.				
M M	cest Iron Monument 4½ South & rd. 2' North & rd. 2' W & N-5 rd.			
O C.S. Disc in power pole # 12896 S.W. 77.02	C.S. Dise in transmission power pole S.E. 60.58			
Statement of evidence relative to this corner location is on back of page.				
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. SIGNATURE Registration No8952	OFFICE OF THE REGISTER OF DEEDS County of I hereby certify that this document was filed in the Reg. of Deeds office atM. on the day of A.D., 19 Register of Deeds			
✓ Land Surveyor, ☐ Professional Engineer	By,Deputy			
☑ County Surveyor, □ County Engineer	DOCUMENT NO.			

- 9-25-1853 Government Notes John Ball, Deputy Surveyor
 West between sections 5 and 32.
 40.00 chs. Set post for quarter section corner.
 Burr Oak 6 in. S3°E 40 lks.
 Burr Oak 8 in. N7°E 232 lks.
- 10-14-1921 The C.H.D. (C.H.D. Book 36 Page 1) set a hub at "Intersection of E&W and N&S roads midway between fence lines which are well defined."
- 11-25-1944 The C.H.D. (C.H.D. Book 168 Page 31) records a hub as the corner.
- DNR found a spike in centerline N-S road, 2' North of the centerline of the road West and 4' South of the centerline of the road East.
- 1979 The County Surveyor's Dept. found spike recorded by the DNR.
- 1-1980 Kleinschmidt and Webber Inc. found monument (no description).
 Used corner for a survey in Section 32.
- 7-10-1980 The County Surveyor found a $\frac{1}{2}$ "by 3" pipe at the location of the spike found in 1979. Dug with backhoe. In a road appx. $3\frac{1}{2}$ ' deep found a 1"x2" hub 2.45 West and 1.35 North of the $\frac{1}{2}$ " pipe location and a 1"x2" hub with a 120d spike beside it 2.3 West of the $\frac{1}{2}$ " pipe location. Dug further and in an old road 6' deep found a 1"x2" hub 2.3 West and .1 South of the $\frac{1}{2}$ " pipe location. This road was on bedrock and we found nothing further.
- The County Surveyor set a Cast Iron Monument over a ½"xl8" rod as the corner at the location of the 1"x2" hub found 6' deep on 7-10-1980. We believe this hub is the corner set here by the C.H.D. in 1921. The 1921 and 1944 C.H.D. topography shows that this corner fit closely a fence West on the South side of a former school property in the N.E. corner of the N.W. ½ Sec. 5 and a fence West near a former property line South of the 1/16th South.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER				
NORTH QUARTER Corner of Section 32 , Township 108 N , Range 11 W , 5 th. P.M.				
STATE OF MINNESOTA, County of WABAS	HA			
At the corner location shown on the sketch				
On found a				
☐ left monument as found, ☐ lowe	red monument, D removed monument (explain)			
☑ On 7 - 26 - 89 placed a 3/4" x 6"	RON ROD, DOWN 0.3'			
	REFERENCE TIES			
NOTE: MONUMENT IS: ON & N - S ROAD N- IN LINE WITH FENCE EAST				
GOOD TIES NOT AVAILABLE				
M O O D 2				
N 89°53' 42" E	N89°46'44"E			
NW CORNER SECTION 32	2629.06' NE CORNER SECTION 32			
CO. RD. 4				
BEARINGS ARE ASSUMED ORIENTATION				
Statement of evidence relative to this corner location is on back of page J.B.M. 9-18-89 P. 078-00.01				
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision Could R. Communating A. 9-21-89	OFFICE OF THE COUNTY RECORDER County of WABASHA I hereby certify that this document was filed in the Co. Recorders office at M. on the 22nd day of September A.D., 19 89			
Registration No. 17005 Land Surveyor, Professional Engineer	County Recorder Geraldine Tibor By Auf Talke Deputy			
County Surveyor County Engineer	DOCUMENT NO.			

Michael 1105 (4 77)

North Quarter Corner Section 32, Township 108 North, Range 11 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN Secretary of State Wabasha County Recorder and Auditor Wabasha County Highway Engineer Plainview Township Clerk

1854 The U.S. General Land Office notes in the the Secretary of State's Office show the corner marked with a post and recorded the following bearing trees:

Burr Oak 10", N. 82° W., 55 links Burr Oak 10", S. 5° W., 87 links

- Book A of Records of Town Plats, on page 60, obtained from the Plainview Township Clerk, contains a road survey by H. W. McDougull, County Surveyor. Survey shows a section of north-south road going through this quarter post.
- Airphotos from the DNR Bureau of Engineering show occupation lines 1954 north-south and east, the latter photo showing a north-south road.
- May, the DNR Bureau of Engineering contacted area resident, Herb Spranger, approximately 70 years old, for testimony regarding this corner. Mr. Spranger has lived in this area since 1938 and stated he rebuilt the existing fence lines in the same place as the old ones. Mr. Spranger had no knowledge of surveys in this area, but though the north-south road was on the quarter line.
- 1979 September, the DNR Bureau of Engineering conducted a search for this corner and located the intersection of a north-south paved road and fence line east. Searched for, but found no evidence of the government bearing trees. The corner area is in a fill section of road of 8 ft., more or less. The above mentioned intersection was found to measure:

2646.69 ft. from the northwest corner Section 32 2629.06 ft. from the northeast corner Section 32

Analysis of the available information led the DNR Bureau of Engineering to conclude that the intersection of occupation, road and fence line, marks the location of the corner. Did not dig for this corner as no resurvey information indicates a monument subsequent to the GLO survey and because of the 8 ft. of road fill.

July, the DNR Bureau of Engineering revisited this corner and found it as described in 1979. Set a 3/4" by 6" iron rod at the above mentioned intersection of occupation. Spoke with David Johnson, Wabasha County Surveyor, who stated this road would be overlayed shortly and a county monument would then be set at this location.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTHEAST Corner of Section 3	2 ,Township 108 N , Range 11 W , 5 th. P.M.	
STATE OF MINNESOTA, County ofWABAS	H A	
At the corner location shown on the sketch		
On found a		
•	ed monument, D removed monument (explain)	
Ø On 7-25-89 placed a 1" x 25" R PATE UP 0.2'	ON PIPE WITH 2" CAST IRON CAP,	
·	EFERENCE TIES	
NOTE: MONUMENT IS 12.0' SOUTH OF & DRY WASH IN LINE WITH FENCE N-S-W WOODS	DNR NAIL & DISC WEST SIDE II" BUR OAK UP 3.2' N15°E 21.24'	
DRY WASH	W A S H	
	33.0' 0 W O O D S	
SOUTH SIDE 10" WHITE OAK UP 1.0'	DNR NAIL & DISC EAST SIDE 12" RED OAK UP 1.0' BEARINGS OBSERVED WITH COMPASS	
Statement of evidence relative to this corner location is on back of page J.B.M. 9-15-89 P.078.00.01		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision Nouell R. Communating 19-21-89	OFFICE OF THE COUNTY RECORDER County of WABASHA I hereby certify that this document was filed in the Co. Recorders office at 4:00 PM. on the 22nd day of September A.D., 1989	
Registration No. 17005	County Recorder Geraldine Tibor	
Land Surveyor, Professional Engineer	DOCUMENT NO	
□ County Surveyor □ County Engineer		

Northeast Corner Section 32, Township 108 North, Range 11 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN Secretary of State Wabasha County Recorder and Auditor Wabasha County Highway Engineer Plainview Township Clerk

1854 The U.S. General Land Office notes in the the Secretary of State's Office show the corner marked with a post and recorded the following bearing trees:

Burr Oak 8", S. 49° W., 230 links Burr Oak 12", N. 32° W., 160 links Burr Oak 10", N. 74° E., 130 links Burr Oak 9", S. 71° E., 225 links

- 1938 Airphotos from the DNR Bureau of Engineering show occupation lines 1954 east-west and north, originating from a wooded area.
- May, the DNR Bureau of Engineering contacted area resident Herb Spranger, approximately 70 years old, for testimony regarding this corner. Mr. Spranger has lived in this area since 1938, and stated he rebuilt the existing fence lines in the same place as the old ones. He said an old timer (now deceased) told him there was a stone buried at this corner. The fence intersection would be real close to where the stone should be. Mr. Spranger had no knowledge of surveys in this area.
- 1979 September, the DNR Bureau of Engineering conducted a search for this corner and found a corner fence post with fences north-south and west. Searched for, but found no evidence of the government bearing trees. The corner falls in a ravine with many stones around it, unable to distinguish one from the other. Corner fence post measures:

2602.93 ft. from the east quarter corner Section 32 2629.06 ft. from the north quarter corner Section 32 2637.45 ft. from a corner fence post to the north

Analysis of the available information led the DNR Bureau of Engineering to conclude that the corner fence post marks the location of the corner per testimony.

July, the DNR Bureau of Engineering revisited this corner and found it as described in 1979. Set a 1" by 25" iron pipe with a 2" cast iron cap up 0.2 ft. at the intersection of above mentioned fences. Area resident, Paul Schmidt, was present when monument was set and confirmed its location.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER				
EAST QUARTER Corner of Section 32	Township 108 N , Range 11 W , 5 th. P.M.			
STATE OF MINNESOTA, County of WABASHA				
At the corner location shown on the sketch				
On found a				
	onument, 🗆 removed monument (explain)			
Ø On 7-26-89 placed a 3/4" x 12" IRO On 10	N PIPE WITH 2" CAST IRON CAP,			
SKETCH OF REFEI	RENCE TIES			
Ĭ Š				
	· N 05 E · 79.37 '			
Î ×	DNR NAIL & DISC EAST SIDE 26" RED OAK			
NOTE: MONUMENT IS 0.3' WNW OF BASE OF WOOD POST ON N-S FENCE				
EAST P	ASTURE			
S 74°W				
PASTURE	S87E DNR NAIL & DISC			
DNR NAIL & DISC SOUTH SIDE 30" RED OAK UP 1.0'	57.75' NORTH SIDE 24" WHITE OAK, UP 1.0'			
BEARINGS OBSERVED WITH COMPASS				
Statement of evidence relative to this corner location	n is on bock of page P. 078.00.01			
I hereby certify that this document and the data contained herein was prepared by me or under County of WABASHA				
1he	co. Recorders office at $\frac{4:00}{1}$ P.M. on the day of September A.D., 1989			
Registration No. 17005 Cou Land Surveyor, Professional Engineer By	Auf Geraldine Tibor Auf Deputy			
· ·	CUMENT NO.			

East Quarter Corner Section 32, Township 108 North, Range 11 West

The DNR Bureau of Engineering contacted the following offices for information on this corner:

MN Secretary of State Wabasha County Recorder and Auditor Wabasha County Highway Engineer Plainview Township Clerk

1854 The U.S. General Land Office notes in the the Secretary of State's Office show the corner marked with a post and recorded the following bearing trees:

Burr Oak 12", N. 55° E., 141 links Burr Oak 8", N. 2° W., 285 links

The government notes also show the corner 12.10 chains south of the Whitewater River.

- 1938 Airphotos from the DNR Bureau of Engineering show a north-south occupation
- 1954 line at the corner area.
- May, the DNR Bureau of Engineering contacted area resident, Laverne Walch, approximately 55 years old, for testimony regarding this corner. Mr. Walch stated his wife grew up in the southwest quarter of Section 33 and they have owned it for years. He said there should be an old fence corner at this corner, the old fence to the east had fallen down years ago.
- 1979 September, the DNR Bureau of Engineering conducted a search for this corner and found an old corner fence post with fences north-south and a down fence east. Searched for evidence of the government bearing trees and located a 23" diameter bur oak to the north, 178.17 ft. from the corner fence post. Took an increment bore of this tree and found it was not old enough to be a bearing tree. The corner fence post measures:

2602.93 ft. from the northeast corner Section 32

2637.02 ft. from the southeast corner Section 32

803 ft. from the north bank of the Whitewater River

739 ft. from the south bank of the Whitewater River

Analysis of the available information led the DNR Bureau of Engineering to conclude that the corner fence post marks the location of the corner per testimony.

July, the DNR Bureau of Engineering revisited this corner and found it as described in 1979. Set a 3/4" by 24½" iron pipe down 1.0 ft. and placed a 3/4" by 12" iron pipe with 2" cast iron cap up 0.3 ft. at the base of the corner fence post. Corner fence post is leaning slightly, monument being placed at its plumb position.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER					
South Quarter Corner of Section 32	,Township <u>108</u> ,Range <u>11</u> , <u>5th</u> P.M.				
STATE OF MINNESOTA, County of Wabasha					
At the corner location shown on the sketch:					
☑ On April 26, 1989ound a Cast iron mo	nument				
	ed monument, 🗆 removed monument (explain)				
☐ Onplaced a					
SKETCH OF R	EFERENCE TIES				
	· · · · · · · · · · · · · · · · · · ·				
4	·				
-N-					
2					
ó l					
U 61 / WAB. Co. Sign					
WAB. Co. Sign					
-i of 52					
7.	25.67 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
<i>∞</i>	fence line				
spike + disk s.E.	spike N.E. side cut off Power Pole up				
side Power Pole	3.5't				
	9.3 %				
Statement of evidence relative to this corner location is on back of page.					
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS County of WABASHA				
my direct supervision.	I hereby certify that this document was filed in				
Davy A. Jomen 7/28/89	the Reg. of Deeds office at 11:55 A.M. on the 1st day of August A.D., 19 ⁸⁹				
Registration No. 12788	Register of Deeds Geraldine Tibor				
Land Surveyor, 🗆 Professional Engineer	By Tay Stacke, Deputy				
☐ County Surveyor, ☐ County Engineer	DOCUMÉNT NO				

SOUTH QUARTER CORNER OF SECTION 32, TOWNSHIP 108, RANGE 11

April 26, 1989

Wabasha County Surveyors Office, visited the corner set by Olmstead County Surveyors Office, and new ties were pulled. See Olmstead County Surveyors records for more details.

	CE	RTIFICAT South G North Que	E OF Luarter (warter	OCATION Labasha C Corner	NOF G of Section	SOVERNMEN 32 5, Township_1	CORNER 1081 / W 071, Range 11W ,
S7	ATE OF	F MINNESOTA,				Quin cy T	
	At the	corner location	shown on the	sketch:			
	3	bedrock.			·····	deep and in ol	
	团	On 8-14-19 DATE location	M80 placed a of the hu	<u>Cast Iro</u>	n Monum	nent over a ½"xl	8" rod at the
				SKETCH OF	REFEREN	CE TIES	
	→ <u>→</u>	1	rt		Wab. Co. Rd. 4 (bit. surface)	North 1/4 Cor. Sec. 5	ed rock rd.
	<u> </u>	1				cest Iron Monumo	nt 4½ South & rd. E 2' North & rd. W 2' W & N-5 rd.
	,		O C.S.D.s. pole # S.W. 11.		Olm. Co. Rd. 10 (bit. sur Face)	f	S. Dise in transmission ower pole S.E. 60.58 Recognize somework
	State	ment of eviden	ce relative to	this corner	ocation is	s on back of page.	7
	contai my di Regist	by certify that ned herein was rect supervision No Land Surveyor.	prepared by on. 8952 Professi	me or under DATE Onal Engineer	County I hereb the Reg Registe By	E OF THE REGISTER of Wabank by certify that this do i, of Deeds office at _ day of er of Deeds MENT NO	cument was filed in

9-25-1853 Government Notes John Ball, Deputy Surveyor
West between sections 5 and 32.
40.00 chs. Set post for quarter section corner.
Burr Oak 6 in. S3°E 40 lks.
Burr Oak 8 in. N7°E 232 lks.

well defined."

- 10-14-1921 The C.H.D. (C.H.D. Book 36 Page 1) set a hub at "Intersection of E&W and N&S roads midway between fence lines which are
- 11-25-1944 The C.H.D. (C.H.D. Book 168 Page 31) records a hub as the corner.
- DNR found a spike in centerline N-S road, 2' North of the centerline of the road West and 4' South of the centerline of the road East.
- 1979 The County Surveyor's Dept. found spike recorded by the DNR.
- 1-1980 Kleinschmidt and Webber Inc. found monument (no description).
 Used corner for a survey in Section 32.
- 7-10-1980 The County Surveyor found a $\frac{1}{2}$ "by 3" pipe at the location of the spike found in 1979. Dug with backhoe. In a road appx. $3\frac{1}{2}$ ' deep found a 1"x2" hub 2.45 West and 1.35 North of the $\frac{1}{2}$ " pipe location and a 1"x2" hub with a 120d spike beside it 2.3 West of the $\frac{1}{2}$ " pipe location. Dug further and in an old road 6' deep found a 1"x2" hub 2.3 West and .1 South of the $\frac{1}{2}$ " pipe location. This road was on bedrock and we found nothing further.
- The County Surveyor set a Cast Iron Monument over a ½"x18" rod as the corner at the location of the 1"x2" hub found 6' deep on 7-10-1980. We believe this hub is the corner set here by the C.H.D. in 1921. The 1921 and 1944 C.H.D. topography shows that this corner fit closely a fence West on the South side of a former school property in the N.E. corner of the N.W. ½ Sec. 5 and a fence West near a former property line South of the 1/16th South.

Index	Nο	

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
Common North Section Corner o	f Section s 4-5, Township 107N, Range 11W,
STATE OF MINNESOTA, County of Olmsted	Quincy Twp.
At the corner location shown on the sketch:	
fences North and East. Found left monument as found, lowere	he backhoe over large area in line wit mark where an old post had stood. ed monument, removed monument (explain)
On 8-14-1980 placed a C.I.M. ov midway and on line between t	er a $\frac{1}{2}$ "x19" iron as the corner the N. $\frac{1}{4}$ Cor. 4 and the N. $\frac{1}{4}$ Cor. 5.
Crashed Rock Rd.	Cast Iron Monument in line with road West and 9' SF'ly Center of road on curve C.S. Disc in attended to the contract of the c
Statement of evidence relative to this corner loc	cation is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. SIGNATURE Registration No. 8952	OFFICE OF THE REGISTER OF DEEDS County of I hereby certify that this document was filed in the Reg. of Deeds office atM. on the day of A.D., 19 Register of Deeds
☑ Land Surveyor, □ Professional Engineer	By,Deputy
🗗 County Surveyor, 🛘 County Engineer	DOCUMENT NO.

- 9-25-1853 Gov't Notes John Ball, Deputy Surveyor
 West between sections 4 and 33.
 80.00 chs. Set post for corner to Sections 4,5,32 & 33.
 Burr Oak 14 in. S9\frac{1}{2}\text{OW} 177 links
 Burr Oak 12 in. S4\frac{1}{2}\text{OE} 282 links
 Dug trench per instructions.
- 10-1853 Gov't Notes William A. Jones, Deputy Surveyor South 35' E. between Sections 4 and 5.
 40.25 chs. Set a quarter section post from whence a Burr Oak 10 in. diam. S84°E 150 links.

 Made trench.
- 12-1891 Thomas Fraser (Book A, B. 467, No.449), County Surveyor, states this corner "gone and obliterated."
- 11-14-1979 The County Surveyor dug over a large area with the backhoe centered over a point in line with the fence North and the fence East. Found a deep hole filled with cable ½' West of the fence line North and 2' North of the fence line East which apparently was the location of a power pole. We found the mark from a large post 1'+ in diameter with pieces of wire and ruaty nails 2½' East of the fence line North and 3' North of the fence line East.
- 1-1980 Kleinschmidt and Webber, Inc. set a monument (no description) for a survey in Section 32.
- 8-14-1980 The County Surveyor set a C.I.M. over a $\frac{1}{2}$ "x19" iron as the corner midway and on line between the N. $\frac{1}{4}$ Cor. 4 (Set in 1979-See Cert. filed) and the N. $\frac{1}{4}$ Cor. 5 (Set this survey-See Cert. filed). The corner is in line with the fence line North, the fence line East, and the centerline of the road West. When we set the monument we removed a pipe ($\frac{1}{2}$ " by 25") which stood .23 North and .32 West of the monument set.

CERTIFICATE OF LOCATION Common South Section (Wabasha Common North Section Corner of	OF GOVERNMENT CORNER 32-33 /08 N // W Section s 4-5, Township 107N, Range 11W,
STATE OF MINNESOTA, County of Olmsted	Quincy Twp.
At the corner location shown on the sketch:	
fences North and East. Found i	he backhoe over large area in line with mark where an old post had stood. d monument, removed monument (explain)
On 8-14-1980 placed a C.I.M. over midway and on line between the	er a $\frac{1}{2}$ "x19" iron as the corner he N. $\frac{1}{4}$ Cor. 4 and the N. $\frac{1}{4}$ Cor. 5.
Crashed Rock Rd.	Cast Iron Monument in line with, road West and 9' SE'ly center of road on curve C.S. Disc in gate post C.S. Disc in gate post East 40.72 North C. Cor. 5-4
Statement of evidence relative to this corner loc	cation is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Signature Signature Date Registration No. 8952 Professional Engineer County Surveyor, County Engineer	OFFICE OF THE REGISTER OF DEEDS Tract index County of

COMMON COR. SEC. 32-33-108-11

9-25-1853 Gov't Notes John Ball, Deputy Surveyor

West between sections 4 and 33.

80.00 chs. Set post for corner to Sections 4,5,32 & 33.

Burr Oak 14 in. S92°W 177 links Burr Oak 12 in. S42°E 282 links Dug trench per instructions.

10-1853 Gov't Notes William A. Jones, Deputy Surveyor

South 35' E. between Sections 4 and 5.

40.25 chs. Set a quarter section post from whence a Burr Oak 10 in. diam. S84°E 150 links.

Made trench.

12-1891 Thomas Fraser (Book A, P. 467, No.449), County Surveyor,

states this corner "gone and obliterated."

11-14-1979 The County Surveyor dug over a large area with the backhoe centered over a point in line with the fence North and the fence East. Found a deep hole filled with cable ½' West of the fence line North and 2' North of the fence line East which apparently was the location of a power pole. We found the mark from a large post l'+ in diameter with pieces of wire and rusty nails 2½' East of the fence line North and 3' North of the fence line East.

1-1980 Kleinschmidt and Webber, Inc. set a monument (no description) for a survey in Section 32.

8-14-1980 The County Surveyor set a C.I.M. over a ½"x19" iron as the corner midway and on line between the N.½ Cor. 4 (Set in 1979-See Cert. filed) and the N.½ Cor. 5 (Set this survey-See Cert. filed). The corner is in line with the fence line North, the fence line East, and the centerline of the road West. When we set the monument we removed a pipe (½" by 25") which stood .23 North and .32 West of the monument set.

CERTIFICATE OF LOCATION (OF GOVERNMENT CORNER	
North 1/4 CORNER OF SECTION 33 TOWNSHIP 108 N RANGE II W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: Y ON 8/2000 FOUND A 5" x 8" x 8" Stone Monument		
*LEFT MONUMENT AS FOUND, _ LOWERED MONUM	MENT, _ REMOVED MONUMENT (EXPLAIN)	
A ON8/2000 PLACED A Wabasha C	ounty Monument	
SKETCH OF REI	FERENCE TIES	
1 %	N= 105380.47 WAB. CO. COORD. E=530826.64 NAD 1983 ADJ. X FENCE X LINE X	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORN	NER LOCATION IS ON THE BACK OF THIS SHEET.	
HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12788 LAND SURVEYOR, PROFESSIONAL ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER	

- 1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.
- John Rafter, County Surveyor, shows a stone monument in place at the corner.
- August, 2000 Johnson & Scofield, Inc. excavated with a backhoe at the intersection of north-south Township Road with fence lines running east and west. The excavation was 7 feet by 12 feet to a depth of 2 1/2 feet. A 5 inch by 8 inch by 8 inch stone monument was found just below natural ground.

The found stone monument is believed to be the one referred to in 1918 by John Rafter and is accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and northwest corners of Section 33. A 1 inch by 18 inch iron pipe was placed at the northeast corner of the stone. A second 1 inch by 18 inch iron pipe, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top, was placed above the stone.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Northeastcorner of section_33, tow STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ONFOUND A	NSHIP 108 N ,RANGE II W ,5th P.M.		
LEFT MONUMENT AS FOUND, _ LOWERED MONUM X ON 10/2000 PLACED A Wabasha Count	ENT, _ REMOVED MONUMENT (EXPLAIN)		
SKETCH OF REF	FRENCE TIES		
FENCE LINE	N=105378.66 WAB CO COOPD E=533445.05 NAD 1983 ADJ.		
X FENCE X LINE			
FENCE			
STATEMENT OF EVIDENCE RELATIVE TO THIS CORN	NER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		
SIGNATURE DATE	THEDAY OFA.D., 20 REGISTER OF DEEDS		
LICENSE NO LAND SURVEYOR, PROFESSIONAL ENGINEER	BY, DEPUTY		
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER		

1850s During the Original Public Land Survey, the US Deputy Surveyor set a section post and made reference to 4 witness trees.

Early 1900s John Rafter, County Surveyor, found a stone monument at the corner.

October, 2000 Johnson & Scofield, Inc. probed a 10 foot diameter area to a depth of 2 feet around a 3-way fence intersection. Nothing was found. It is believed that the stone monument, referred to by John Rafter, was removed during fence constructions.

The 3-way fence intersection was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the west quarter corner and south quarter corner of Section 27 and by measurements made to the north quarter corner and east quarter corner of Section 33. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East 1/4 CORNER OF SECTION 33 TOWNSHIP 108 N , RANGE R 11 W , 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ___ ON____FOUND A _____ _ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) X ON 11/2000 PLACED A Wabasha County Monument SKETCH OF REFERENCE TIES N= 102764.26 WAB. CO. COORD. E= 533454.99 NAD 1983 ADJ. WOODS WOODS W0005 WOODS STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET. I HEREBY CERTIFY THAT THIS DOCUMENT AND THE OFFICE OF THE REGISTER OF DEEDS DATA CONTAINED HEREIN WAS PREPARED BY ME OR COUNTY OF _____ UNDER MY DIRECT SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT______.M. ON THE _____DAY OF _____A.D., 20___ 15 NOV. 2000 SIGNATURE DATE LICENSE NO. 12788 REGISTER OF DEEDS_____ _ PROFESSIONAL ENGINEER LAND SURVEYOR. DOCUMENT NUMBER _ COUNTY SURVEYOR, _ COUNTY ENGINEER

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

John Rafter, County Surveyor, indicates a stone monument at the 1/16th corner north of the east quarter corner of Section 33.

November, 2000

Johnson & Scofield, Inc. found a fence corner at the 1/16th corner north of the east quarter corner of Section 33. An area 10 feet in diameter around the fence corner was probed and hand dug to a depth of 1 foot in search of the stone monument referred to by John Rafter. Nothing was found. A position for the east quarter of Section 33 was established at a point which puts the above mentioned fence corner midway and on line between said east quarter corner of Section 33 and the northeast corner of Section 33. A 20 foot diameter area was probed and hand dug to a depth of 1 foot and nothing was found. An area 10 feet in diameter, at the lost position, was also hand probed and dug to a depth of 1 foot and nothing was found.

The position, which puts the above mentioned fence corner at a point midway and on line between the east quarter corner of Section 33 and the northeast corner of Section 33, was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 33. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION C	OF GOVERNMENT CORNER
Southeast corner of Section 33 Town	NSHIP 108 N RANGE II W 5th P.M.
STATE OF MINNESOTA, COUNTY OF Wabasha.	
AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 Established A Wabash:	a County Coordinate NAD
1983 AdJ. Using Information Sho	wn on A Survey By the D.N.R.
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUM	ENT, _ REMOVED MONUMENT (EXPLAIN)
ONPLACED A	
SKETCH OF REF	ERENCE TIES
Ť	
7 N N N N N N N N N N N N N N N N N N N	
- <u>-</u> -	
FE NCE	
<u>u</u>	
1	
	Y TENCE X LINE X
	N=100121.75 WAB. CO. COORD.
ļ	E= 533465.03 NAD 1983 ADJ.
· • • • • • • • • • • • • • • • • • • •	
_	
1	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORN	NER LOCATION IS ON THE BACK OF THIS SHEET.
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	COUNTY OF
() UNTIA. AMEM 15Nov. 2000	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON
SIGNATURE DATE	THEDAY OFA.D., 20
LICENSE NO. 12788	REGISTER OF DEEDS
LAND SURVEYOR, _ PROFESSIONAL ENGINEER	BY DEPUTY
COUNTY SURVEYOR COUNTY ENGINEER	DOCUMENT NUMBER
- AAALLI AALLIAM - AAALLI EHAMEEL	

٠.

.....

SW COR SEC 34 SE COR SEC 33

	•		2/4 00/2 200
	Cert	rificate of Location of Government Corner	SE COR SEC 33
(D #: 8134	405		
Elevation	:	Description: NORTH SEC COR 3-4	County: Olmsted
Corner T	itle:	Section: 34	Township: 107N
Range: 11	ıw	Principle Meridian:	Date Set:
Monumei	nt Description:		
CIC/p2			
Reference	e Ties:		
Spike and	CSD on E side blazed 7" Burr O CSD S side blazed 14" Black O CSD W side blazed 24 Black O		
Corner H	listory:		
9-1853	Gov't Notes: Set post and dro	ve charred stake, built mound with trench.	
cor betwe between l place. Al	ling plain. 1/16 cor south set staken 3-4 a stake reset by B trees. 1 N 1/4 4 and center found stone and	4) Geo Wedge found fence post set by Mr. A Ferrier is on line and prop dist line overran 56 1/4 lks meas fr /16 center NE 1/4 4 set stake M&L 20.16-1/4 on EW d stake set by Mr. Basturck a surveyor from Wabasha in 4. Accepted stone and stake as corner for work at h	om corner S 20.25 then 20.28-1/4 to 1/6 line. 1/16 cor on N-S 1/4 line. County set years ago when corners in
	7 County Surveyor accepted the ner post to fences N and east.	e comer post as per Tom Fraser survey No.449. Set a	CIC/p2 as the corner on the SE side
I her	eby certify that this document	and the data contained herein was prepared by me	or under my direct supervision.
		Signature Olmsted County Surveyor	Date
			•

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
South 1/4 CORNER OF SECTION 33 TOWNSHIP 108 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 Established A Wabasha County Coordinate, NAD 1983 AdJ. Using Information Shown on A Survey By the D.N.R. LEFT MONUMENT AS FOUND, LOWERED MONUMENT, REMOVED MONUMENT (EXPLAIN)		
ONPLACED A		
SKETCH OF REFERENCE TIES		
X X		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
OFFICE OF THE REGISTER OF DEEDS COUNTY OF UNDER MY DIRECT SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE AT		

S14 COR SEC 33

Certificate of Location of Government Corner

ID#: \$13304	(FROM OLMSTED COUNTY)	
Elevation:	Description: NORTH 1/4 SEC COR 4 71	County: Olmsted
Corner Title:	Section: 33	Township: 107N
Range: 11W	Principle Meridian:	Date Set: 11/29/79
Monument Description:		
Cast iron cap on a square pipe o	ver 1" square x 35" pipe.	
Reference Ties:		
Monument is 2.5' NNW of corne	er postSurvey marker sign on corner post to fences N-S-W.	
Corner History:		
	n Ball, Deputy Surveyor West between sections 4 and 33, 40, 87 lks. Black Oak 10 N4°W 266 lks.	0.00 chs. Set post for quarter section
12-1891Thomas Fraser, County	Surveyor, (Book A, Page 467, No. 449) states that this corn	ner was gone and obliterated.
then found a 21/2" square mark	or dug at the corner of fences N-S-E. Found a 6" square marriage from another $1/2$ " + and tapering to a point. We dr st standing $21/2$ " NNW of the present corner post.	rk in clay which we scraped down 1/2' and rove a 1" square by 35" pipe in the mark.
11-29-1979 The County Survey	or set a Cast Iron Cap on a square pipe driven over the pipe	set 11-20-1979.
I hereby certify that this o	document and the data contained herein was prepared by	y me or under my direct supervision.
	Signature Olmsted County Surveyor	Date
	~	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
North 14 corner of section 34 township 108 N range 11 W 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: ON FOUND A			
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) X ON 1/2000 PLACED A _ Wabasha County Monument			
SKETCH OF RE	FERENCE TIES		
NO OCCUPATIO	n lines		
FIEL	N= 105317.98 WAB. CO. COORD. E= 536064.94 NAD. 1983 ADJ.		
*(E)	* KA		
FIE	LD		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORI	NER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE DATE LICENSE NO. 1778 LAND SURVEYOR, PROFESSIONAL ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		
COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER		

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

Early 1900s John Rafter, County Surveyor, established the corner midway between the northeast corner and northwest corner of Section 34. He does not indicate what type of monument, if any, was placed.

November, 2000 Johnson & Scofield, Inc. set the corner using lost methods, as did John Rafter in the early 1900s. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Northcast CORNER OF SECTION 34 TOWNSHIP 108 N RANGE 11 W 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A 1" Iron Shaft And A 5"X 7"X 8" Pointed Stone Monument Removed Iron Shaft And Lowered Stone LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN) X ON 8/2000 PLACED A Wabasha County Monument			
SKETCH OF REFE	ERENCE TIES		
·			
ROAD			
4	No. 10505720		
	N= 105257.30 WAB. CO. COORD. E= 538684.82 NAD 1983 ADJ.		
Found I" Iron Shaft			
	X FENCE X LINE X-		
1.38			
1142 171			
1 7 4			
TOWN			
	1		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.			
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS		
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	COUNTY OF		
L HERERY CERTIFY THAT THIS DOCUMENT WAS FILED			
SIGNATURE DATE	IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20		
LICENSE NO. 12788	REGISTER OF DEEDS		
	BY DEPUTY		
_ LAND SURVEYOR, _ PROFESSIONAL ENGINEER			
COUNTY SURVEYOR,COUNTY ENGINEER	DOCUMENT NUMBER		

During the Original Public Land Survey, the US Deputy
Surveyor set a section post and made reference to 4 witness
trees

John Rafter, County Surveyor, indicates a stone monument in place at the corner.

March, 1997 Vince Fangman found a 1 inch iron shaft at the corner.

August, 2000 Johnson & Scofield, Inc. found the same 1 inch iron shaft, as found by Vince Fangman in 1997. The found iron shaft was at the intersection of the centerline of a north-south Township Road and a fence line running east. A 6 foot by 12 foot by 3 feet deep excavation was made with a backhoe at the location of the found 1 inch iron shaft. A 5 inch by 7 inch by 8 inch pointed stone monument was found at a depth of 1 foot. The stone monument was 1.38 feet southeasterly of the 1 inch iron shaft.

The found stone monument is believed to be the stone monument referred to by John Rafter in 1918 and was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the west quarter corner and south quarter corner of Section 26 and measurements made to the north quarter corner and east quarter corner of Section 34. The stone monument was lower and a 1 inch by 18 inch iron pipe was placed on the west side. A second 1 inch by 18 inch iron pipe, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top, was placed above the stone.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
East 1/4 corner of section 34 township 108 N _range 11 W _5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: \(\text{\formula 0} \frac{\beta/2000}{2000} \) FOUND A 1" \(\text{\formula 0} \) Bolt			
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUM	MENT, AREMOVED MONUMENT (EXPLAIN)		
X ON8/2000 PLACED A Wabasha Co	unty Monument		
SKETCH OF REI	FERENCE TIES		
TOWNSHIP	N=102623.68 WAB. CO. COOKD. E=538699.83 NAD. 1983 RDJ. TOWNSHIP ROAD CENTERLINE		
STATEMENT OF EVIDENCE RELATIVE TO THIS COR	NER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. WWW. Was prepared by ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE DATE LICENSE NO. 12788	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		
LAND SURVEYOR, _ PROFESSIONAL ENGINEER BY DEPUTY COUNTY SURVEYOR, _ COUNTY ENGINEER DOCUMENT NUMBER			

- 1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.
- 1918 John Rafter, County Surveyor, indicates a stone monument at the corner.
- August, 2000 Johnson & Scofield, Inc. talked with Ben Marshman, a land owner in the area. He said that his father, Herb, was on the town board during the 1960s and remembers them digging up a stone and lowering it during a survey for a nearby dike. He also said the road has not been regraded since that time. We also talked with Bob Marshman, a land owner in the area, who thinks the stone is near the west edge of the gravel. We also asked him about a fence line running west. He said that the fence line was not on the land line.

An excavation was made for the stone monument, referred by John Rafter, at the intersection of the centerline of a north-south township road with the centerline of a township road running east. The excavation was 20 feet by 18 feet to a depth of 4 feet and extended 4 feet west of the west shoulder of the north-south township road. A 1 inch by 6 inch bolt was found at a depth of 2 feet. The stone monument, indicated by John Rafter, was not recovered. It was determined that the stone monument must have been removed.

The 1 inch by 6 inch bolt was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and southeast corners of Section 34. Two 1 inch by 18 inch iron pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
Southeast corner of section 34 Township 108 N RANGE II W 5th P.M.			
STATE OF MINNESOTA, COUNTY OF Wabasha.			
AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 Established a Wabasha	County Coordinate NAD 1483		
Ads. , USING INFORMATION ShowR or _ LEFT MONUMENT AS FOUND, _ LOWERED MONUM	a syrvey By the D.N.R.		
_ ELT MOROMENT AS TOORS, _ LONEALES MOROM	ILIET, _ ILLMOYED MORUMERT (EXILENT)		
ONPLACED A			
SKETCH OF REF	TERENCE TIES		
1			
N N N N N N N N N N N N N N N N N N N			
DHIPSINA			
	ROAD		
	N=100019.62 WAB. CO. C. ORD. E= 538698.63 NAD. 1983 ADJ.		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORI	VER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS		
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	COUNTY OF		
1 Savid A. mom 15 Nov. 2000	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20		
SIGNATURE DATE	THEDAY OFA.D., 20		
LICENSE NO. 12788	REGISTER OF DEEDS		
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY DEPUTY		
_ COUNTY SURVEYOR, _ COUNTY ENGINEER	DOCUMENT NUMBER		

SW COR SEC 35 SE COR SEC 34

Certificate of Location of Government Corner (FROM OLMSTED COUNTY)

ID4. 912505	(FROM OLMSTE	P COUNTY)	
ID#: \$13505			
Elevation:	Description: NORTH SE	EC COR 2-3	County: Olmsted
Corner Title:	Section: 35		Township: 107N
Range: 11W	Principle Meridian:	· · · · · · · · · · · · · · · · · · ·	Date Set:
Monument Description:			
cic /p2			
Reference Ties:		<u>:</u>	
Punched hole in SW end 18" CMP 7.90' 30d spk in 10" Elm SE 23.90' 30d spk in 6" Elm SW 38.35'			
Corner History:			
9-1853 Gov't Notes: Set post for corne 25 W 45 links. White Oak 12" S 87-1/2 E		11 E 6 links. White Oak 12	2" S 42 W 24 links. White Oak 12" i
10&11-1900 W.Fraser (P.69208 No.615 S stake. Mr. Kimberly present both avered a found stone in place proved to be 11 lks ea proved to be 16 lks east and 5-1/2 lks south lkis east and 4-1/2 lks south to be M&L lef gov't prop. Plat shows 19.42 south then 19	s to care in prop accuratly to st and 1-1/2 lks south to be a to be M&L sec cor and 1/ it but used correct corner for	the former location of corn M&L 40.04 total. 1/64 ea 16 cor 20 rods east 4" P.69 or survey. 1/16 south No.5	er, left as is. 1/16 east "2" P.693 ust "3" P.693 found stone in place proved to be P.693 drove stake and set stone, set
6-28-1977 County Surveyor found 1-1/2' pipe and found limestone standing 4" x 5" 1.2' curve in road ± 10' below road grade le	x 24" with top 1.5 3-1/2' de	ep side of stone and set Cl	
6-21-1994 Vince Fangman found 4' telsp x 1' chunk of rip-rap for culvert. He cut th straight. He hit the previous mentioned storaround the southerly side of monument and in 10" Elm SE. 38.35 to 30d spk in 6" Elm	ne monument in half and re ne when he got the monum If the following ties were se	set by DNR coordinates when the set by DNR coordinates when the set by DNR coordinates with the set by DNR coordinates when the set by DNR coordinates with the set by DNR coordinates when th	hich fit the location if stood up or chunks of limestone were piled
I hereby certify that this document :	and the data contained he	erein was prepared by me	or under my direct supervision.
	Signature Olmsted County Surveyor	·	Date

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
Courth Va		
South 1/4 corner of section 34 township 108 N range 11 W ,5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha		
AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 Established A Wabash	a County Coordinate NAD	
1983 Add. Using Information She		
_ LEFT MONUMENT AS FOUND, _ LOWERED MONUM	ENT REMOVED MONUMENT (EXPLAIN)	
ONPLACED A		
SKETCH OF REF	TERENCE TIES	
	2′±	
	Z =	
, w		
7 7 7 1+ 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1-		
1 11		
X FENCE 1 Y	XX	
l	N=100080.10 WAB. CO. COOPD.	
	E=536064.32 NAD. 1983 RDJ.	
1		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORI	NER LOCATION IS ON THE BACK OF THIS SHEET.	
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE	OFFICE OF THE REGISTER OF DEEDS	
DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	COUNTY OF	
(Dinis) (Daniel 1841 and	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED	
MW 4. 4 M8M 15 Nov. 2000	IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
SIGNATURE DATE	DEGISTER OF DEEDS	
LICENSE NO. 12788	REGISTER OF DEEDS	
LAND SURVEYOR, PROFESSIONAL ENGINEER	BY DEPUTY	
COUNTY SURVEYOR. COUNTY ENGINEER	DOCUMENT NUMBER	

SV4 COR SEC 34

Cerr	nneate of Location of Gov		•
ID#: 813404		,	
Elevation:	Description: NORTH 1/4 CO	R SEC 3	County: Olmsted
Corner Title:	Section: 34		Township: 107N
Range: 11W	Principle Meridian:	· · · · · · · · · · · · · · · · · · ·	Date Set:
Monument Description:			
CIC/p2 with stone along side.	•		
Reference Ties:	:		
Spike and CSD in W side blazed White Oal Spike and CSD in E side blazed White Oal Spike and CSD in E side blazed 7" White Oal Spike and CSD W side blazed 12" Hackber Blazed 16" White Oak NE 5'	k S 52 W 24.54' Oak N 2 W 27.69'		
Corner History:			
9-1853 Gov't Notes: Set post for 1/4 sec 45.00 chains enter dry creek bottom bears			Oak 10" N 75 W 364 links 240.24. SE.
9-13-1977 County Surveyor set CIC/p2 in fence and 2' east of the fence north. Set th and .55 S of T.N. RP's: Spike and CSD ir W 24.54. Spike and CSD in E side blazed Blazed 16" White Oak NE 5'.	e stone along side the monumen n W side blazed White Oak S 6 I	t. Set sq. pipe up 2' 1- E 43.93. Spike and CS	1/2' SE of the corner. Corner .55 E SD in E side blazed 8" White Oak S 52
7-13-1977 County Surveyor found 1/2" p to final corner.	sipe (up 1') in line with the fence	S (E-W fence not dist	rinct). Pipe 4.61 S and .58 E of M&L
I hereby certify that this document	and the data contained herein	was prepared by me	or under my direct supervision.
	Signature Olmsted County Surveyor		Date

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
North 1/4 CORNER OF SECTION 35 TOV STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH:	MNSHIP 108 N , RANGE 11 W , 5th P.M.		
ONFOUND A			
SKETCH OF RE	FERENCE TIES		
X FENCE Y LINE X	N= 105254.86 WAB. Co. Coord. E=541335.10 NAD 1983 ADJ. FENCE CORDER AS ESTABLISHED FROM TESTIMONY GIVEN BY LAND OWNER CHARLES LOBLSKY		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.			
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. METHODOLOGICAL DIRECT SUPERVISION. SIGNATURE DATE LICENSE NO. 12788	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		
LAND SURVEYOR, PROFESSIONAL ENGINEERCOUNTY SURVEYOR, COUNTY ENGINEER	DOCUMENT NUMBER		

1850s During the Original Public Land Survey, the US Deputy Surveyor set a quarter section post and made reference to 2 witness trees.

November, 2000

Johnson & Scofield, Inc. received testimony from Charles Loblski, who owns the Southwest Quarter of Section 26. Mr. Loblski showed us the location where a 3-way fence corner had been standing. The east-west fence line is still in place, however, the fence line running north has been removed. A 10 foot diameter area around the position, shown to us by Mr. Loblski, was hand probed to a depth of 3 feet and nothing was found. The 3-way fence corner, as shown to us by Mr. Loblski, was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the northeast and northwest corners of Section 35. Two 1 inch by 18 inch pipes were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER		
Northeast CORNER OF SECTION 35, TOWNSHIP 10B N _RANGE 11 W 5th _P.M. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A P.K. NAIL & A 1/2" x 12" I fon PIN Below			
_ LEFT MONUMENT AS FOUND, _ LOWERED MONU	MENT, X REMOVED MONUMENT (EXPLAIN)		
X ON 8/2000 PLACED A Wabasha Cou	inty Monument		
SKETCH OF RE	FERENCE TIES		
SKETCH OF REFERENCE TIES N=105240.38 WAB. CO. COORD. E=543957.88 NAD 1983 RDJ. FENCE X LINE TOTAL AND THE STATE OF THE			
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.			
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 1218 LAND SURVEYOR, PROFESSIONAL ENGINEER COUNTY SURVEYOR, COUNTY ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		

During the Original Public Land Survey, the US Deputy Surveyor set a section post and made reference to 4 witness trees.

November, 1985 The Minnesota Department of Natural Resources, on survey in Section 36, found an iron monument at the intersection of the centerline of County Road Number 25 with fence lines running east and west.

August, 2000

Johnson, Scofield & Rehder, Inc. found a PK nail at the intersection of the centerline of County Road Number 25 with a fence line running east and a fence line running west. A 9 foot by 9 foot by 6 feet deep excavation was made with a backhoe at the above found PK nail. A 1/2 inch by 12 inch iron pin was found directly below the PK nail. A second road bed was found at a depth of 4 feet. No black dirt was found beneath the second road bed. The natural soil appeared to have been disturbed during the construction of the second road bed. No other monuments were found.

The PK nail and the 1/2 inch by 12 inch iron pin found at the intersection of the centerline of County Road Number 25 with the fence line running east and the fence line running west was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the west quarter corner and south quarter corner of Section 25 and by measurements made to the north quarter corner and east quarter corner of Section 35. Two 1 inch by 18 inch iron monuments were placed, one on top of the other, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
EAST QUARTER Corner of Section 35 Township 108 N., Range 11 W., 5th P.M.		
STATE OF MINNESOTA, County of WABASH	<u>A</u>	
At the corner location shown on the sketch:		
On 7-2-85 found a 3/4" IRON DATE	PIPE WITH RLS CAP # 14888	
□ left monument as found, □ lower	red monument, D removed monument (explain)	
Onplaced a		
SKETCH OF R	EFERENCE TIES	
NOTE: MONUMENT IS 6.5'S. OF & ROAD WEST	TOP OF STEEL FENCE POST UP 3.6	
GRAVEL TWP. ROAD S 26° W	WOODEN GATE POST TOP OF STEEL CORNER FENCE	
NAIL AND DNR DISC SE SIDE OF POWER POLE UP 4.7	* POST S 74° E 35.16' *	
READINGS ORSER	VED WITH COMPASS	
BEARINGS OBSERVED WITH COMPASS Statement of evidence relative to this corner location is on back of page. J.A.G. 8-28-85 G-152		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. I hereby certify that this document was filed in the Co. Recorders office at		
■ Land Surveyor, □ Professional Engineer	By,Deputy	
□ County Surveyor, □ County Engineer	DOCUMENT NO.	

East Quarter Corner Section 35, Township 108 North, Range 11 West

This corner was originally established by the U. S. General Land Office in 1854. The government notes show corner marked with a wood post with the following bearing trees marked:

14" Burr Oak, S. 58° W., 43 lks. (28.38 ft.)
7" Burr Oak, N. 88° E., 35 lks. (23.10 ft.)

In July 1985, the DNR Bureau of Engineering contacted the following for corner information:

Wabasha County Offices of the Recorder, Highway Engineer and Surveyor Land Surveying firm of Kleinschmidt and Webber of Winona

The following information was obtained from the Wabasha County Surveyor's Office: A plat of survey by Vincent Fangman RLS #14888, dated March 9, 1985 shows a 3/4" iron pipe was set at this corner being 5273.51 feet from the east quarter corner Section 36.

In July 1985, the DNR Bureau of Engineering traversed to the area of the corner and found a 3/4" iron pipe with plastic cap stamped "RLS #14888," on the center line of a north-south in line with a ridge line east and 6.5 ft. south of the center line of a road west. Searched for, but did not find the bearing trees marked by the GLO. On July 25, 1985, a backhoe was used to dig for evidence of the corner. Dug a 11 ft. east-west by 12 ft. north-south by 4.5 ft. deep hole, the center of which was at the intersection of above mentioned roads. Found a 10" by 7" by 5" stone down 3 ft., actually found in the excavated dirt pile. It was approximated that the stone could have been 1 ft. to 3 ft. west of the iron pipe. Measured 5272.89 ft. from the iron pipe to the east quarter corner Section 36.

On October 3, 1985 contacted Vincent Faugman RLS #14888 for information on this corner. Mr. Faugman stated he set the corner at occupation lines. It appeared to him that the corner had ± 5 ft. of fill, so anything that could be found probably wasn't of record.

Accept the found iron pipe as marking the location for the corner.

127hab/missu4.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER		
Southeast corner of section 35 , township 108 N , range 11 W , 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha. AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A Cast Iron Monument			
LEFT MONUMENT AS FOUND, _ LOWERED MONUMENT, _ REMOVED MONUMENT (EXPLAIN)			
ONPLACED A			
SKETCH OF REFERENCE TIES			
HEMMOT	N= 99969.82 WAB. CO. COORD. E=543967.72 NAD. 1983 ADJ.		
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.			
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION. SIGNATURE LICENSE NO. 12788 LAND SURVEYOR, _ PROFESSIONAL ENGINEER COUNTY SURVEYOR, _ COUNTY ENGINEER	OFFICE OF THE REGISTER OF DEEDS COUNTY OF		

Certificate of Location of Government Corner

•	(From Olmsted County)	
ID#: 813605	•	

Elevation:

Description: NORTH SEC COR 1-2

County: Olmsted

Corner Title:

Section: 36

Township: 107N

Range: 11W

Principle Meridian:

Date Set:

Monument Description:

CIM over 3/4"x18" bolt over stone.

Reference Ties:

Spike in telephone pole NNW 27.55' 60p spike in S side of 48" Willow tree west 11.1' centerline of driveway on curve east 15' Corner lines 2' east of centerline main road to north.

Corner History:

Gov't Notes: Set post for corner line tree 12" Black Oak 5.71 chains south. BT's: Burr Oak 14" N 74 E 97 links. Black Oak 12" N 4 W 315 links. Burr Oak 8" S 80 E 127 links. Black Oak 14" S 80 W 112 links.

10-11-1900 W. Fraser (P.692-8 No.615 S.2-3,10-11) found stone at corner and stumps SE and SW B trees which checked correct. New B tree 8" Black Oak S 16-1/2 W 33 lks. Drove stake by side of stone meas west to 1/4 cor stone 39.78 (2625.48) which proved 15 (9.9') links too far east for midway and 6 (3.96) links too far south for line. Accepted 1/4 cor and section corners as true corners but not stones west of 1/4 corner.

County Surveyor found 4" x 7" x 14" limestone with 3/4" x 18" bolt on E side of it. Top stone down 2-! 2' in sh. slope set bolt back on E side and placed lots of junk around the stone with 20" CIM above it. Corner ± 7' east of drill steel shaft which we removed. RP's: Spike in telephone pole NNW 27.55. 60p spike in S side of 48" Willow tree west 11.1 centerline of criveway on curve east 15'. Corner lines 2' east of centerline main road to north.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Signature	Date
Olmsted County Surveyor	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER South Y4 CORNER OF SECTION 35 , TOWNSHIP 108 N, RANGE 11 W , 5th P.M. STATE OF MINNESOTA, COUNTY OF Wabasha AT THE CORNER LOCATION SHOWN ON THE SKETCH: X ON 8/2000 FOUND A CIC SET BY OLMSTED COUNTY Syrvayor ___ ON____PLACED A ______ SKETCH OF REFERENCE TIES 2.5± TOWNSHIP ROAD CENTERLINE N=9990.40 WAB. CO. COORD. E=541343.67 NAD 1983 ADJ. STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET. OFFICE OF THE REGISTER OF DEEDS I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR COUNTY OF ____ UNDER MY DIRECT/SUPERVISION. I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED 13NOU. 2000 IN THE REG. OF DEEDS OFFICE AT______.M. ON THE _____DAY OF _____A.D., 20___ SIGNATURE DATE LICENSE NO. 12788 REGISTER OF DEEDS_____

LAND SURVEYOR.

COUNTY SURVEYOR.

_ PROFESSIONAL ENGINEER

_ COUNTY ENGINEER

_____ DEPUTY

DOCUMENT NUMBER_____

S14 COR SEC 35

Certificate of Location of Government Corner (FROM OLMSTED COUNTY)

ID#: 813504		•
Elevation:	Description: N 1/4 COR SEC 2	County: Olmsted
Corner Title:	Section: 35	Township: 107N
Range: 11W	Principle Meridian:	Date Set:
Monument Description:		
CIC/p2	•	
Reference Ties:		
Spike and CSD E side corner post NNW 32 Spike and CSD SW side 10" Elm NW 86.03		
Corner History:		
9-1853 Gov't Notes: Set post for quarter Oak (line tree) 1.53 chains N???	corner. BT's White Oak 10" N 69 E 69 links	. White Oak 14" S 59 W 65 links. 14" Burr
corner. Lies 15 lks east and 6 lks south to be place as 1/16 cor lies 11(7.26) lks too far eaused M&L 20.02. Also corners "3" and "4"	se M&L. Meas west 40.08 (2645.28) east 39. st and 1-1/2 (1.0) links too far south to be M&' found stones simularly too far east sec NW 2 south 19.36-1/4 then 19.71-1/4 south line sections.	2 used correct for work but left stones. 1/16
6-14-1977 County Surveyor dug out entire Found nothing.	e surface of E-W road from 5' E to 5' W of the	N-S fence 4-1/2 deep to clay. Fill to clay.
the SW side and a stake on the S side. Storthis stone the one recorded by W.F. as 1-1/2 recorded by W.F. (Bk 9 P.64) as 11 lks too	t and 4-1/2 lks too far S. Point came in line w	he road and in line with the fence S. Believe
from the NW cor 2 over a pt 1-1/2' lks N of	f the stone found at the 1/16 west as per W.F. and S. RP's: Spike and CSD SW side 10" E	
I hereby certify that this document a	and the data contained herein was prepared	d by me or under my direct supervision.
	Signature Olmsted County Surveyor	Date

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER NORTH QUARTER Corner of Section 36 Township 108 N., Range 11 W., 5 th P.M.			
STATE OF MINNESOTA, County of WABASHA			
At the	corner location shown on the sketch:		
⊠	On <u>7-3-85</u> found a <u>7/8" IRON</u>	PIPE, UP 0.3	
	☑ left monument as found, ☐ lower	ed monument, removed monument (explain)	
	Onplaced a		
	SKETCH OF R	EFERENCE TIES	
-7-		 	
	DNR NAIL & DISC S. SIDE WOOD FENCE POST UP 0.3' WEST	DNR NAIL & DISC E.SIDE WOOD FENCE POST UP 0.3' NORTH O 0.63'	
—x-	DNR NAIL & DISC 0.96 O.96 UP 0.3'	DNR NAIL & DISC EAST S. SIDE WOOD FENCE POST UP 0.3	
		*	i .
		×	
	BEARINGS OBSERVI	ED WITH COMPASS	
State	ment of evidence relative to this corner to	cation is on back of page. LRP 11-6- G-152 TR	85 ₹ 192
contain my din	by certify that this document and the data ned herein was prepared by me or under rect supervision. Self R. Jouwereurs f. 11-6-85 ration No. 17005	OFFICE OF THE COUNTY RECORDER County of I hereby certify that this document was filed the Co. Recorders office at	the
Neckisi.	Land Surveyor, Professional Engineer	Ву,Dер	
1 '	County Surveyor, 🗋 County Engineer	DOCUMENT NO.	

North Quarter Corner Section 36, Township 108 North, Range 11 West

This corner was originally established by the U. S. General Land Office in 1854. The government notes show corner marked with a wood post with the following bearing trees marked:

8" Burr Oak, N. 21° E., 10 lks. (6.60 ft.) 11" Burr Oak, S. 84° W., 44 lks. (29.04 ft.)

In July 1985, the DNR Bureau of Engineering contacted the following for corner information:

Wabasha County Offices of the Recorder, Highway Engineer and Surveyor Land Surveying firm of Kleinschmidt and Webber of Winona

No resurvey information was obtained on this corner.

In July 1985, the DNR Bureau of Engineering traversed to the area of the corner and found a 3/4" iron pipe up 0.4 ft., at the intersection of fences north-south and east-west. Searched for, but did not find the bearing trees marked by the GLO.

We contacted the following area landowner(s) for testimony regarding this corner: Ray Stoning, approximately 65 years old. Mr. Stoning stated the iron pipe has been there ever since he owned the farm, which is 40 years.

Accept the iron pipe as marking the location of the corner.

Traverse information is available from the DNR Bureau of Engineering.

129hab/missu4

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
Northaast corner of section 36 , township 108 N , range 11 W , 5th p.m. STATE OF MINNESOTA, COUNTY OF Wabasha.		
AT THE CORNER LOCATION SHOWN ON THE SKETCH:		
x 018/200 FOUND A 6"x 8x12" 52nd	stone Monument	
_ LEFT MONUMENT AS FOUND, & LOWERED MONU	MENT, REMOVED MONUMENT (EXPLAIN)	
X ON 8/2000 PLACED A Wabasha Cour	nty Monument	
SKETCH OF RE	FERENCE TIES	
NOAD POAD		
\vec{\pi}		
	N=105214.98 WAB. CO. COORD. E=549236.67 NAD. 1983 ADJ.	
X FENCE X LINE X		
	ш	
	<u>z</u>	
(S)	ਲ ਬ	
TOW OF	C E N T E	
	$ec{ec{ec{ec{v}}}}$	
STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON THE BACK OF THIS SHEET.		
I HEREBY CERTIFY THAT THIS DOCUMENT AND THE DATA CONTAINED HEREIN WAS PREPARED BY ME OR UNDER MY DIRECT SUPERVISION.	OFFICE OF THE REGISTER OF DEEDS COUNTY OF	
Ownin. Imam anov. 2000	I HEREBY CERTIFY THAT THIS DOCUMENT WAS FILED IN THE REG. OF DEEDS OFFICE ATM. ON THEDAY OFA.D., 20	
SIGNATURE DATE LICENSE NO. 1278	REGISTER OF DEEDS	
LICENSE NO. 1 - 100	BY, DEPUTY	
	DOCUMENT NUMBER	
LICENSE NO. 1 100 PROFESSIONAL ENGINEER		
COUNTY SURVEYOR, COUNTY ENGINEER	DOCUMENT NUMBER	

- 1850s During the Original Public Land Survey, the US Deputy Surveyor set a section post and made reference to 4 witness trees.
- 1905 E. C. Burns indicates a stone monument and bearing tree at the corner.
- 1931 E. C. Burns indicates found stone monument at the corner.
- August, 2000 Johnson & Scofield, Inc. excavated with a backhoe at the intersection of the centerline of a north-south Township Road and a fence line running west. The excavation was 10 feet by 12 feet to a depth of 2 feet. At a depth of 1.7 feet, a 6 inch by 8 inch by 12 inch sandstone monument was found.

The found sandstone monument was accepted as the best perpetuation of the Original Public Land Survey Corner and was substantiated by measurements made to the east and south quarter corners of Section 25 and to measurements made to the east quarter corner of Section 36. A 1 inch by 18 inch iron pipe was placed on the west side of the stone monument. A second 1 inch by 18 inch iron pipe was place above the stone, with a 2 inch diameter cast iron cap, stamped "survey marker", affixed to the top.

CERTIFICATE OF LOCATION	CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
EAST QUARTER Corner of Section 36 , Township 108 N., Range 11 W., 5th P.M.			
STATE OF MINNESOTA, County of WABASH			
At the corner location shown on the sketch:			
Ø On 7-8-85 found o 2" IRON PIP	E, FLUSH		
□ left monument as found, □ lower	ed monument, D removed monument (explain)		
Onplaced a			
	EFERENCE TIES		
8	· S		
NOTE: NOTE: THERE IS A STEEL	NONA NONA NONA		
NOTE: MERE IS A STEEL SE	\ <u>X</u> × X		
FENCE POST 1.5' EAST OF MONUMENT	FOUND NAIL		
1 • .	NNW. SIDE 12" BOXELDER UP 3.0'		
R N O M	N 72°E 14.48'		
<u> </u>	× A		
-	DOWN FENCE -XX-		
	Î:		
SOUTH	! `. * .		
FOUND NAIL	SOUTH		
W. SIDE 15 " BOXELDER 15.12			
UP 2.0'			
,	I 1/4" IRON PIPE UP 1.0'		
	0P 1.0		
>			
BEARINGS OBSERVED	WITH COMPASS		
Statement of evidence relative to this corner location is on back of page. LRP 11-6-85 G-152 TR 192			
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER			
contained herein was prepared by me or under	County of with		
my direct supervision.	I hereby certify that this document was filed in		
Lowell R. Youngerein by 11-6-85	the Ca. Recorders office at // a. M. on the		
Registration No. 17005	County Recorder Halling Like		
☐ Land Surveyor, ☐ Professional Engineer	By,Deputy		
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.		

East Quarter Corner Section 36, Township 108 North, Range 11 West

This corner was originally established by the U. S. General Land Office in 1853. The government notes show corner marked with a wood post with the following bearing trees marked:

10" Burr Oak, N. 30° E., 32 1ks. (21.12 ft.) 12" Black Oak, S. 76° W., 85 1ks. (58.08 ft.)

In July 1985, the DNR Bureau of Engineering contacted the following for corner information:

Wabasha County Offices of the Recorder, Highway Engineer and Surveyor. Winona County Recorder's Office
Land Surveying Firm of Kleinschmidt and Webber of Winona

The following information was obtained from the Winona County Recorder's Office:
A certificate of location of a government corner, number 193, signed by E.
C. Burns, County Surveyor on August 24, 1923 shows this corner was a stone close to the intersection of fences. Burns set a 2" by 42" iron pipe for the corner and a 1½" by 32" iron pipe for a witness to the corner 15 ft. south.

The following information was obtained from the Wabasha County Surveyor's Office:
A plat of survey by Vincent Fangman RLS #14888, dated March 9, 1985 shows a
2" iron pipe inplace at the corner being 5273.51 ft. from the east quarter
corner of Section 35.

In July 1985, the DNR Bureau of Engineering traversed to the area of the corner and found a 2" iron pipe flush, at the intersection of old down fences north-south and east. Searched for and found a $1\frac{1}{4}$ " iron pipe 15.1 ft. south of the 2" iron pipe. Searched for, but did not find the bearing trees marked by the GLO.

Accept the 2" iron pipe as marking the location of the corner.

Traverse information is available from the DNR Bureau of Engineering.

126hab/missu4

CERTIFICATE OF LOCATI	ON OF GOVERNMENT CORNER	
N.E. Con	rner of Section 1 , Township 107N, Range 11W	
STATE OF MINNESOTA, County of Olmsted		
At the corner location shown on the sketch:	•	
On 6-30-1977 found a 10"x1	0" cut stone township monument (up 6")	
☐ left_monument as found, ☐ lowered monument, ☐ removed monument (explain)		
DATE '	con (up 1') on the North side of the	
SKETCH	OF REFERENCE TIES	
-N-		
Spike & C.S.D. in north Side blezed Red Oak W.N.W. 6.33	Spike & C.S.D. N.W.sid of 8" blazed Hackberr N.E Z6.21 Engraved Cat Stone Monuma	
WAB. CO. COORD. N=99970.41 NAD 1983 AD). E=549225.54	Spike & C.S.D. in west side 31/2" blazed white oak S.E. 20.23	
Note: The corner line with f west is lying on the gr the north side of the sta	rences North & west. the Fence round. We drove a 1/2" iron on one one of a 1/2" pipe on the south side.	
Statement of evidence relative to this corr	ner location is on back of page.	
I hereby certify that this document and the contained herein was prepared by me or un my direct supervision. **North Brand May 3 **SKINATURE** **PATE** *	l hereby certify that this document was filed in the Reg. of Deeds office atM. on theday ofA.D., 19	
Registration No. 8952 Mand Surveyor, Professional Engl	Register of Deeds	
M cond contector of tholesalough child	india 1 of management to the state of the st	

Statement of Evidence:

1853

Gov't Notes E. Norris, Deputy Surveyor
North between sections 1 and 6.

50.00 chs. Set post for corner to Townships 107 and 108
North of Ranges 10 and 11 West
Black Oak 14 in. N28°W 158 lks.
White Oak 14 in. S17°W 45 lks.
Black Oak 12 in. S10°E 70 lks.
White Oak 13 in. N425°E 50 lks.

1875

Fedral law required that township monuments be set at the township corners.

6-30-1977

The County Surveyor found a 10"x10" cut stone monument up 6". Drove a $\frac{1}{2}"$ iron (up 1') on the North side of the stone and a $\frac{1}{2}"$ pipe (up 1') on the South side of the stone.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
SOUTH QUARTER Corner of Section 36 Township 108 N., Range 11 W., 5th P.M.		
STATE OF MINNESOTA, County of WABASHA		
At the corner location shown on the sketch:		
☑ On 7-23-85 found a 11/4" IRON PIPE, UP 1.3		
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)		
DATE PIGGES S		
SKETCH OF REFERENCE TIES		
4		
NAIL AND DNR DISC ON EAST SIDE OF IO" WHITE OAK UP!4' WITH FACE BLAZE		
WIIII TAGE BEAZE	NAIL AND DNR DISC ON SE. SIDE OF	
N 04° E 17.65'	4" WHITE OAK UP 0.4' WITH FACE BLAZE	
WABASHA CO.	N 38° E 12.07' T. 108 N.	
OLMSTED CO.	T. 107 N.	
S 22° E∠ 38.52'		
	NAIL AND DNR DISC ON NE. SIDE OF	
	IO" RED OAK UP 0.7' WITH FACE BLAZE	
BEARINGS OBSERVED WITH COMPASS		
Statement of evidence relative to this corner local	ation is on back of page. J.A.G. 8-28-85 G-152	
Lipereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER	
contained herein was prepared by me or under my direct supervision.	I hereby certify that this document was filed in	
1 11-1-25	the Co. Recorders, office at 11 a. M. on the	
Sound K. Tourse James 177. 11-9-00	County Recorder A.D., 19 4	
Registration No. 17005/ X Land Surveyor, Professional Engineer	ByDeputy	
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.	

South Quarter Corner Section 36, Township 108 North, Range 11 West

This corner was originally established by the U. S. General Land Office in 1853. The government notes show corner marked with a wood post with the following bearing trees marked:

10" Burr Oak, S. 25° W., 49 lks. (32.34 ft.) 14" Black Oak, N. 14° W., 6 lks. (3.96 ft.)

In July 1985, the DNR Bureau of Engineering contacted the following for corner information:

Wabasha County Offices of the Recorder, Highway Engineer and Surveyor Olmsted County Surveyor's Office
Land Surveying Firm of Kleinschmidt and Webber of Winona

No resurvey information was obtained for this corner.

In July 1985, the DNR Bureau of Engineering traversed to the area of the corner and found a 1½" galvanized iron pipe up 1.3 ft. and leaning to the west, plumbed up same. Searched for but did not find the bearing trees marked by the GLO. Measured the following to the iron pipe:

2624.42 ft. from the northeast corner Section 1 2633.40 ft. from the northwest corner Section 1

The iron pipe was found on a very steep west facing slope with stones lying around it.

Accept the found iron as marking the location for the corner.

Traverse information is available from the DNR Bureau of Engineering.

125hab/missu4